


SITE NUMBER AND NAME C07 H16:30 Kenilworth Lake		HIGHWAY & KM	PREVIOUS INSPECTION DATE May 19, 2010	INSPECTION DATE May 19, 2011
LEGAL DESCRIPTION NE 28-50-4-4	NAD 83 COORDINATES N 5910800 E 532788		RISK ASSESMENT PF: 4 CF: 2 TOTAL: 8	

SUMMARY OF SITE INSTRUMENTATION: 4 Pneumatic piezometers and 1 standpipe operational as of 2002 (No instrument readings have been taken since 2002 when the slope was repaired.) LAST READING DATE: May 23, 2002		INSPECTED BY: 
PRIMARY SITE ISSUE: Cracking and settlement of shoulder		
APPROXIMATE DIMENSIONS: 50 m long		
DATE OF ANY REMEDIAL ACTION: 2001 - granular berm placed at the toe of the slope keyed through the potential weak shear zone in combination with an overall flattening of the slope to about 6H:1V.		

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		Cracking of the pavement and settlement was observed on the shoulder. Some cracking extended into the driving lane. No significant changes since last inspection in 2010.		X
Slope Movement					
Erosion					
Seepage					
Culvert Distress					
COMMENTS					
Refer to previous reports and photographs.					
MCI to monitor – remove from Geohazard program					