

**STONY PLAIN REGION
GEOHAZARD RISK ASSESSMENT
SITE INSPECTION FORM**

SITE NUMBER AND NAME: NC 47 – Embankment Slope Failure	HIGHWAY AND KM: Access Road 172, km 2.1	PREVIOUS INSPECTION DATE: May 21, 2010	INSPECTION DATE: June 15, 2011
LEGAL DESCRIPTION: SE 4-50-22-W4M	NAD 83 COORDINATES:	RISK ASSESSMENT: PF: 2 CF: 4 TOTAL: 8	

SUMMARY OF SITE INSTRUMENTATION: Slope Inclinometer: 1	INSPECTED BY: Adam Gmeinweser, P. Eng. (EBA) Fred Cheng, P. Eng. (TRANS) Sabhago Oad, P. Eng. (TRANS)
LAST READING DATE: May 18, 2011	
PRIMARY SITE ISSUE: Shallow rotational failure of south embankment slope remediated in 2008.	
APPROXIMATE DIMENSIONS: Approximately 6.1 m in height and 12.2 m in length.	
DATE OF REMEDIAL ACTION: October 2008	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		Cracks along shoulder associated with embankment failure 2H:1V embankment failure stabilized with soil nails		X
Slope Movement	X				X
Erosion		X			
Seepage		X			
Culvert Distress		X			

COMMENTS:
 Rotational failure centered on a culvert; failure possibly due to a high water event.
 Soil nailing performed in 2008 to stabilize embankment.
 2009 Risk Assessment reduced from 48 to 8 after repairs. Risk level unchanged since 2009.
 Location and site plan shown in Figure NC-47.
 Site conditions shown in Photos 1 and 2.
 Soil stabilization performing reasonably well.

**STONY PLAIN REGION
GEOHAZARD RISK ASSESSMENT
SITE INSPECTION FORM**

SITE OBSERVATIONS:

- The fill slope is steeper than what is normally constructed by TRANS being approximately 2H:1V and 6.1 m high.
- The slope failure was repaired in October 2008.
- Soil nails sticking out of ground, potentially a risk to public; primarily concerning snowmobile and/or ATV traffic.
- Shallow slope movements have stopped since application of soil nailing in 2008.
- There were minor deep seated movements noted at approximate embankment base level. These could be associated with lateral spreading along organics or wet soils near the culvert/creek location.

RECOMMENDATIONS:

- Consider removing site from GRMP.