

CENTRAL REGION GEOHAZARD RISK ASSESSMENT SITE INSPECTION FORM



SITE INSIECTION FORM							
SITE NUMBER AND NAME	PREVIOUS	INSPECTION DATE					
C27A H11:08 Emban	INSPECTION DATE	_ n	May 20, 201	11			
OZIA IIII.OO EIIIDAII	May 14, 2013		viay 20, 20	17			
LEGAL DESCRIPTION	NAD 83 COORDINATES	RISK ASSESMEN	١T				
NW 32-40-11-W5	N 5816691 E 598230	PF: 6 CF:	2	TOTAL: 1	2		

C27A H11:08 Embankment Slide			INSPECTION DATE May 14, 2013 May 20, 2014				_		
LEGAL DESCRIPTION	NAD 83 COORD	INATES	RISK	ASSE	SMENT	Γ			
NW 32-40-11-W5	N 5816691 E	598230	PF:	6	CF:	2	TOTAL:	12	

SUMMARY OF SITE INSTRUMENTATION:

2 Standpipe Piezometers (2003):

	Water Level (mbgl)				
	2005	2006	2007	2010	2012
TH03-01	5.75	7.83	5.46	4.25	2.6
TH03-02	3.94	7.52	3.76	-	1.7



LAST READING DATE:2012

PRIMARY SITE ISSUE:

Slide on highway embankment

APPROXIMATE DIMENSIONS:

DATE OF ANY REMEDIAL ACTION:

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION		NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO	
Pavement Distress		Х	Pavement overlay in 2003 – no cracks on highway		Χ	
Slope Movement	Х		Cracks and scarp on slope – no significant changes since 2011.		Χ	
Erosion		Х			Χ	
Seepage		Х			Х	
Culvert Distress		Х			Χ	

COMMENTS

Refer to previous reports and attached photos

Slide is likely related to the relatively high water levels within the fill, associated with seepage from the high ground to the northeast. Seepage zones (indicated by vegetation growth) are apparent on the slope and coincide with the movement zones.

MCI to monitor – remove from Geohazard program.



Page 1 of 2



Page 2 of 2