


SITE NUMBER AND NAME C41 H22:22 Erosion		HIGHWAY & KM 17.8	PREVIOUS INSPECTION DATE May 18, 2011	INSPECTION DATE May 20, 2014
LEGAL DESCRIPTION 7-38-6-W5	NAD 83 COORDINATES N5791465 E646190		RISK ASSESMENT PF: 1 CF: 1 TOTAL: 1	

SUMMARY OF SITE INSTRUMENTATION: None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: An erosion channel had formed on the west side of the bridge abutment and extended down to the river.	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: An HDPE pipe and gabion inlet and outlet structures were installed in the summer of 2007. The culvert east of the road was also repaired.	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress					
Slope Movement					
Erosion	X	X	No erosion is apparent since construction on west side. Slope is eroding below culvert on east side of bridge.	X	X
Seepage					
Culvert Distress		X			X

COMMENTS
Refer to previous reports and attached photos.
Repairs to be conducted as part of High Water Mitigation Program







