


SITE NUMBER AND NAME C10A H53:04 Erosion		HIGHWAY & KM 5 km east of H22	PREVIOUS INSPECTION DATE June 26, 2007	INSPECTION DATE May 20, 2014
LEGAL DESCRIPTION SW 10-43-6-W5	NAD 83 COORDINATES N 5840057 E 648688		RISK ASSESMENT PF: 1 CF: 1 TOTAL: 1	

SUMMARY OF SITE INSTRUMENTATION: None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: Ditch Erosion & Instability	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: "Living Wall" (compost filled tubes) and rip rap installed September 2006	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress					
Slope Movement		X	Instability in bank slopes due to toe erosion repaired with rip rap and compost filled tubes.		X
Erosion		X	Toe and bank erosion occurring due to flows from culverts over a length of about 100 m.		X
Seepage					
Culvert Distress					

COMMENTS
Refer to previous reports and attached photos
Culvert was replaced in 2005 and rip rap installed in 2006.
Bank is now well vegetated. Beaver dam located downstream of culvert.









