


SITE NUMBER AND NAME C10B H53:04 Erosion		HIGHWAY & KM 1.2 km east of H22	PREVIOUS INSPECTION DATE June 26, 2007	INSPECTION DATE May 20, 2014
LEGAL DESCRIPTION SE 7-43-6-W5	NAD 83 COORDINATES N 5839935 E 644634		RISK ASSESMENT PF: 6 CF: 2 TOTAL: 12	

SUMMARY OF SITE INSTRUMENTATION: None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: Ditch Erosion & Instability	
APPROXIMATE DIMENSIONS: Erosion channel about 50 m in length, 4 m to 6 m wide and 2 m to 3.5 m deep.	
DATE OF ANY REMEDIAL ACTION:	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress					
Slope Movement		X	Instability in bank slopes due to toe erosion.		X
Erosion	X		An erosion channel has developed in the north ditch of H53. Fence posts are being undermined.		X
Seepage					
Culvert Distress					

COMMENTS
Refer to previous reports and attached photos
No significant change over last 7 years.
Rip rap channel proposed for repair.



