


SITE NUMBER AND NAME <b>C49 B H614:02 Ditch Erosion</b>		HIGHWAY & KM	PREVIOUS INSPECTION DATE May 14, 2007	INSPECTION DATE <b>June 25, 2008</b>
LEGAL DESCRIPTION SE 16-46-4-W4	NAD 83 COORDINATES N 5867933 E 532914		RISK ASSESMENT PF: 9 CF: 2 TOTAL: <b>18</b>	

SUMMARY OF SITE INSTRUMENTATION:  None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: Erosion channel in north ditch of H614:02, near RR 4-4.	
APPROXIMATE DIMENSIONS: West end about 3 m wide & 1 m deep, extends about 50 m, becoming shallower to the east.	
DATE OF ANY REMEDIAL ACTION:	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		X			X
Slope Movement		X			X
Erosion	X		Erosion has exposed a uniform sand deposit under the topsoil. Area is beginning to vegetate itself.	X	
Seepage		X			X
Culvert Distress		X			X

<b>COMMENTS</b>
See attached photos and previous site assessment form.
Erosion channel appears to have enlarged since previous inspection, but it is about 10 m from highway edge and does not present a hazard to traffic. It is recommended that the channel be backfilled with available fill and seeded.

Site C49 B H614:02 Ditch Repair  
June 25, 2008



Site C49 B H614:02 Ditch Repair  
June 25, 2008



Site C49 B H614:02 Ditch Repair  
June 25, 2008



Site C49 B H614:02 Ditch Repair  
June 25, 2008



Site C49 B H614:02 Ditch Repair  
June 25, 2008

