


SITE NUMBER AND NAME C06 H881:10 Myrnam Spring		HIGHWAY & KM	PREVIOUS INSPECTION DATE May 19, 2004	INSPECTION DATE May 14, 2007
LEGAL DESCRIPTION 14-54-9-W4	NAD 83 COORDINATES N 5955328 E 485473		RISK ASSESMENT PF: 9 CF: 2 TOTAL: 18	

SUMMARY OF SITE INSTRUMENTATION: None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: Frost heave, Pavement distress	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: Subexcavation and gravel replacement / sub-drains in September 2005	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X				X
Slope Movement		X			X
Erosion		X			X
Seepage		X			X
Culvert Distress		X			X
Frost Heave	X				X

COMMENTS
Refer to previous reports and attached photographs.
A section of highway about 20 m long was subexcavated with gravel replacement / drains in 2005. This road section appears to be performing well and the new drain was observed to be flowing. The existing "Myrnam Spring" was unaffected by the construction. It is reported that the highway section to the south is heaving in winter months and the gravel replacement section should be extended. It is recommended that an inspection be undertaken in January/February 2008 to determine the extent of the section to be remediated.









