


<b>SITE NUMBER AND NAME</b> C063 Frost Heave	<b>HIGHWAY &amp; KM</b> H11:12 km 24.734	<b>PREVIOUS INSPECTION DATE</b> March 2, 2017	<b>INSPECTION DATE</b> <b>Feb 28, 2018</b>
<b>LEGAL DESCRIPTION</b> NE 24-38-1 W5	<b>NAD 83 COORDINATES</b> Northing Easting 52°16.999' 114°0.579'	<b>RISK ASSESSMENT</b> PF: 8 CF: 3 TOTAL: 24	
2017 Average Annual Daily Traffic (Ref. 70000488) (AADT): 16180 (westbound) 16420 (eastbound)		Contract Maintenance Area (CMA): 19	

<b>SUMMARY OF SITE INSTRUMENTATION:</b>  3 vibrating wire piezometers 3 ground temperature cables  LAST READING DATE: January 17, 2018	<b>INSPECTED BY:</b> Chris Gräpel (KCB) Hanh Hong (KCB) Rocky Wang (AT) Tony Penney (AT) Dewayne Wlad (AT)
<b>PRIMARY SITE ISSUE:</b> Frost heave occurring in the westbound highway embankment. Frost heave exacerbated by the installation of 26 drains (8 in the west section, 18 in the east section) across the westbound highway embankment during the twinning of the highway in 2008. Differential heaving is occurring between frost susceptible highway fill and non-frost-susceptible drain backfill resulting in a "rolling" pavement surface	
<b>APPROXIMATE DIMENSIONS:</b> West section is approximately 200 m long, east section is approximately 450 m long (westbound lanes only)	
<b>DATE OF ANY REMEDIAL ACTION:</b>	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		Transverse pavement cracking generally corresponds to locations of drains		X
Slope Movement		X			X
Erosion		X			X
Seepage		X			X
Culvert Distress		X			X

<b>COMMENTS</b>
Frost heaving on the highway appears to occur at the drain backfill locations. Frost heaving observed to have worsen as compared to the previous winter; with the west section heaving more than the east section. Frost heaving observed to be the worst near and west of the yellow rough pavement signs as shown in Photo 3.
A Preliminary Engineering Report was issued by KCB on September 19, 2017 that provided KCB's recommendations for repair work. 3 repair options were presented to AT.
AT prefers repair option 1 that involves excavating the non-frost-susceptible backfill above the drains and then backfilling the excavation with frost-susceptible material. Based on the variability in the existing highway fill, it may be difficult to match the frost-susceptibility of the trench backfill to the existing highway fill. Option 1 may have a high risk of not working and differential frost heave may still occur. KCB, therefore, recommends that a trail section be constructed in the west section to evaluate the performance of repair option 1.
In discussion with AT, KCB will arrange to have a winter pavement-LiDAR survey of the westbound lanes to locate the pavement dips.




- Legend**
- ① Photo Location
  - ➔ Photo Direction
  - GPS Track (February 28, 2018)
  - ⋯ Drain
  - ⋈ Culvert



<b>NOTES:</b> 1. HORIZONTAL DATUM: NAD83 2. GRID ZONE: UTM Zone 11N 3. IMAGE SOURCE: Bing Maps 2018, Microsoft Corporation. Image dated September 2013 4. Site visit photos dated February 28, 2018	CLIENT 	PROJECT CENTRAL REGION GEOHAZARD RISK MANAGEMENT PROGRAM
		TITLE C063 - Site Inspection Hwy 11:12, km 24.734
	SCALE 1:2,500	PROJECT No. A05115A02
		FIG No. 1

Time: 15:25:16 PM  
 Date: March 05, 2018  
 File: Z:\A\EDM\A05115A02\ABT\_Central Region GRNIP\A00 Drawings\2018\2\_Section B11\_2018 Frost Heave Tour\MXD\C63\_180301.mxd



**Photo 1** Transverse pavement cracking along westbound lane (east section). Cracking generally aligns with horizontal drains. Photo taken February 28, 2018 looking south.



**Photo 2** Transverse pavement cracking and depression along westbound lane (east section). Photo taken February 28, 2018 looking south.



**Photo 3** Location of frost heave site (east section). Photo shows a rolling pavement condition. Photo taken on February 28, 2018 looking southwest.



**Photo 4** Location of frost heave site (east section). Photo taken on February 28, 2018 looking east.



**Photo 5**      **Location of frost heave site (east section). White posts indicate drain outlets. Photo taken on February 28, 2018 looking west.**

