

SITE NUMBER AND NAME: C072 North of Rocky Mountain House (RMH)		HIGHWAY & KM: 22:24, 9.8	PREVIOUS INSPECTION DATE: June 11, 2018	INSPECTION DATE: July 09, 2019
LEGAL DESCRIPTION: 09-33-040-07 W5M 12-34-040-07 W5M	NAD 83 COORDINATES: UTM Northing Easting 11 5817436 640058		RISK ASSESSMENT: PF: 8 CF: 4 TOTAL: 32	
AVERAGE ANNUAL DAILY TRAFFIC (AADT): 2,540 (north) (Ref No. 990020)			CONTRACT MAINTENANCE AREA (CMA): 17	

SUMMARY OF SITE INSTRUMENTATION: Three slope inclinometers (SIs) installed on the east slope in 1990 – status unknown. LAST READING DATE: N/A		INSPECTED BY: Chris Gräpel (KCB) Ryan Gazley (KCB) Rishi Adhikari (AT) Tony Penney (AT)
PRIMARY SITE ISSUE: An upper slope failure along the west slope (southbound lane) of the highway embankment. At the location of the slide, Hwy 22 crosses a tributary creek of Canyon Creek, which is a tributary of the North Saskatchewan River. The original slide on the east embankment slope was repaired in 1990.		
APPROXIMATE DIMENSIONS: The upper west slope is approximately 6 m high sloped at approximately 3H:1V. The east slope is approximately 13 m high sloped at approximately 4H:1V.		
DATE OF ANY REMEDIAL ACTION: 1990: site investigation and repair work conducted/completed at the location of the original slide on the east slope; October 2016 – southbound lane patched. 2017 – southbound lane patched.		

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		Old pavement cracks reflected in asphalt patch placed in 2017 appear to have expanded. Little to no change in cracking at south end of patch since 2018.	X	
Slope Movement	X		Guardrail subsided and deflected; fence deflected within slide area, no evidence of ground cracking		X
Erosion		X	None observed		X
Seepage		X	None observed		X
Culvert Distress		X	1300 mm diameter CSP culvert (BF13457)		X


COMMENTS
No new cracking was observed in the pavement patch placed in 2017. The old pavement cracks that are reflecting through the patch appear to have expanded slightly. The cracking at the south end of the patch observed during the 2018 inspection does not appear to have expanded.
The fence at the toe of the embankment is deflected slightly to the west with little to no change from the 2018 inspection. The slope below the crest of the highway and the bench were both wet (likely due to recent rainfall).
Cracking in the southbound lane could indicate potential retrogression of the backscarp onto the highway.
The presence of wet areas on the slope, bench, and near the deflected section of fence, indicate the slope is poorly drained.
During the 2017 inspection, debris (e.g., branches, and small logs - flotsam) was observed at or just above the crown elevation of the culvert inlet indicating that the water level at some point was at or just above the crown

elevation of the culvert. This may indicate that the culvert has insufficient capacity to handle flow volumes.

The bridge file number of the culvert is BF13457. The culvert consists of a 1300-mm-diameter CSP culvert sleeved into the original 1800-mm-diameter multi-plate CSP culvert. Previous inspection observations have included flotsam from highwater events present above the crown of the culvert, indicating the culvert could be undersized.

A geotechnical site investigation (e.g., drilling, laboratory testing, and instrumentation installation and monitoring program) should be conducted on the west slope to assess subsurface conditions; and to monitor depth of movement, and groundwater conditions.

Discussed remedial actions: Repair of the upper slide area could include excavating the slide area and reconstructing the upper portion of the slope with geosynthetic reinforced fill, with a shear key and subsurface drainage. The bridge culvert should be inspected with a remotely operated video camera, and a hydrologic assessment should be conducted to assess the discharge capacity of the culvert. If needed, a new culvert could be drilled through the base of the embankment.



- Legend**
- GPS Track (July 9, 2019)
 - Power Pole
 - Guardrail
 - Creek
 - Culvert
 - ▬▬▬▬▬▬ Berm Downslope Crest
 - - - - Buried Powerline
 - × × × × Fence
 - ~~~~~ Crack
 - Flow Direction
 - Wet Area

NOTES:
 1. HORIZONTAL DATUM: NAD83
 2. GRID ZONE: UTM Zone 11N
 3. IMAGE SOURCE: Bing Maps 2018, Microsoft Corporation. Image dated August 2012

CLIENT

Alberta

Klohn Crippen Berger

PROJECT CENTRAL REGION GEOHAZARD RISK MANAGEMENT PROGRAM		
TITLE Site Plan C072 – North of Rocky Mountain House (RMH) Hwy 22:24, km 9.8		
SCALE 1:2,000	PROJECT No. A05115A02	FIG No. 1

Time: 10:37:44 AM
 Date: August 01, 2019
 File: Z:\AEDM\A05115A02\ABT_Central Region GRMIP\400 Drawings\2019\2. Section B12_2019_Site Inspections\MXD\C072_190911.mxd



© 2019 Microsoft Corporation © 2019 DigitalGlobe © CNES (2019) Distribution Airbus DS

Photo 1 Pavement cracking in asphalt patch appears to have expanded. Photo taken July 9, 2019 looking south. (Photo from 2018 inspection included for comparison)



Photo 2 Close-up view of cracking through patch in southbound lane. Photo taken July 9, 2019.



Photo 3 The fence line at the toe of the slide is deflected but shows little change since 2018 inspection. Photo taken July 9, 2019 looking north.

