

GEOHAZARD ASSESSMENT PROGRAM

PEACE REGION – PEACE-HIGH LEVEL

2013 INSPECTION



Site Number	Location	Name	Hwy	km
PH46	Fairview	South Rings Creek	64:06	25.96
Legal Description		UTM Co-ordinates		
SW¼ 24-081-04 W6M		11V E 406752	N 6210542	

	Date	PF	CF	Total
Previous Inspection:	21-Jun-2012	13	4	52
Current Inspection:	4-Jun-2013	13	4	52
Road AADT:	520		Year:	2013
Inspected By:	Ed Szmata Ken Szmata Roger Skirrow		Don Proudfoot Shawn Russell	
Report Attachments:	<input checked="" type="checkbox"/> Photographs <input checked="" type="checkbox"/> Plans <input type="checkbox"/> Maintenance Items			

Primary Site Issue:	A slide occurred along the east sideslope of the highway embankment above a multiplate culvert.	
Dimensions:	Slide mass was about 25 m wide by about 50 m in length and about 2 m to 3 m in depth.	
Maintenance:	None since last inspection on May 26, 2011	
Observations:	Description	Worsened?
<input checked="" type="checkbox"/> Pavement Distress	Slide backscarp extended 0.7 m into the edge of the paved roadway over a length of 7.5 m. Pavement lost in slide below cracked area. Three guardrail posts are hanging and guardrail is slightly bowed. Longitudinal cracks are also present.	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/> Slope Movement	A slide is retrogressing in the east shoulder and sideslope north of the culvert.	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/> Erosion	Ongoing erosion along NW, NE and SE crotches of fill per June 2012 observations.	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/> Seepage	Seepage on the west sideslope at 26+890	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/> Bridge/Culvert Distress	Slide material is beginning to accumulate above culvert at inlet and could eventually obstruct water flow.	<input checked="" type="checkbox"/>
<input type="checkbox"/> Other		<input type="checkbox"/>
Instrumentation:		
No instruments installed at this site.		
Assessment:		
Soils at this site appear to be particularly susceptible to erosion by concentrated flowing water. It is likely that high precipitation events combined with a progressive loss of cohesion in the clay embankment fill due to weathering are the triggering mechanism for this slide.		

Local experience suggests that for embankments constructed using high plastic clay fill, failures begin to occur sometime between 10 years and 20 years after construction (this structure was re-built in 1990). Long-term stable slopes in similar materials are typically 5H: 1V, while current slopes are 2.75H: 1V to 3H: 1V.

Recommendations:

Cost

Thurber was retained by TRANS in September 2012 to conduct a Preliminary Geotechnical Investigation in September 2012 and to prepare a design and tender package for the current slide repair in May of 2013.


\$50,000

Landslide repair work, under TRANS Contract 14929, was awarded to In-Line Contracting Partnership in September 2013. Landslide repair work is due to be complete by the contractor by mid November 2013.

The repairs for this slide consist of:

- Digging out the slide and northbound lanes of the highway and rebuilding the east sideslope with gravel fill.
- NW, NE and SW ditch erosion repairs with gabion mats and RECP.
- Enhancements to rip rap to accommodate gabion matting at culvert inlet and outlet.

\$1,300,000



NOTE: O/H POWERLINE AND BURIED TELEPHONE CABLES

26+700

EROSION GULLY HAS RETROGRESSION BENEATH FENCE

33m ACP PATCH

12 m LONG SECTION ERODED 2.5-3.2 m DEEP, 2-7.5 m WIDE

12 m LONG SECTION ERODED 2-5 m DEEP, 3 m WIDE

DITCH ERODED UP TO 1.5 m DEEP x 3 m WIDE

TREES CUT BY MAINTENANCE CONTRACTOR

NEW SLIDE CRACK HAS 10cm-20cm VERTICAL OFFSET (WORSENER SINCE 2009)

FENCE UTILIZED DOWN SLOPE

SLUMPING OF BANKS SHRUBS

DITCH ERODED SEVERELY UP TO 1.8m DEEP UP TO 4-8m WIDE FURTHER EROSION

CRACK

CRACK

1.1m DEEP x 3m WIDE CRACK TO CRACK

DITCH ERODED TO 15-70cm DEEP

EROSION HAS RETROGRESSION UP TO 3.1m WIDE

SLIGHT EROSION IN DITCH

3m LONG 300mm DEEP 1m WIDE EROSION

15m LONG, 1m TO 1.5m WIDE, 0.75 m DEEP, SCOUR AT OUTLET OF CULVERT

27+000

6210700
6210680
6210660
6210640
6210620
6210600
6210580
6210560
6210540
6210520
6210500
6210480
6210460
6210440
6210420




PEACE REGION (PEACE RIVER/HIGH LEVEL)
PH46 HIGHWAY 64:06

2013 PH46 INSPECTION PLAN

FIGURE 1

NOTES:
1 LOCATION DATA RECORDED USING HAND HELD GPS RECEIVER. ALL LOCATIONS ARE APPROXIMATE AND ARE FOR ILLUSTRATIVE PURPOSES ONLY.
2 JUNE 4, 2013 OBSERVATIONS SHOWN IN RED

LEGEND
① → PHOTO AND DIRECTION



DRAWN BY	KLW
DESIGNED BY	SGR
APPROVED BY	DWP
SCALE	1:1000
DATE	JULY 2013
FILE No.	15-16-283





Photo 1.
Looking southwest at NW corner of the site with ditch along the cut/fill contact.



Photo 2.
Slump in the NW corner of the site. No significant change since 2012.



Photo 3.
Looking southwards
along the west side of
the road.



Photo 4.
Looking south
along the west side of the
road. Winter highway
salt is likely impeding
vegetation growth
below the shoulder.



Photo 5.
Outlet (west end) of the multi-plate culvert under the highway. No significant change since 2009.



Photo 6.
Small erosion rill along the downstream end of the ditch in the SW corner of the site. No significant change since 2012.



Photo 7.
Middle portion of the ditch in the NE corner of the site has worsened since 2012 with the gully sidewalls failing and falling into the bottom.



Photo 8.
Ditch gullying at upper portion of the ditch at the NE corner of the site has extended further north and west than observed in 2012.



Photo 9.
Looking northwards along the ditch in the SE corner of the site. Erosion gullies have slightly widened with sod falling into their base.



Photo 10.
Looking southwest at culvert inlet. Slide material and barbed wire from fence originally situated about 23 m upslope of the culvert is now draped over the pipe.



Photo 11.
Looking southwest at toe of slide area. Slide debris continues to move gradually downslope towards the culvert inlet.



Photo 12.
Looking northwards along the east side of the highway near 26+890. Backscarp has encroached into the northbound lane with traffic having to cross centerline to avoid.



Photo 13.
Looking along the east side of the road near 26+800. Three guardrail posts are now hanging



Photo 14.
Looking southwards along the road near 26+800 at backscarp of east side slide which is encroaching about 0.7 m beyond the guardrail. Pavement cracks have grown in the middle of the northbound lane since 2012. Thurber test hole TH12-1 from September 2012 investigation can be seen in lower left corner.



Photo 15.
Asphalt cracking extends south of patched area.