

**ALBERTA TRANSPORTATION
GEOHAZARD ASSESSMENT PROGRAM
PEACE REGION–GRANDE PRAIRIE
2022 INSPECTION REPORT**



Site Number	Location	Name	Hwy	km
GP029	Saddle (Burnt) River Crossing North Valley Slope	RR771 Slide (Church Camp)	2:70	11.881
Legal Description		UTM Co-ordinates		
NW¼4-077-05-W6M		11U E 393076	N 6168469	

	Date	PF	CF	Total
Previous Inspection:	28-May-2020	11	6	66
Current Inspection:	17-May-2022	11	6	66
Road AADT:	3260		Year:	2021
Inspected by:	Ed Szmata, AT Max Shannon, AT Kristen Tappenden, AT Austin Dillman, AT Ken Szmata, AT		Don Proudfoot, Thurber Nicole Wilder, Thurber Barry Meays, Thurber	
Report Attachments:	<input checked="" type="checkbox"/> Photographs <input checked="" type="checkbox"/> Plans <input type="checkbox"/> Maintenance Items			

Primary Site Issue:	<p>This section of Highway 2:70 is located adjacent to the crest of the valley slope on the west side of the Saddle (Burnt) River. The highway was widened further east in 2013 to accommodate the construction of a new northbound passing lane. A portion of the passing lane was likely constructed over the backscarp of an existing landslide on the west valley slope.</p> <p>River erosion at the toe of valley slope undermines the global stability of the overall valley slope in combination with artesian conditions observed to occur at this site.</p>	
Dimensions:	<p>The cracks observed on the ACP surface of the Hwy 2:70 indicated that the landslide backscarp extended beyond the SBL shoulder and into the west highway ditch. The lateral extent of the cracks observed in the ACP indicated that the affected area is about 240 m in width.</p>	
Maintenance:	<p>Previously several ACP patches were observed in a small section of the SBL as well as a section of both NBLs over the previously distressed areas near the intersection between Highway 2:70 and Township Road 771 in 2019. The site on all lanes was chip sealed in 2021 immediately prior to when we would have inspected the site in 2021. Hence why the 2021 inspection was postponed to 2022.</p>	
Observations:	Description	Worsened?
<input checked="" type="checkbox"/> Pavement Distress	<p>Cracks are showing through the chip seal that was placed in 2021 with opening width up to 80 mm were observed on the shoulder of SBL. The scarp crack observed in the pavement extended 200 m further south through all lanes and into the east shoulder. The cracks in the east shoulder are about 20 mm in width. A crack extended about 50 m further south running parallel to a crack directly east of the crack</p>	<input checked="" type="checkbox"/>

	extension. There is also a dip in the road that is evident when cars drive over the surface.	
<input checked="" type="checkbox"/> Slope Movement	The readings of the SIs installed in 2017 indicated the presence of a deep slip surface at a depth about 45 m below the existing ground surface. There were also movement zones observed between 17 m and 33 m depth below ground surface. Only SI17-5 did not show movement; however, this may be installed too shallow.	<input checked="" type="checkbox"/>
<input type="checkbox"/> Erosion		<input type="checkbox"/>
<input checked="" type="checkbox"/> Seepage	Ponded water observed mid-slope northeast of SI-2 appeared to have more water.	<input checked="" type="checkbox"/>
<input type="checkbox"/> Bridge/Culvert Distress		<input type="checkbox"/>
<input type="checkbox"/> Other		<input type="checkbox"/>
Instrumentation:		
SI-1 (Destroyed)	Installed at about 20 m downslope (east) of Hwy 2:70 as a part of the 2007 geotechnical investigation program. This SI was likely destroyed during the construction of the northbound climbing lane in 2013. Readings of this SI indicated a slip surface at an approximate elevation of 622.6 m (about 22 m below ground surface).	
SI-2	Installed about 60 m downslope of the Hwy 2:70 NBL at approximately the middle of the Saddle (Burnt) River west valley slope. This SI showed a rate of slope movement of: 1.8 mm/yr within depths from 6.4 m to 9.5 m below the existing ground surface during the spring 2022 readings. A movement zone within depths of 34.4 m to 35.1 m showed a rate of slope movement of 1.5 mm/yr during the spring 2022 readings.	
SI-3	Installed about 120 m downslope of the Hwy 2:70 NBL, approximately 20 m west of the crest of the top of bank of the lower terrace of the Saddle (Burnt) River. This SI showed a rate of movement of: 5.6 mm/yr within depths from 4.5 m to 7 m in spring 2022. The SI showed 0.5 mm/yr within depths of 9.4 m to 10.6 m in spring 2022.	
PN-2	Installed at the same location as SI-2 with the tip at an elevation of 629.66 m. The measured piezometric surface was 0.02 m above ground surface (B.G.S) indicating an increase in water level of approximately 1.3 m since the fall 2021 readings.	
PN-3	Installed at the same location as SI-3. Piezometer leads were damaged. The last water level measured in 2014 was at an elevation of about 626 m (approximately 5 m below ground surface).	
SI17-1	Installed about 12 m downslope of the Hwy 2:70 NBL, opposite of Township Rd 771. This SI previously showed a rate of movement of 4.1 mm/yr within depths from 25 m to 26.3 m and 16.7 mm/yr within depths of 31.8 m to 33 m. However, this SI has since sheared off at 33.2 m below the ground surface.	
SI17-2	Installed about 55 m downslope of the Hwy 2:70 NBL and 43 m downslope of SI17-1. This SI showed a rate of movement of: 3.1 mm/yr within depths from 17.2 m to 19.7 m. The SI showed a zone of movement with rate of movement of 1.0 mm/yr within depths of 21.5 m and 23.3 m and showed a rate of movement of: 8.0 mm/yr within depths of 48.3 m to 50.8 m in spring 2020. However, this SI has since sheared off at 50.6 m below the ground surface.	
SI17-3	Installed about 137 m downslope of the Hwy 2:70 NBL and 75 m downslope of SI17-2. This SI showed a rate of movement of:	

	58.2 mm/yr within depths from 42.2 m to 44.6 m in Fall 2019; however, this SI has since sheared off at 43.6 m below the ground surface.
SI17-4	Installed about 112 m downslope of the Hwy 2:70 NBL and 25 m north of SI-3. This SI showed a rate of movement of: 17.1 mm/yr within depths from 37.4 m to 39.2 m and a rate of movement of: 59.9 mm/yr within depths of 43.5 m to 45.3 m in Fall 2018; however, this SI has since sheared off at 45.1 m below the ground surface.
SI17-5	Installed about 12 m west of Hwy 2:70 SBL and about 80 m upslope from SI-2. This SI has shown no discernable movement since installation.
PN17-1A PN17-1B	Installed at same location as SI17-1 with PN17-1A and PN17-1B tips at elevations of 633.9 m and 610.5 m (11.7 m and 35.0 m B.G.S.), respectively. Both PN17-1A and PN17-1B are not functioning now.
PN17-2A PN17-2B PN17-2C	Installed at same location as SI17-2 with PN17-2A, PN17-2B and PN17-2C tips at elevations of 628.4 m, 598.5 and 587.9 m (10.2 m, 40.1 m, and 50.8 m B.G.S.), respectively. PN17-2A showed an increase in water level of 0.77 m, PN17-2B showed an increase in water level of 0.64 m and PN17-2C showed an increase in water level of 0.28 m since the fall 2021 readings.
PN17-3A PN17-3B PN17-3C	Installed at same location as SI17-3 with PN17-3A, PN17-3B and PN17-3C tips at elevations of 603.8 m, 591.3 and 581.4 m (25.7 m, 38.2 m, and 48.1 m B.G.S.), respectively. PN17-3A has not been functioning since installation. PN17-3B and PN17-3C both showed an increase of 0.50 m and 0.56 m, respectively in water levels since the fall 2021 readings, respectively.
PN17-4A PN17-4B PN17-4C	Installed at same location as SI17-4 with PN17-4A, PN17-4B and PN17-4C tips at elevations of 606.3 m, 590.9 and 582.7 m (24.9 m, 40.3 m, and 48.5 m B.G.S.), respectively. PN17-4A and PN17-4B showed decreases in water levels of 0.07 m and 0.21 m, respectively and PN17-4C showed an increase in water level of 0.49 m since the fall 2021 readings. PN17-4C shows the ground water level to be 7.53 m above ground surface.
PN17-5A PN17-5B	Installed at same location as SI17-5 with PN17-5A and PN17-5B tips at elevations of 633.2 m and 612.0 m (14.2 m and 35.4 m B.G.S.) respectively. PN17-5A showed an increase in water levels of 0.28 m and PN17-5B showed a decrease in water level of 0.14 m since the fall 2021 readings.
SP17-6	Installed in the farmers field about 125 m south of SI17-5 and showed a decrease of 0.72 m in water level since the fall 2021 readings.
Assessment:	
<p>Cracks on the ACP surface have been regularly observed and patched/chip sealed yearly since 2004. The distress and cracking of the pavement observed at the site since 2014 are likely the result of the widening of the roadway and the construction of pavement over the backscarp of the existing landslide.</p> <p>The depth of the slip surface previously observed in the slope inclinometer SI-1 was about 22 m below the existing ground surface, indicating that the landslide affecting the highway is a deep-seated slope failure. The new SIs installed on September 2017 indicated that the landslide failure plane is even deeper, at approximately 45 m depth. The cracks observed in the ACP indicated that the backscarp of the landslide extended into the west highway ditch beyond the SBL.</p> <p>The instruments installed in 2017 confirmed that the landslide affecting the highway is in fact a deep-seated landslide driven by artesian groundwater conditions; therefore, the most feasible mitigation measure is to realign the highway further west out of the landslide area. The conventional slope stabilization measures such as toe berms and pile walls are not considered to be feasible alternatives.</p>	

A preliminary design for a highway re-alignment was carried out by Thurber and WSP to by-pass the affected area. The preliminary design was submitted to AT in July 2018.

On July 24, 2018 a call-out was performed at this site as Mr. Ken Misik, AT's MCI for this area observed a pronounced dip at the inner wheel path of the road. A copy of the call-out letter dated August 16, 2018 is included in the site binder.

Currently, a detailed design for highway re-alignment is being carried out by Thurber and WSP. A key issue for the finalization of the detailed design is related to obtaining agreements for pipeline crossing and existing oil wells along the proposed re-alignment, in addition to the acquisition of additional ROW.

Recommendations:	Ballpark Cost
-------------------------	----------------------

In the short term, the development of the cracks on in the ACP surface of the roadway should be regularly monitored. Cracks should be timely patched/sealed to prevent surface water infiltration into the landslide backscarp.	Monitoring
---	------------

Closure

It is a condition of this letter report that Thurber's performance of its professional services will be subject to the attached Statement of Limitations and Conditions.

Yours very truly,
Thurber Engineering Ltd.
Don Proudfoot, P.Eng.
Principal | Senior Geotechnical Engineer

Nicole Wilder, M.Eng., P.Eng.
Geotechnical Engineer



STATEMENT OF LIMITATIONS AND CONDITIONS

1. STANDARD OF CARE

This Report has been prepared in accordance with generally accepted engineering or environmental consulting practices in the applicable jurisdiction. No other warranty, expressed or implied, is intended or made.

2. COMPLETE REPORT

All documents, records, data and files, whether electronic or otherwise, generated as part of this assignment are a part of the Report, which is of a summary nature and is not intended to stand alone without reference to the instructions given to Thurber by the Client, communications between Thurber and the Client, and any other reports, proposals or documents prepared by Thurber for the Client relative to the specific site described herein, all of which together constitute the Report.

IN ORDER TO PROPERLY UNDERSTAND THE SUGGESTIONS, RECOMMENDATIONS AND OPINIONS EXPRESSED HEREIN, REFERENCE MUST BE MADE TO THE WHOLE OF THE REPORT. THURBER IS NOT RESPONSIBLE FOR USE BY ANY PARTY OF PORTIONS OF THE REPORT WITHOUT REFERENCE TO THE WHOLE REPORT.

3. BASIS OF REPORT

The Report has been prepared for the specific site, development, design objectives and purposes that were described to Thurber by the Client. The applicability and reliability of any of the findings, recommendations, suggestions, or opinions expressed in the Report, subject to the limitations provided herein, are only valid to the extent that the Report expressly addresses proposed development, design objectives and purposes, and then only to the extent that there has been no material alteration to or variation from any of the said descriptions provided to Thurber, unless Thurber is specifically requested by the Client to review and revise the Report in light of such alteration or variation.

4. USE OF THE REPORT

The information and opinions expressed in the Report, or any document forming part of the Report, are for the sole benefit of the Client. NO OTHER PARTY MAY USE OR RELY UPON THE REPORT OR ANY PORTION THEREOF WITHOUT THURBER'S WRITTEN CONSENT AND SUCH USE SHALL BE ON SUCH TERMS AND CONDITIONS AS THURBER MAY EXPRESSLY APPROVE. Ownership in and copyright for the contents of the Report belong to Thurber. Any use which a third party makes of the Report, is the sole responsibility of such third party. Thurber accepts no responsibility whatsoever for damages suffered by any third party resulting from use of the Report without Thurber's express written permission.

5. INTERPRETATION OF THE REPORT


- a) Nature and Exactness of Soil and Contaminant Description: Classification and identification of soils, rocks, geological units, contaminant materials and quantities have been based on investigations performed in accordance with the standards set out in Paragraph 1. Classification and identification of these factors are judgmental in nature. Comprehensive sampling and testing programs implemented with the appropriate equipment by experienced personnel may fail to locate some conditions. All investigations utilizing the standards of Paragraph 1 will involve an inherent risk that some conditions will not be detected and all documents or records summarizing such investigations will be based on assumptions of what exists between the actual points sampled. Actual conditions may vary significantly between the points investigated and the Client and all other persons making use of such documents or records with our express written consent should be aware of this risk and the Report is delivered subject to the express condition that such risk is accepted by the Client and such other persons. Some conditions are subject to change over time and those making use of the Report should be aware of this possibility and understand that the Report only presents the conditions at the sampled points at the time of sampling. If special concerns exist, or the Client has special considerations or requirements, the Client should disclose them so that additional or special investigations may be undertaken which would not otherwise be within the scope of investigations made for the purposes of the Report.
- b) Reliance on Provided Information: The evaluation and conclusions contained in the Report have been prepared on the basis of conditions in evidence at the time of site inspections and on the basis of information provided to Thurber. Thurber has relied in good faith upon representations, information and instructions provided by the Client and others concerning the site. Accordingly, Thurber does not accept responsibility for any deficiency, misstatement or inaccuracy contained in the Report as a result of misstatements, omissions, misrepresentations, or fraudulent acts of the Client or other persons providing information relied on by Thurber. Thurber is entitled to rely on such representations, information and instructions and is not required to carry out investigations to determine the truth or accuracy of such representations, information and instructions.
- c) Design Services: The Report may form part of design and construction documents for information purposes even though it may have been issued prior to final design being completed. Thurber should be retained to review final design, project plans and related documents prior to construction to confirm that they are consistent with the intent of the Report. Any differences that may exist between the Report's recommendations and the final design detailed in the contract documents should be reported to Thurber immediately so that Thurber can address potential conflicts.
- d) Construction Services: During construction Thurber should be retained to provide field reviews. Field reviews consist of performing sufficient and timely observations of encountered conditions in order to confirm and document that the site conditions do not materially differ from those interpreted conditions considered in the preparation of the report. Adequate field reviews are necessary for Thurber to provide letters of assurance, in accordance with the requirements of many regulatory authorities.

6. RELEASE OF POLLUTANTS OR HAZARDOUS SUBSTANCES

Geotechnical engineering and environmental consulting projects often have the potential to encounter pollutants or hazardous substances and the potential to cause the escape, release or dispersal of those substances. Thurber shall have no liability to the Client under any circumstances, for the escape, release or dispersal of pollutants or hazardous substances, unless such pollutants or hazardous substances have been specifically and accurately identified to Thurber by the Client prior to the commencement of Thurber's professional services.


7. INDEPENDENT JUDGEMENTS OF CLIENT

The information, interpretations and conclusions in the Report are based on Thurber's interpretation of conditions revealed through limited investigation conducted within a defined scope of services. Thurber does not accept responsibility for independent conclusions, interpretations, interpolations and/or decisions of the Client, or others who may come into possession of the Report, or any part thereof, which may be based on information contained in the Report. This restriction of liability includes but is not limited to decisions made to develop, purchase or sell land.



- LEGEND**
- ⊗ TEST HOLE FOR HIGHWAY REALIGNMENT
 - APPROXIMATE LOCATION OF INSTRUMENT
 - ⊕ APPROXIMATE LOCATION OF FORMER INSTRUMENT
 - ⊖ APPROXIMATE LOCATION OF FORMER TEST HOLE
 - SI SLOPE INCLINOMETER
 - PN PNEUMATIC PIEZOMETER
 - ▲ SCARP CRACK
 - CRACK
 - OP— OVERHEAD POWER LINE (APPROXIMATE)
 - GUARDRAIL (APPROXIMATE)
 - APPROXIMATE LOCATION OF ABANDONED WELL
 - BURIED TELUS CABLE (APPROXIMATE)
 - ①➔ DIRECTION AND NUMBER OF PHOTO

- NOTES :**
1. FEATURE LOCATIONS ARE APPROXIMATE
 2. PREVIOUS OBSERVATIONS SHOWN IN BLACK
 3. MAY 18, 2022 FEATURES SHOWN IN RED
- 0 25 50 75 100 150 200 m
SCALE 1:3000




**PEACE REGION (GRANDE PRAIRIE)
GP29-1: HWY 2:70 RR771 SLIDE**

2022 INSPECTION FIGURE

DWG No. 32123-GP29-1-1

DRAWN BY	ML
DESIGNED BY	NPW
APPROVED BY	RVC
SCALE	1:3000
DATE	OCTOBER 2022
FILE No.	32123



THURBER ENGINEERING LTD.



Photo 1.
Looking southwest from middle of highway about 50 m north of the intersection between Hwy 2:70 and Township Road 771.



Photo 2.
Looking at cracks in ACP patch in the northeast outer NB passing lane.



Photo 3.
Looking south
standing near
Township Road
771 looking at
crack in the SBL.



Photo 4.
Looking south at
the cracks in the
SBL shoulder just
south of Township
Road 771.



Photo 5.
Looking south at cracks observed crossing both NBL and extending into the shoulder.



Photo 6.
Looking north from highway embankment to the east where scarp crack was observed and was slightly more grown over in 2022.



Photo 7.
Looking east at low lying wet land area where water was ponded.



Photo 8.
Looking south at cracks observed crossing both NBL.