

**ALBERTA TRANSPORTATION  
GEOHAZARD ASSESSMENT PROGRAM  
PEACE REGION (GRANDE PRAIRIE DISTRICT- NORTH)  
2022 INSPECTION**



Site Number	Location	Name	Hwy	km
PH024	11 km W. Cleardale	Clear River East Hill-(Old Site 8)	64:02	24.2-25.5
Legal Description		UTM Co-ordinates (NAD 83)		
NE27/SE34-84-11-W6		11 N 6244830	E 336445	

	Date	PF	CF	Total
<b>Previous Inspection:</b>	July 14, 2021	9	4	36 (Risk Eros. Scale)
<b>Current Inspection:</b>	May 17, 2022	9	4	36 (Risk Eros. Scale)
<b>Road AADT:</b>	290		<b>Year:</b>	2021
<b>Inspected By:</b>	Don Proudfoot, Barry Meays (Thurber). Ed Szmata, Kristin Tappenden, Austin Dillman, Ken Szmata, Max Shannon (AT)			
<b>Report Attachments:</b>	<input checked="" type="checkbox"/> Photographs <input checked="" type="checkbox"/> Plans <input checked="" type="checkbox"/> Maintenance Items			

<b>Primary Site Issue:</b>	Erosion of the highway south ditch and embankment shoulder (took place in 2013, 2018, 2019, and again in 2020). Caused by water backup/release ovetop of the 1200 mm CSP culvert inlet which had iced up and was unable to handle all of the flow northwards beneath the highway from the spring melt. Also, some gabion drop structure erosion along the north ditch channel.		
<b>Dimensions:</b>	South embankment/ditch/channel erosion ~900m long x <7m wide x <2m deep; North gabion erosion ~50m long x 20m wide x 5m deep.		
<b>Date of any remediation:</b>	1979 - North ditch gabion liner at select locations, channel shaping. 2008 - Slide excavation/subdrains/recompaction, erosion repair, drainage re-routing, 1200 CSP repair/extension, embankment fill and backslope flattening. 2020 - MC performed culvert maintenance, excavated out south hwy embankment & loose ditch erosion material, and lined the south ditch/embankment with 6-80 gravel along an upper ~7% reach, Class 2 riprap along the middle ~9% reach, and left the lower reach unlined west of the 760 mm SWSP cross culvert.		
<b>Maintenance:</b>	August 2008 - Asphalt overlay. 2013, 2018 - Pitrun placed to infill major erosion locations along the south highway embankment immediately after the spring flow events. 2016 - WB lane ACP patch adjacent to SI. 2017 (Fall) - Chip seal. 2019 – Excavated south ditch erosion and backfilled with pitrun covered by TRM.	<b>Worsened?</b>	
<b>Observations:</b>	<b>Description</b>	<b>Yes</b>	<b>No</b>
<input checked="" type="checkbox"/> Pavement Distress	A 3m long crack observed in the WB shoulder directly below the creeping north backslope area at the east end of the site. Some erosion and undermining of the south (eastbound) shoulder, with a few cracks and vertical drop off along the edge of paved shoulder (repaired most recently in 2020).	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/> Slope Movement	Along the toe (~10 m high) of the natural south valley slope near the 1200 CSP inlet area due to softening from saturation and rapid drawdown. Also, creep movement in the north backslope area at the east end of the site. Also, a 10m wide x 3m high slump in south ditch backslope.	<input checked="" type="checkbox"/>	<input type="checkbox"/>

<input checked="" type="checkbox"/> Erosion	<p>The ditch along the south highway embankment became severely eroded from the spring, 2020 and 2019 flows, incising through the pitrun gravel placed in 2018 and 2019, and carried down-gradient and deposited near the west end of the site (ditch/embankment were repaired in 2020). This erosion extended southwards into the bush due to the over-flow water along the south ditch.</p> <p>There was retrogressive slumping around two of the north ditch gabion drop structures (50 m long, across and upstream of the 760 mm dia. culvert outlet) that were completely destroyed from previous flood events. Below the outlet of the 760 mm dia. SWSP (where riprap was added in 2020), a gully has formed along the west edge of the riprap and joined the gully around the gabion drop structure.</p> <p>1 m deep scour holes across the north ditch channel exist (1 about midway between the 760 mm dia. and 810 mm dia. culvert outlets, and another below the 760 mm outlet).</p> <p>Rilling outside the guardrail along the north highway embankment edge over a length of ~100 m, due to excess sanding gravel build-up (east half was graded in 2020, west half remains).</p>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Seepage	<p>From former/existing subdrains in south ditch and Lookout slide.</p>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Bridge/Culvert Distress	<p>The 1200 mm dia. culvert outlet has a slight oval shape beneath the settled area.</p> <p>The 810 CSP cross-culvert that was ½ full of sediment was flushed/cleaned in 2020.</p> <p>The pitrun covered inlet and outlet areas of the 760 mm dia. SWSP cross-culvert were flushed/cleaned and the pitrun removed in 2020.</p>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/> Other		<input type="checkbox"/>	<input type="checkbox"/>
<p><b>Instrumentation:</b></p> <p>Inclinometer SI08-1, last read June 4, 2011 – No discernable movement since the fall of 2009.</p>			
<p><b>Assessment</b> (Refer to Figures PH024-1-1, -2, &amp; -3):</p> <p>A surge of meltwater occurred during spring thaw in 2013 along the channel leading to the south embankment near the east end of this site, at the entrance of the 1200 mm dia. CSP culvert that drains northwards beneath the highway. It was likely joined by highway ditch runoff meltwater further east, which also drains down along the south embankment and outlets in front of the 1200 mm inlet via the 900 mm dia. SWSP. The volume of water was greater than the culvert could handle (it is also possible that ice was also restricting the culvert), causing the water to back up overtop the inlet/headwall. It backed up high enough (10 to 12 m of head) that the water flowed westwards along the toe of the south embankment, then along the south highway ditch, and finally southwest away from the highway through the bush (it was documented to have subsided by the next morning). In addition to eroding soil, it eroded the erosion control soil covers, and some of the buried subdrain that was installed in the south ditch in 2008. This scenario was forecast as part of the 2007 design measures, prior to the 2008 construction, where the culvert was estimated to only handle a 1 in 5-year design flood peak, which would result in a build-up of water for events greater than 1 in 5 years. Similar occurrences took place during the spring flow events in 2018, again between April 1 to 3, 2019, and again in 2020. Ice build-up at the inlet of the CSP culvert was documented by the maintenance contractor LaPrairie as a cause of the 2019 event.</p>			

There was no backed up overflow into the south ditch in 2022 (LaPrairie cleared a bit of snow/ice prior to spring break-up).

The pitrun gravel that was used to fill 2018's erosion event was eroded and washed downslope, filling the south ditch near the west end, and water also ran overtop the highway and down the north embankment at one location. LaPrairie used a backhoe to dig part of the ditch out and swept the excess pitrun off the road. Similar south ditch erosion occurred in spring, 2020 after the 2019 installation of pitrun with TRM cover. As shown on Drawings PH024-1-2 and -3, the 2020 repairs involved grading the south embankment with 6-80 gravel, and installing a south ditch liner consisting of: 6-80 gravel over a 130 m upper channel length where the average gradient was ~7 percent; then installing Class 2 riprap along the center portion of this channel over a 110 m length extending up to the 760 mm SWSP culvert where the gradient was ~9 percent, as shown on Section D-D'; and then left the lower ditch bottom unlined west of the 760 SWSP (where a modest ditch block was constructed), as shown on Section C-C'. The 9 percent gradient is likely too steep, and flood surge flows too large, for these prior ditch liner repair attempts consisting only of 6-80 (pitrun) gravel. This section of the ditch bottom that was lined with Class 2 riprap should be an improvement, but the riprap may have to be extended further eastwards.

The 810 mm diameter culvert had been half full of sediment for several years. This culvert appears to have been originally installed to bring water from the south ditch across to the north side of the highway for discharge via the 1.04 m dia. SWSP centreline pipe down into the dissipation pool on the south side of the highway. It appeared that this pipe had not been allowing flow to the north side either due to lack of maintenance or after it was purposely blocked. This culvert was cleaned out in 2020, and the inlet was formed with a riprap covered inlet bowl and a downstream ditch block that grades downwards to the south which would appear to let flood water overflow to the west through the bush if this culvert backs up flow.

The backed-up water from the flood surges nearer the inlet of the 1200 mm dia. culvert saturated the native soil along the toe of the natural valley slope and combined with toe erosion from flowing water and a likely sudden drawdown scenario, caused toe slumping of the natural tree covered slope. This has gotten worse the last couple of years but is not currently affecting the functionality of the site, although some slide debris was observed beyond the toe of the slope in 2021.

On the north side of the highway, the 1200 mm dia. CSP flowing full was also likely combined with runoff from the area/slopes to the north, which caused damage to two of the steeper sloping gabion lined channel sections further west and created a scour hole in the channel further west of this. The channel was overgrown with trees which reduced the flow capacity causing water to flow around and erode the sides of the gabion structure. In the 2013 event, there was also an erosion scour around the outlet of the 760 mm dia. SWSP in the north ditch, resulting from runoff originating from the south ditch flowing beneath the highway, which may have also contributed to the large erosion feature around the gabions immediately west (downslope) of this outlet. Both the inlet and outlet of this pipe were covered with pitrun in 2019, but this culvert was flushed/cleaned in 2020. A runoff gully has since formed beyond this culvert outlet and joined the gully that exists around the channel gabion.

It was also indicated by AT that it is planned to bore another cross-culvert across the hwy (between the existing 1200 mm CSP culvert inlet and the present gravel lined south ditch), and then line the remaining segment with riprap west of this up to the current Class 2 riprap liner, to help pass more spring flood surge flows from the south ditch over to the north side of the hwy.

**Recommendations:**

**Cost**

**Maintenance:**

The highway side of the south ditch erosion was backfilled with pitrun gravel in 2013 (~400 m<sup>3</sup>), in 2018, in 2019, and again in 2020 as emergency measures to re-establish the eroded/undermined highway embankment. Additional gravel should be placed as required against the edge of asphalt to buttress the pavement and maintain hazard-free traffic safety.

The 1200 mm dia. CSP inlet should be inspected and steamed each spring (if required) to remove ice build-up with a backhoe and establish unrestricted flow. We recommend that this late winter/early spring

check and steaming be formally added to the maintenance contractor's annual maintenance work requirements (as was done in 2022, which may have prevented an overflow). **\$5,000 annually**

Some of the rilling erosion near the north hwy embankment guardrail had been graded/smoothened. Repair the remaining rill erosion outside the north edge of the guardrail and along the edge of the eroded ACP north shoulder by first grading the existing surface, then adding/track-packing/shaping a few loads of gravel infill (Photo 14), and then covering with topsoil and TRM. **\$5,000**

Grade/shape the downstream banks of the ditch blocks at the inlets of the 760mm SWSP and the 810mm CSP, and then add some Class 2 riprap over non-woven geotextile to induce more flow into these culverts. **\$5,000**

Clean out future slide toe debris accumulations from in front of the 1200 culvert inlet area, and along the south ditch, if required.

#### **Short Term:**

The damaged gabion structures on the north side of the highway need to be reconstructed to their original condition. The downstream end of the damaged gabion drop structure furthest west (Section A-A' on Drawings PH24-1-1 and -3) should have the sideslopes trimmed back flatter, and then use some of this material to build up the bed, before armouring the bottom and sideslopes. Consideration could be given to lining the replacement structures with Class 2 riprap instead of gabion mattress.

**Ballpark Cost \$150,000**

The main 1200 mm dia. CSP should be inspected with a camera inserted along the pipe to see if it is restricted or damaged in any way, or if the joints are compromised which could lead to water leaking out and creating erosion around the outside of the pipe. To prevent future icing of the culvert inlet, perhaps a permanent heat system consisting of heat wires inside small metal tubing attached to the inside of the culvert inlet over a 10 m length and powered by a solar cell mounted on a post with a battery backup could be employed. **\$75,000**

The 150 mm dia. and 150 m long CSP subdrain near the east end of the south ditch (installed as part of the 2008 repairs to intercept seepage and keep water levels lower above the former Lookout Slide) should be replaced and outlet it onto the ditch surface further west. **\$50,000**

As a minimum, the ~330 m long segment of the currently unlined south ditch bottom extending west of the riprap lined segment up to the 810 CSP culvert, should be topsoiled, seeded, and covered with TRM. **\$10,000**

The erosion gully between the outlet of the recently opened 760 mm diameter SWSP and north channel should be repaired by grading a trapezoidal channel and lining it with Class 1 riprap over non-woven geotextile. **Ballpark Cost \$20,000**

#### **Medium Term:**

Future erosion along the toe of the south highway embankment and ditch is still a potential threat to the highway and although some repairs were performed in 2020, supplementary repairs might still be needed. A Class 2 riprap south ditch bottom segment ~110 m long was installed in 2020, but a hard armour liner (such as riprap or gabion mattress) should extend over the entire ditch that has a ~9 % gradient (to the 810 CSP inlet at the west end) and may also need to be extended further east over the present 130 m long ~7% gravelled ditch segment (also installed in 2020).

**Ballpark Cost \$350,000**

The 150 m length of the south ditch away from the highway in the bush near the west end, should also be repaired. Even if the now cleaned and flushed 810 mm and 760 mm diameter centreline culverts (and a proposed new centerline bore, discussed below) take some flow to the north and then through the 1.04 SWSP beneath the hwy, there may still be some flow extending down the south bank through this eroded area. A more durable fix for this section would be to **a)** infill the eroded areas with clay compacted in thin lifts using a sheepsfoot compactor, grading the surface and then covering it with gabion mattress all the way down to the stilling pool.

**Ballpark Cost \$150,000**

**Or alternatively,**

**b)** A cheaper stop gap approach for the 150 m length away from the highway would be to fill the eroded areas with Class 1 riprap placed over non-woven geotextile in the upper slope area and construct a riprap lined drop structure on the lower 20° slope above the 1040 mm SWSP outlet (1.9 m headscarp area) to dissipate flows upslope of the stilling basin.

**Ballpark Cost \$80,000**

**Long Term**

As mentioned in the assessment section of this report, it is planned to bore another cross-culvert across the hwy (somewhere between the existing 1200 mm CSP culvert inlet and the present gravel lined south ditch), and then line the remaining segment with riprap west of this up to the current Class 2 riprap liner, to help pass more spring flood surge flows from the south ditch over to the north side of the hwy (assumed 200 m long x <10 m deep). If this longer term repair is completed it would replace some of the medium term work.

**Ballpark Cost \$700,000**

**CLOSURE**

It is a condition of this letter report that Thurber's performance of its professional services will be subject to the attached Statement of Limitations and Conditions.

Don Proudfoot, P.Eng.  
Principal | Senior Geotechnical Engineer

Barry Meays, P.Eng.  
Senior Geotechnical Engineer



## STATEMENT OF LIMITATIONS AND CONDITIONS

### 1. STANDARD OF CARE

This Report has been prepared in accordance with generally accepted engineering or environmental consulting practices in the applicable jurisdiction. No other warranty, expressed or implied, is intended or made.

### 2. COMPLETE REPORT

All documents, records, data and files, whether electronic or otherwise, generated as part of this assignment are a part of the Report, which is of a summary nature and is not intended to stand alone without reference to the instructions given to Thurber by the Client, communications between Thurber and the Client, and any other reports, proposals or documents prepared by Thurber for the Client relative to the specific site described herein, all of which together constitute the Report.

IN ORDER TO PROPERLY UNDERSTAND THE SUGGESTIONS, RECOMMENDATIONS AND OPINIONS EXPRESSED HEREIN, REFERENCE MUST BE MADE TO THE WHOLE OF THE REPORT. THURBER IS NOT RESPONSIBLE FOR USE BY ANY PARTY OF PORTIONS OF THE REPORT WITHOUT REFERENCE TO THE WHOLE REPORT.

### 3. BASIS OF REPORT

The Report has been prepared for the specific site, development, design objectives and purposes that were described to Thurber by the Client. The applicability and reliability of any of the findings, recommendations, suggestions, or opinions expressed in the Report, subject to the limitations provided herein, are only valid to the extent that the Report expressly addresses proposed development, design objectives and purposes, and then only to the extent that there has been no material alteration to or variation from any of the said descriptions provided to Thurber, unless Thurber is specifically requested by the Client to review and revise the Report in light of such alteration or variation.

### 4. USE OF THE REPORT

The information and opinions expressed in the Report, or any document forming part of the Report, are for the sole benefit of the Client. NO OTHER PARTY MAY USE OR RELY UPON THE REPORT OR ANY PORTION THEREOF WITHOUT THURBER'S WRITTEN CONSENT AND SUCH USE SHALL BE ON SUCH TERMS AND CONDITIONS AS THURBER MAY EXPRESSLY APPROVE. Ownership in and copyright for the contents of the Report belong to Thurber. Any use which a third party makes of the Report, is the sole responsibility of such third party. Thurber accepts no responsibility whatsoever for damages suffered by any third party resulting from use of the Report without Thurber's express written permission.

### 5. INTERPRETATION OF THE REPORT

- a) Nature and Exactness of Soil and Contaminant Description: Classification and identification of soils, rocks, geological units, contaminant materials and quantities have been based on investigations performed in accordance with the standards set out in Paragraph 1. Classification and identification of these factors are judgmental in nature. Comprehensive sampling and testing programs implemented with the appropriate equipment by experienced personnel may fail to locate some conditions. All investigations utilizing the standards of Paragraph 1 will involve an inherent risk that some conditions will not be detected and all documents or records summarizing such investigations will be based on assumptions of what exists between the actual points sampled. Actual conditions may vary significantly between the points investigated and the Client and all other persons making use of such documents or records with our express written consent should be aware of this risk and the Report is delivered subject to the express condition that such risk is accepted by the Client and such other persons. Some conditions are subject to change over time and those making use of the Report should be aware of this possibility and understand that the Report only presents the conditions at the sampled points at the time of sampling. If special concerns exist, or the Client has special considerations or requirements, the Client should disclose them so that additional or special investigations may be undertaken which would not otherwise be within the scope of investigations made for the purposes of the Report.
- b) Reliance on Provided Information: The evaluation and conclusions contained in the Report have been prepared on the basis of conditions in evidence at the time of site inspections and on the basis of information provided to Thurber. Thurber has relied in good faith upon representations, information and instructions provided by the Client and others concerning the site. Accordingly, Thurber does not accept responsibility for any deficiency, misstatement or inaccuracy contained in the Report as a result of misstatements, omissions, misrepresentations, or fraudulent acts of the Client or other persons providing information relied on by Thurber. Thurber is entitled to rely on such representations, information and instructions and is not required to carry out investigations to determine the truth or accuracy of such representations, information and instructions.
- c) Design Services: The Report may form part of design and construction documents for information purposes even though it may have been issued prior to final design being completed. Thurber should be retained to review final design, project plans and related documents prior to construction to confirm that they are consistent with the intent of the Report. Any differences that may exist between the Report's recommendations and the final design detailed in the contract documents should be reported to Thurber immediately so that Thurber can address potential conflicts.
- d) Construction Services: During construction Thurber should be retained to provide field reviews. Field reviews consist of performing sufficient and timely observations of encountered conditions in order to confirm and document that the site conditions do not materially differ from those interpreted conditions considered in the preparation of the report. Adequate field reviews are necessary for Thurber to provide letters of assurance, in accordance with the requirements of many regulatory authorities.



### 6. RELEASE OF POLLUTANTS OR HAZARDOUS SUBSTANCES

Geotechnical engineering and environmental consulting projects often have the potential to encounter pollutants or hazardous substances and the potential to cause the escape, release or dispersal of those substances. Thurber shall have no liability to the Client under any circumstances, for the escape, release or dispersal of pollutants or hazardous substances, unless such pollutants or hazardous substances have been specifically and accurately identified to Thurber by the Client prior to the commencement of Thurber's professional services.

### 7. INDEPENDENT JUDGEMENTS OF CLIENT

The information, interpretations and conclusions in the Report are based on Thurber's interpretation of conditions revealed through limited investigation conducted within a defined scope of services. Thurber does not accept responsibility for independent conclusions, interpretations, interpolations and/or decisions of the Client, or others who may come into possession of the Report, or any part thereof, which may be based on information contained in the Report. This restriction of liability includes but is not limited to decisions made to develop, purchase or sell land.

H:\32000\32123 AT GRMP - Grande Prairie District North 2021-2025\CAD\2022\BDM\32123 PH024-1-1-3 1\_11394\_1129.svg.dwg - 1 - Oct. 14, 2022




LEGEND :

- PHOTO & DIRECTION
- SLOPE INCLINOMETERS
- SLIDE SCARP
- EROSION RILL

NOTE:

1. MAY 17, 2022 OBSERVATIONS SHOWN IN RED



SATELLITE IMAGE FROM ESRI WORLD IMAGERY (DOWNLOADED 2019-06-17)



PEACE REGION (GRANDE PRAIRIE DISTRICT - NORTH)  
PH024: HWY 64:02 CLEAR RIVER EAST HILL SLIDE


PH024 INSPECTION

FIGURE PH024-1

DRAWN BY	KLP
DESIGNED BY	BDM
APPROVED BY	DWP
SCALE	1:2500
DATE	MAY 17, 2022
FILE No.	32123



H:\32000\32123 AT GRMP Grande Prairie District North 2021-2025\CAD\2022\BDM\32123 PH024-1-1-3 1\_11394\_1129.sv\$.dwg - 2 - Oct. 14, 2022



**LEGEND :**

- PHOTO & DIRECTION
- SLOPE INCLINOMETERS
- SLIDE SCARP
- EROSION RILL

**NOTE:**

1. MAY 17, 2022 OBSERVATIONS SHOWN IN RED

0 25 50 75 100 125 150m  
SCALE 1:2500

SATELLITE IMAGE FROM ESRI WORLD IMAGERY (DOWNLOADED 2019-06-17)

**PEACE REGION (GRANDE PRAIRIE DISTRICT - NORTH)  
PH024: HWY 64:02 CLEAR RIVER EAST HILL SLIDE**

**PH024 INSPECTION**


**FIGURE PH024-2**

DRAWN BY	KLP
DESIGNED BY	BDM
APPROVED BY	DWP
SCALE	1:2500
DATE	MAY 17, 2022
FILE No.	32123

**THURBER ENGINEERING LTD.**



H:\32000\32123 AT GRMP Grande Prairie District North 2021-2025\CAD\2022\BDM\32123 PH024-1-1-3 1\_11394\_1129.sv8.dwg - 3 - Oct. 14, 2022




*Alberta*

**PEACE REGION (GRANDE PRAIRIE DISTRICT - NORTH)  
PH024: HWY 64:02 CLEAR RIVER EAST HILL SLIDE**

**PH024 CROSS-SECTIONS A-A' & B-B'**

**FIGURE PH024-3**

DRAWN BY	KLP
DESIGNED BY	BDM
APPROVED BY	DWP
SCALE	N.T.S.
DATE	MAY 17, 2022
FILE No.	32123



**THURBER ENGINEERING LTD.**



Photo 1 – Looking west at site from the helicopter.



Photo 2 – Looking south along the eroded bush channel at the west end of the site.



Photo 3 – Looking north at the inlet of the 810 CSP on the south side of the hwy embankment.



Photo 4 – Looking west along the unlined south ditch from near the west end, at the 2020 grading that took place along the south highway embankment and ditch.



Photo 5 – Looking east along the south ditch and hwy embankment.



Photo 6 – Looking at a 12m wide x 3m high toe slump into the south edge of the south ditch.



Photo 7 - Looking west along the unlined south highway ditch from the inlet of the 760 mm dia. SWSP.



Photo 8 – Looking east from the ditch block along the riprapped south ditch channel from the inlet of the 760 mm dia. SWSP.



Photo 9 – Looking west along the south ditch channel and hwy embankment that was lined with 6-80 gravel.



Photo 10 – Looking west at the erosion that formed in 2020 along the boundary of the south embankment fill and the bush line.



Photo 11 - Looking northwest at the 1200 CSP inlet headwall (left), and the 900 SWSP outlet and gabion outlet structure (right).



Photo 12 – Looking south at the valley slope slumping above the 1200 culvert inlet and gabion outlet area, caused by rapid drawdown of built-up floodwater.



Photo 13 – Looking east along the north ditch from the north 900 mm SWSP entrance.



Photo 14 – Looking west at the rilling adjacent to the north guardrail (just west of the repaired rilling on the north embankment).





Photo 15 - Looking southwest at the 810 CSP outlet (left), and the 1040 SWSP inlet (right), at the west end of the north ditch channel.



Photo 16 - Looking west (downstream) along the north ditch channel upstream of the 810 CSP outlet. Note the gabions are still intact here.



Photo 17 – Looking east (upstream) along the north ditch channel at the ongoing erosion and eroded gabion liner just downstream of the 760 SWSP outlet.



Photo 18 - Looking south at the 760 mm SWSP outlet. Note the erosion gully along the west side of the riprap that was added downslope of the culvert in 2020.



Photo 19 – Looking west (downstream) at the erosion just upstream of the 760 SWSP outlet.



Photo 20 - Looking east at the erosion in the north ditch channel at the completely eroded gabion liner between the 760 SWSP and 1200 CSP outlets.



Photo 21 - Looking east at the 1200 CSP outlet area in the north channel.



Photo 22 – Looking northwest at the 1200 culvert outlet area.