

**SITE INSPECTION FORM**

<b>SITE NUMBER AND NAME:</b> GP002 Candle Road Slide		<b>HIGHWAY &amp; KM:</b> 40:38, 7.457	<b>PREVIOUS INSPECTION DATE:</b> June 13, 2023	<b>INSPECTION DATE:</b> <b>June 3, 2025</b>
<b>LEGAL DESCRIPTION:</b> NE 20-61-04-W6M	<b>NAD 83 COORDINATES:</b> UTM    Northing    Easting 11       6017104    398952		<b>RISK ASSESSMENT:</b> PF: 8    CF: 2    TOTAL: 16	
<b>AVERAGE ANNUAL DAILY TRAFFIC (AADT):</b> 900 (north) & 880 (south) (Reference No. 70000673, 2024)			<b>CONTRACT MAINTENANCE AREA (CMA):</b> 504	

<b>SUMMARY OF SITE INSTRUMENTATION:</b>  Operable: In 2023, a reference/survey stake was placed approximately 1 m upslope of the slide scarp to monitor retrogression.  Inoperable: Two slope inclinometers installed in 1997.  LAST READING DATE: N/A	<b>INSPECTED BY:</b> Chris Gräpel (KCB) Courtney Mulhall (KCB) Babatunde Awokunle (TEC) Rocky Wang (TEC)
<b>PRIMARY SITE ISSUE:</b> Slide in highway embankment side-hill fill and foundation on east side of Hwy 40:38 due to a high groundwater table. Site is a repeat failure at a previous repair site completed in 2004 as described below.	
<b>APPROXIMATE DIMENSIONS:</b> Slide approximately 20 m to 40 m wide, and 25 m to 30 m high.	
<b>DATE OF ANY REMEDIAL ACTION:</b> Repaired in 2004 as described below.	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		X	None observed at time of 2025 inspection, except where guardrail struck and damaged as discussed below.		X
Slope Movement	X		Extents of slide area appeared similar to 2021 and 2023 inspections, but some possible additional movement and cracking observed in middle slide area.	X	
Erosion	X		Some erosion of exposed soils along slide scarps.		X
Seepage	X		Seepage previously observed in lower slide area during 2021 inspection. Conditions during 2023 and 2025 inspections were drier at ground surface (some cracks appeared damp, but no visible seepage or ponded water observed).		X
Culvert Distress		X	No culverts observed by KCB.		X

**COMMENTS**

Slide is on an embankment side-hill fill with a shear key excavated into a subsurface bedrock ledge that was previously repaired in 2004 with granular fill and subsurface drains (perforated pipe). TEC previously mentioned that the bedrock ledge was at the same elevation below the slope as it was below the highway (based on borehole logs). Two drain outlets were installed (upper and lower) in case the lower drain became blocked with sediment which was happening in 2004.

Silt fencing observed at the mid-slope and near the tree line at the toe of the slide area, likely the extent of the previous repairs.

Seems to be more rounded gravel and cobbles visible in the upper slide area than the lower slide area. Seems like the lower slide area may have been previously graded with native material and the upper slide area was previously reconstructed with gravelly/granular fill.

Upper slide area (Photos 1 through 3) has settled, and middle and lower slide areas (Photos 4 through 6) appear more active than upper slide area, especially along the left/north side where several scarps have formed.

Slope appears to have failed again due to plugged drains resulting in rising water level and saturation of the repair fill and/or shearing through the bedrock ledge.

Gully near the north side of the slide.

Section of the guardrail along the northbound lane of Hwy 40:38, south of the site, was struck and damaged. Pavement damaged around the posts which were shifted by the impact.

Maintenance/Repair/Monitoring Recommendations:

- A geotechnical site investigation, including installation of geotechnical instruments and possible geophysical surveying, is recommended so repair options can be assessed. Estimated cost: approximately \$250,000.
- Possible repair options could include construction of deep cast-in-place piles, construction of a driven-steel wall, and/or reconstructing the slope with drainage. Estimated cost: approximately \$2,000,000 to \$4,000,000 (deep cast-in-place piles), \$800,000 to \$1,500,000 (driven-steel wall), and/or \$400,000 to \$800,000 (slope reconstruction and drainage – similar to previous repair, which failed), respectively.
- Falling down and/or damaged silt fencing should be removed and disposed.

This report is an instrument of service of Klohn Crippen Berger (KCB). The report has been prepared for the exclusive use of Alberta Transportation and Economic Corridors (Client) (Client) for the specific application to the Peace Region (Grande Prairie District – South) Geohazard Risk Management Program (Contract No. CON0022166), and it may not be relied upon by any other party without KCB's written consent.



KCB has prepared this report in a manner consistent with the level of care, skill and diligence ordinarily provided by members of the same profession for projects of a similar nature at the time and place the services were rendered. KCB makes no warranty, express or implied.

Use of or reliance upon this instrument of service by the Client is subject to the following conditions:

1. The report is to be read in full, with sections or parts of the report relied upon in the context of the whole report.
2. The observations, findings and conclusions in this report are based on observed factual data and conditions that existed at the time of the work and should not be relied upon to precisely represent conditions at any other time.
3. The report is based on information provided to KCB by the Client or by other parties on behalf of the client (Client-supplied information). KCB has not verified the correctness or accuracy of such information and makes no representations regarding its correctness or accuracy. KCB shall not be responsible to the Client for the consequences of any error or omission contained in Client-supplied information.
4. KCB should be consulted regarding the interpretation or application of the findings and recommendations in the report.
5. This report is electronically signed and sealed and its electronic form is considered the original. A printed version of the original can be relied upon as a true copy when supplied by the author or when printed from its original electronic file.

Courtney Mulhall, M.Sc., P.Eng.  
Geotechnical Engineer





**Legend**

- Slide Extent
- Guardrail



NOTES:  
1. HORIZONTAL DATUM: NAD83  
2. GRID ZONE: UTM ZONE 11N  
3. IMAGE SOURCE: 2025 MICROSOFT CORPORATION  
2025 MAXAR CNES, DISTRIBUTION AIRBUS DS  
4. INSTRUMENTS INOPERABLE PRIOR  
TO 2021 NOT SHOWN.

CLIENT

Alberta

Klohn Crippen Berger

PROJECT PEACE REGION (GRANDE PRAIRIE DISTRICT-SOUTH) GEOHAZARD RISK MANAGEMENT PROGRAM		
TITLE Site Plan GP002 - Candle Road Slide Hwy 40:38 km, 7.457		
SCALE 1:2,000	PROJECT No. A05116A01	FIG No. 1



## Inspection Photographs

**Photo 1** Slide backscarp on east side of Hwy 40:38. Photo taken June 3, 2025, facing north.



**Photo 2** Slide backscarp on east side of Hwy 40:38. Photo taken June 3, 2025, facing south.





**Photo 3**      **Looking up across top slide area from north/left flank. Photo taken June 3, 2025, facing southwest.**



**Photo 4**      **Looking down across middle slide area from north/left flank. Photo taken June 3, 2025, facing southeast.**





**Photo 5**      **Looking across middle of slide from north/left flank. Photo taken June 3, 2025, facing south.**



**Photo 6**      **Looking down across lower slide area from middle of slide. Photo taken June 3, 2025, facing southwest.**





**Photo 7** Gully near north side of slide. Photo taken June 3, 2025, facing north.



**Photo 8** Section of guardrail damaged south of site. Photo taken June 3, 2025, facing north.

