

**ALBERTA TRANSPORTATION
GEOHAZARD ASSESSMENT PROGRAM
PEACE REGION (PEACE RIVER DISTRICT)
2022 INSPECTION**



Site Number	Location	Name	Hwy	km
PH034	Judah Hill	Fence Slide	744:04	59.177
Legal Description		UTM Co-ordinates		
SE¼ 29-083-21 W5M		11V E 482792	N 6230946	

	Date	PF	CF	Total
Previous Inspection:	6-July-2021	14	5	70
Current Inspections:	24-May-2022	14	5	70
Road WAADT:	620		Year:	2021
Inspected by:	Tyler Clay, TEL Ed Szmata, TRANS Max Shannon, TRANS		Don Proudfoot, TEL Roger Skirrow, TRANS	
Report Attachments:	<input checked="" type="checkbox"/> Photographs <input checked="" type="checkbox"/> Plans <input type="checkbox"/> Maintenance Items			

Primary Site Issue:	An approximately 50 m wide slide, with its backscarp within the road, was repaired in 2005 by excavating the slide mass (including some old stone columns) and rebuilding the highway with geogrid reinforced fill. Since repairs, settlement and cracking of the pavement have occurred and cracks have extended further south and north of the original slide.	
Dimensions:	Main slide is about 60 m wide at the road shoulder. Additional areas of pavement distress and cracking extend 80 m to 100 m north and south of the main slide.	
Maintenance:	Cracking and dips in pavement were patched in 2008 and again in 2011. Patching has occurred intermittently following these repairs and both the guardrail and posts were replaced in 2009. Highway was closed between May 2013 and December 2013 due to the occurrence of the Sunshine Landslide at km 58.2 further to the south.	
Observations:	Description	Worsened?
<input checked="" type="checkbox"/> Pavement Distress	<p>Near km 59.1 (near S110-12), subsidence within the SBL near the guardrail is up to 150 mm. No significant expansion or change from 2021. (Photo 1)</p> <p>Existing cracks in the SBL shoulder near km 59.13 did not change significantly since 2021.</p> <p>At the main repair area (km 59.14) the cracks in the SBL shoulder are worse and are open up to 100 mm. The depression has a differential drop up to 350 mm with a sharp differential edge in the ACP that is worse from the previous inspection in 2021. (Photos 2 and 3)</p> <p>Pavement condition at km 59.2 had no significant change from 2021. (Photo 6)</p>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/> Slope Movement	At main slide repair area: the previously observed shallow slump and skin failure in the	<input type="checkbox"/>

	<p>clay cap that was constructed over the sideslope during the 2005 repairs had no changes. Except for surficial erosion, slope appears similar to 2021 condition. (Photo 4)</p> <p>A shallow and dry earth slide was noted below SI10-15 on the west sideslope (km 59.25). (Photo 7)</p>	
<input checked="" type="checkbox"/> Erosion	Increased rill erosion is present in the upper sideslope at the main slide repair area (km 59.18).	<input checked="" type="checkbox"/>
<input type="checkbox"/> Seepage		<input type="checkbox"/>
<input type="checkbox"/> Bridge/Culvert Distress		<input type="checkbox"/>
<input checked="" type="checkbox"/> Other	Geogrid installed as part of the 2005 repair has been previously observed becoming exposed on the embankment downslope resulting in a further reduction of its anchoring capacity.	<input type="checkbox"/>

Instrumentation:

SI05-15	Slope inclinometer installed in 2005 at the top of the hill in the ATCO gas utility right of way above the Fence Slide, approximately 30 m elevation above the road, has not shown any consistent trend of movement since installation.
SI10-12 and 15	The Spring 2021 readings for SI10-15 showed a rate of movement of 4.4 mm/yr over 2.4 m to 5.5 m depth. The rate of movement in SI10-15 has shown a generally steady trend since initialization and has typically been between 2 to 7 mm/yr. SI10-12 sheared at 4.9 m depth in Fall 2019.
SI10-13 and 14	SI10-13 and SI10-14 are obstructed at depths of 6.4 m and 5.7 m, which correspond to the approximate elevation of the base of the upper clay fill of the 2005 repair.
PN10-12 and 15	Pneumatic piezometers PN10-12 and PN10-15 showed decreases in groundwater level of 0.04 m and 0.05 m, respectively, since the fall of 2021 readings. The equivalent piezometric depths have shown generally steady trends since initialization in 2010.
PN10-13 and 14	Non-Operational (Pinched or Blocked).

Assessment:

Cracking and settlement at the repair have continued, and cracking is re-appearing through the 2011 asphalt patch and continues to worsen along the road shoulder to the north and south of the main slide. The shearing or buckling of SI10-13 and SI10-14 indicate that slide movement or settlement is occurring at a steady rate in the clay backfill from the 2005 repair. SI10-12, located to the south outside the former landslide repair limits, showed a steady annual rate of movement of about 8 mm/yr up until it sheared off in Fall 2019. The movement measured at SI10-15, located north of the slide repair area, is at a rate of about 5 mm/yr (highest movement rate of 11 mm/yr was recorded in the fall of 2020).

It is postulated that the dipping in the highway pavement surface is the result of the clay fill settling and spreading over time. The shallow sloughing of the clay cap is considered due to the loss of cohesion as a result of weathering (wetting and desiccation cycles). The repaired sideslope is over-steepened and lateral spreading of the clay fill is expected to continue. The shear depth of the SI's correlates with this assessment.

The development of additional cracks in the highway shoulder south and north of the Fence Slide (in the vicinity of SI10-12 and SI10-15) within the last few years are getting worse and likely indicate potential slope failures at these locations in the southbound lanes in the future. No toe bulge or other visible slide features have been apparent on the slope below the road in recent inspections.

Rill erosion and scouring below the highway SBL resulting from the concentrated water runoff in the lower dipped sections also needs to be addressed as it can lead to progressively larger erosion gullies, skin failures and landslide features, which could eventually retrogress into the roadway.

To reduce maintenance effort along this section of the road it is understood that AT is converting the ACP to a gravel surface between KM 58.480 to KM 59.540 so that any ongoing settlement or slide movements that distort the road surface can be graded out until a more permanent solution is implemented. As part of this work ditch erosion design repairs have also been provided by Thurber between approximately KM 58.5 KM to KM 59.525. Ditch erosion repair designs consist of adding Class 1M riprap to ditch areas already filled with rock, regrading and adding Class 1M over geotextile, TRM with synthetic ditch barriers, and adding riprap bowls. This work is anticipated to be complete by end of October 2022.

Recommendations:

Cost

<p>A short-term solution for the shallow skin failures in the clay cap over the sideslope is to seed and cover the sideslope with Macmat and anchor it into the slope with Duckbill anchors.</p>	<p>\$75,000</p>
<p>Mid-term to long term solutions would involve excavating and removing the upper clay backfill from the 2005 repair and rebuilding the highway embankment with granular fill reinforced with uniaxial geogrid, the reinstatement of the clay cap on the embankment sideslope and the placement of an overlying slope protection (Armormax anchored with Duckbill anchors).</p>	<p>\$ 300,000</p>
<p>Long-term solutions to deal with the propagation of cracks to the north and south of the Fence Slide could consist of a realignment of the highway into the backslope (now that the natural gas pipeline is decommissioned), digging out weaker clay layers and rebuilding the slope with geogrid reinforced gravel (like the Fence Slide repair from 2015) or pile walls. The cost could range from \$2,000,000 to \$10,000,000. The realignment is likely the cheapest option but will only buy some time until further retrogression occurs whereas the pile wall or dig and replace options should be a more permanent solution.</p>	<p>\$2M - \$10M</p>

Closure:

It is a condition of this letter report that Thurber's performance of its professional services will be subject to the attached Statement of Limitations and Conditions.

Don Proudfoot, P.Eng.
Principal | Senior Geotechnical Engineer

Tyler Clay, P.Eng.
Geological Engineer



STATEMENT OF LIMITATIONS AND CONDITIONS

1. STANDARD OF CARE

This Report has been prepared in accordance with generally accepted engineering or environmental consulting practices in the applicable jurisdiction. No other warranty, expressed or implied, is intended or made.

2. COMPLETE REPORT

All documents, records, data and files, whether electronic or otherwise, generated as part of this assignment are a part of the Report, which is of a summary nature and is not intended to stand alone without reference to the instructions given to Thurber by the Client, communications between Thurber and the Client, and any other reports, proposals or documents prepared by Thurber for the Client relative to the specific site described herein, all of which together constitute the Report.

IN ORDER TO PROPERLY UNDERSTAND THE SUGGESTIONS, RECOMMENDATIONS AND OPINIONS EXPRESSED HEREIN, REFERENCE MUST BE MADE TO THE WHOLE OF THE REPORT. THURBER IS NOT RESPONSIBLE FOR USE BY ANY PARTY OF PORTIONS OF THE REPORT WITHOUT REFERENCE TO THE WHOLE REPORT.

3. BASIS OF REPORT

The Report has been prepared for the specific site, development, design objectives and purposes that were described to Thurber by the Client. The applicability and reliability of any of the findings, recommendations, suggestions, or opinions expressed in the Report, subject to the limitations provided herein, are only valid to the extent that the Report expressly addresses proposed development, design objectives and purposes, and then only to the extent that there has been no material alteration to or variation from any of the said descriptions provided to Thurber, unless Thurber is specifically requested by the Client to review and revise the Report in light of such alteration or variation.

4. USE OF THE REPORT

The information and opinions expressed in the Report, or any document forming part of the Report, are for the sole benefit of the Client. NO OTHER PARTY MAY USE OR RELY UPON THE REPORT OR ANY PORTION THEREOF WITHOUT THURBER'S WRITTEN CONSENT AND SUCH USE SHALL BE ON SUCH TERMS AND CONDITIONS AS THURBER MAY EXPRESSLY APPROVE. Ownership in and copyright for the contents of the Report belong to Thurber. Any use which a third party makes of the Report, is the sole responsibility of such third party. Thurber accepts no responsibility whatsoever for damages suffered by any third party resulting from use of the Report without Thurber's express written permission.

5. INTERPRETATION OF THE REPORT

- a) Nature and Exactness of Soil and Contaminant Description: Classification and identification of soils, rocks, geological units, contaminant materials and quantities have been based on investigations performed in accordance with the standards set out in Paragraph 1. Classification and identification of these factors are judgmental in nature. Comprehensive sampling and testing programs implemented with the appropriate equipment by experienced personnel may fail to locate some conditions. All investigations utilizing the standards of Paragraph 1 will involve an inherent risk that some conditions will not be detected and all documents or records summarizing such investigations will be based on assumptions of what exists between the actual points sampled. Actual conditions may vary significantly between the points investigated and the Client and all other persons making use of such documents or records with our express written consent should be aware of this risk and the Report is delivered subject to the express condition that such risk is accepted by the Client and such other persons. Some conditions are subject to change over time and those making use of the Report should be aware of this possibility and understand that the Report only presents the conditions at the sampled points at the time of sampling. If special concerns exist, or the Client has special considerations or requirements, the Client should disclose them so that additional or special investigations may be undertaken which would not otherwise be within the scope of investigations made for the purposes of the Report.
- b) Reliance on Provided Information: The evaluation and conclusions contained in the Report have been prepared on the basis of conditions in evidence at the time of site inspections and on the basis of information provided to Thurber. Thurber has relied in good faith upon representations, information and instructions provided by the Client and others concerning the site. Accordingly, Thurber does not accept responsibility for any deficiency, misstatement or inaccuracy contained in the Report as a result of misstatements, omissions, misrepresentations, or fraudulent acts of the Client or other persons providing information relied on by Thurber. Thurber is entitled to rely on such representations, information and instructions and is not required to carry out investigations to determine the truth or accuracy of such representations, information and instructions.
- c) Design Services: The Report may form part of design and construction documents for information purposes even though it may have been issued prior to final design being completed. Thurber should be retained to review final design, project plans and related documents prior to construction to confirm that they are consistent with the intent of the Report. Any differences that may exist between the Report's recommendations and the final design detailed in the contract documents should be reported to Thurber immediately so that Thurber can address potential conflicts.
- d) Construction Services: During construction Thurber should be retained to provide field reviews. Field reviews consist of performing sufficient and timely observations of encountered conditions in order to confirm and document that the site conditions do not materially differ from those interpreted conditions considered in the preparation of the report. Adequate field reviews are necessary for Thurber to provide letters of assurance, in accordance with the requirements of many regulatory authorities.


6. RELEASE OF POLLUTANTS OR HAZARDOUS SUBSTANCES

Geotechnical engineering and environmental consulting projects often have the potential to encounter pollutants or hazardous substances and the potential to cause the escape, release or dispersal of those substances. Thurber shall have no liability to the Client under any circumstances, for the escape, release or dispersal of pollutants or hazardous substances, unless such pollutants or hazardous substances have been specifically and accurately identified to Thurber by the Client prior to the commencement of Thurber's professional services.


7. INDEPENDENT JUDGEMENTS OF CLIENT

The information, interpretations and conclusions in the Report are based on Thurber's interpretation of conditions revealed through limited investigation conducted within a defined scope of services. Thurber does not accept responsibility for independent conclusions, interpretations, interpolations and/or decisions of the Client, or others who may come into possession of the Report, or any part thereof, which may be based on information contained in the Report. This restriction of liability includes but is not limited to decisions made to develop, purchase or sell land.


H:\32000\32121 AT GRMP Peace River District 2021-2025\CAD\2022 GEOHAZARD\TTC\32121-PH034-1.dwg - PH84 FENCE SLIDE - Oct. 11, 2022



- LEGEND**
- TEST HOLE LOCATION
 - SLOPE INDICATOR
 - DIRECTION AND PHOTO NUMBER



- NOTES:**
1. LOCATION DATA RECORDED USING HANDHELD GPS RECEIVER. ALL LOCATIONS ARE APPROXIMATE AND ARE FOR ILLUSTRATIVE PURPOSES ONLY.
 2. MAY 24, 2022 OBSERVATIONS SHOWN IN RED.



PEACE REGION (PEACE RIVER DISTRICT)

PH034-1 JUDAH HILL FENCE SLIDE
2022 SITE INSPECTION PLAN

DWG No. 32121-PH034-1

DRAWN BY	ML
DESIGNED BY	TTC
APPROVED BY	DWP
SCALE	1:750
DATE	OCTOBER 2022
FILE No.	32121





Photo 1.
Looking northwest from km 59.07 at the cracking and pavement distress along the downhill side of the road near S110-12. No significant visual change in the pavement from the 2021 condition.



Photo 2.
Looking north from the south end of the Fence Slide repair at km 59.14. Slide damage extends into the NBL. The sharp pavement edge due to the dip has been milled.



Photo 3.
Looking south from the north end of the Fence Slide repair at km 59.18. Depression extends into the NBL and appears more pronounced. Differential pavement edge has been milled.



Photo 4.
Looking south from the west sideslope of Hwy 744:04 from km 59.18. The bow and vertical deflection in the guardrail are visible.



Photo 5.
Looking northwest from km 59.21 at the west sideslope below S110-15. Minor rill erosion otherwise no major change from 2021.



Photo 6.
Looking southeast from km 59.25 along the SBL. Cracking and dip along the shoulder appeared slightly worse relative to the 2021 condition. Sand buildup along the shoulder.



Photo 7.
View of old slump
in the backslope
near km 59.3.
Fresh soil visible in
the upper scarp
since the 2021
condition.