Geohazards Associated with Dispersive-Soil Voids

Chris Grapel, M.Eng., P.Eng.


GRMP 2018







Dispersive-Soil GRMP Sites







S040 Dorothy Hwy 848:02







S040 Dorothy Hwy 848:02







Dispersive Soils

- Dispersive clays are present across the Red Deer River valley in the badlands area and were first identified in 1925 (NRCA 1945).
- Dispersive clays erode in the presence of still or flowing water through a process called deflocculation.
- Deflocculation occurs when the repulsive forces between individual clay particles exceed the interparticular attractive forces and any other forces that bind the particles together (Ghuman et al 1976, and Sherard et al 1972).
- Dissolved-sodium (Na+) cations act to increase the double-diffuse layer of adsorbed molecules, decreasing the attraction between the clay particles, and facilitating separation of the particles from the soil mass into solution (in either flowing or still water)






Erosion of Dispersive Soils

- The individual clay particles deflocculate into the water column and are suspended in solution.
- Chemical analyses such as exchangeable sodium percentage (ESP) and sodium adsorption ratio (SAR) relate the relative abundance of exchangeable cations to clay-structure stability and dispersion potential.
- Dispersive clays are generally classified with a ESP greater than 6, and a SAR greater than 3, though dispersion can occur in soils with ESP below 6 and SAR below 3 (Hardie 2009).





C035 Simplified Crumb Testing (Immersion)







What makes the badlands so bad?

(According to a Vegetation Ecologist)

- Exposed marine bedrock;
- Salt-affected topsoil (solonetzic soils);
- Minimal vegetation cover, only salt-tolerant species can thrive;
 and
- Limited moisture-retention capacity of surface soils exacerbates arid conditions.





Overview of Dispersive Soil GRMP Sites

Geohazards in dispersive soils consist of subsurface voids forming below highway infrastructure, along drainage routes (e.g., ditches, culverts, channels), and erosion of ditches and backslopes

Erosion Geohazards

- C011
- C035

Void geohazards

- C011
- C058
- C065





C011 Ditch Erosion and Sinkholes

Hwy 837:02, km 5.637


AADT 290

PF 12

CF 4























C035 Ditch Erosion

Hwy 590:04, km 20.104

AADT 670

PF 11

CF 4



































C065-I and -II East of Trochu

Hwy 585:02, km 16.136

AADT 400

PF 13

CF8























C065 Geophysics


TetraTech hired to complete a geophysics survey:

- goal was to assess if voids were present below the two dip areas
- Drilled a borehole at one dip (no void) but soils below highway were quite soft and wet compared to the soils encountered in a borehole drilled on adjacent higher ground
- started at S040 to assess if voids could be detected (success)
- Conducted electrical-resistive tomography (ERT), ohm-mapper, multi-channel analysis of surface waves (MASW), and electromagnetic (EM) conductivity surveys at C065
- The ERT and MASW gave the best results
- Conclusion no void detected below highway, but ongoing dissolution at a preferential seepage path could be causing the settlement





C065 Geophysics







C058 Sinkholes

Hwy 570:02, km 12.000

AADT 510

PF 5

CF 4











Back to S040 Dorothy

Hwy 848:02, km 11.507

AADT 120

PF 9

CF 4





S040 Dorothy Hwy 848:02







S040 Dorothy Hwy 848:02







S040 – Sinkhole near culvert inlet








S040 – Geophysics (EM Conductivity)








S040 – Geophysics (EM Conductivity)







S040 – Geophysics (EM Conductivity)







Thank you for your attention

Questions?



