



Alberta Transportation
Bi-Annual GRMP
Meeting

North Central
Region – NC76,
NC82, and
NC57 Overview



Agenda

1. Overview
2. NC76 – Blue Ridge Slide
3. NC82 – Morinville Slide
4. NC57 – HWY 624
Embankment Failure
5. Questions




Image from http://www.transportation.alberta.ca/Content/docType329/Production/2015_TRANSPORTATION_REGIONS_DISTRICTS.pdf


Edson and Stony Plain Districts

Overview

**GEOHAZARD
MONITORING SITES
NORTH CENTRAL REGION
EDSON AREA**



Prepared by GIS and Cartography Section, Corporate Services and Information Division
From Transportation Infrastructure Management System (TIMS) Digital Data, © 2016
Base map information provided by the Government of Alberta




NC76 – Blue Ridge Slide


Background




- Fill embankment through valley of Bull Creek (12 m to 15 m high)
- Side slopes at 3.5H:1V
- Slope failures during culvert replacement in 2009
- Call-out in October 2011 and subsequently included in inspection list
- Instruments installed in 2012

PIEZOMETER DATA NC76: HWY 658:02 km 7.5 BLUE RIDGE SLIDE






HWY 658:02 km 7.5 Blue Ridge Slide, Inclinometer SI12-3



HWY 658:02 km 7.5 Blue Ridge Slide, Inclinator SI12-3

Alberta Transportation





2011 – Thurber Inspection Report



2014 – Golder Inspection Report



2016 – Stantec Inspection



2017 – Stantec Inspection


Challenges


- Limited space due to creek
 - Pile wall – Cantilevered pile alone inadequate for support. Needed anchors.
 - Large number of anchors required became costly – went with berm solution (additional ROW needed for construction access)
- Relatively weak clay till
 - Concerns with constructability of a shear key due to poor soil and groundwater conditions – built a larger berm instead
- High groundwater table and springs
 - Drainage blanket with interceptor drains

Figure E4

Overall slope of ~4.5H:1V

| Color | Name | Unit Weight (kN/m ³) | Cohesion (kPa) | Phi (°) | Piezometric Line |
|-------------|---------------|----------------------------------|----------------|---------|------------------|
| Yellow | Fill | 19 | 5 | 28 | |
| Light Green | Clayey Silt | 19 | 0 | 24 | 1 |
| Green | Failure Plane | 18 | 0 | 12 | 1 |
| Light Blue | Clay Till | 20 | 0 | 30 | 1 |
| Cyan | Lower Clay | | | | 1 |
| Blue | Clay | 18 | 0 | 20 | 1 |
| Purple | Slope Fill | 19 | 0 | 24 | 1 |
| Pink | Berm Fill | 19 | 0 | 24 | 1 |
| Red | Gravel Fill | 21 | 0 | 35 | 1 |





APPROX LOCATION OF EXISTING CULVERT

UNKNOWN BURIED UTILITY

EXISTING 1-3 990 mm x 90.9 m LONG CULVERT CENTERLINE

EDGE OF ROAD

HWY 658

EDGE OF ROAD

PROPOSED BERM
 EXISTING DITCH/SWALE W/ EROSION CONTROL MEASURES

APPROXIMATE LOCATION OF EXISTING DITCH/SWALE W/ EROSION CONTROL MEASURES

EXISTING CLASS 1 ROCK RIPRAP (REMOVE & SALVAGE)

PROPOSED DRAINAGE DITCH

83.183
 233°29'8"

EXISTING 1-3 990 mm DIA x 90.90 m SPCSP. REMOVE AND DISPOSE CULVERT BEVELLED END SECTION AT DOWNSTREAM END. INSTALL 1-2 620 mm SPAN x 3 200 mm RISE x 40.41 m LONG SPCSP VERTICAL ELLIPSE AS LINER AND EXTENSION OF EXISTING PIPE AT 35° LHF SKEW TO ROAD

ROAD PLAN 162 2867

EXISTING LIMITS OF ROAD ROW

TOP OF BANK
 TOP OF BULL CREEK
 TOP OF BANK

PROPOSED ADDITIONAL LIMITS OF ROW REQUIRED


59.052
 178°41'19"

SE 26-59-10-W5M

25.456
 133°41'19"

EDGE OF WATER

FLOW



NC82 Morinville Slide

Background



- Two slides
 - North 55 m x 20 m
 - South 30 m x 15 m
- 4 m to 5 m high embankment, 3H:1V
- Standing water in east ditch – No grade
- Test pits showed soft soils, possible high water table, and uncontrolled fill
- No instrumentation




Photo 1 – Looking north at north slide




Photo 2 – Looking west from north slide



Photo 3 – Looking north at drainage ditch

Figure 7E - Repair Option (Long Term)
 Remove and Replace with Granular Backfill

| Color | Name | Model | Unit Weight (kN/m ³) | Cohesion' (kPa) | Phi' (°) |
|-------------|------------------------|--------------|----------------------------------|-----------------|----------|
| Light Green | Clay (Cl) | Mohr-Coulomb | 19 | 2 | 24 |
| Yellow | Clay Fill_2 | Mohr-Coulomb | 18.5 | 3 | 20 |
| Orange | Clay Fill-Residual (3) | Mohr-Coulomb | 18.5 | 1 | 13 |
| Blue | Pit Run Fill | Mohr-Coulomb | 20 | 0 | 35 |










Challenges

- Excavations in soft soil
 - Limit construction widths to 5 m sections if shear key to be constructed
 - Must backfill shear key the same day it's excavated
- Construction in winter
 - Control the material going into the site for compaction
 - Benefit of winter shutdown – touch up in spring.
- Working with a brand new contractor
 - Work closely during development of work plan
 - Keep them informed on “why”




**GEOHAZARD
 MONITORING SITES
 NORTH CENTRAL REGION
 STONY PLAIN AREA**

Prepared by GIS and Cartography Section, Corporate Services and Information Division
 From Transportation Infrastructure Management System (TIMS) Digital Data © 2015
 Base map information provided by the Government of Alberta

NC57 – HWY 624 Embankment Failure

- NC57 –
Highway
624
Embankment
Failure

Background



- 2 m embankment with 6H:1V to 7H:1V side slopes
- Settlement and lateral spreading of highway
- First embankment failure in 2006
- Repaired in 2007 with granular sub-drains installed.
- Highway 624 performed well until 2014




Photo 1 – Looking west gentle slope



Photo 2 – Looking east, wet ground




Photo 3 – Looking southeast, pavement distress

Challenges

- Very soft to soft clay
 - Need to improve strength. Remove and replace. Cematrix?
- High Groundwater Table
 - Boreholes drilled showed piezometric levels 1 m above highway surface
 - Need free draining material. Not Cematrix.
 - Gravel available nearby
 - Tire derived aggregate (TDA) also available from Alberta recycling

Figure E4 - Section A - Tire Derived Aggregate
Option 2

| Color | Name | Model | Unit Weight (kN/m ³) | Cohesion' (kPa) | Phi' (°) | Piezometric Line |
|-------------|------------------------|--------------|----------------------------------|-----------------|----------|------------------|
| Light Green | Clay (CH) | Mohr-Coulomb | 16.5 | 0 | 17 | 1 |
| Blue | Clay Fill (Imported) | Mohr-Coulomb | 18 | 0 | 25 | 1 |
| Green | Clay Till (CI) | Mohr-Coulomb | 19 | 2 | 28 | 2 |
| Red | Tire Derived Aggregate | Mohr-Coulomb | 8 | 0 | 21 | 1 |



A wide-angle photograph of a large concrete bridge spanning a river. The bridge has multiple concrete piers supporting its structure. The water is calm and reflects the sky. In the foreground, there are some young trees and bushes. The background shows a green landscape with rolling hills and a blue sky with scattered white clouds. The word "Questions?" is written in a large, white, sans-serif font across the center of the image.

Questions?