

Bridge Inspection										
Bridge File Number	01097 -1 Bridge					Form Type	TH TT			
Year Built/Year Supstr	1909/1907					Lot No.	2			
Bridge or Town Name	FORT MACLEOD					Inspector Name	Paul Carter			
Located Over	OLDMAN RIVER, 2.12, WATERCRS-ST					Inspector Class	BR CLS A			
Located On	811:02 C1 0.793					Assistant Name				
Water Body Cl./Year						Assistant Class				
Navigabil. Cl./Year						Inspection Date	20-Jan-2010			
Legal Land Location	SE SEC 13 TWP 9 RGE 26 W4M					Data Entry By	Jill Potts			
Longitude, Latitude	-113:23:53, 49:43:55					Data Entry Date	11-May-2011			
Road Authority	Alberta Transportation (AIT)					Reviewer Name	Garry Roberts			
Contract Main. Area	CMA26					Review Date	20-Mar-2010			
Clear Roadway/Skew	5 /					Dept. Reviewer Name	Tim Davies			
AADT/Year	1,240 / 2010 (A)					Dept. Review Date	20-May-2011			
Road Classification	RCU-208-110					Follow-Up By				
Detour Length (km)	12									
Allowable Load (t):	Single	H 25 STRINGER			Semi	HS 40 U1L1		Train	CS3 62	----> On Critical Spans ---->Critical Member
Design Loading:	HS20									----> Primary Span

Posting Information												
Required Vert. Clearance Posting (m)												
Posted Vertical Clearance (Y/N)												
Posted:	Lane	NB	On Bridge (m)	4.4	In Advance (Y/N)	Yes	Lane	SB	On Bridge (m)	4.4	In Advance (Y/N)	Yes
Remarks Measured 4.58 both ends.												
Required Load Posting (t)												
Posted Loading (t)												
Posted:	Lane	NB	At Junction (Y/N)	Yes	In Advance (Y/N)	Yes	At Bridge (Y/N)	Yes				
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	Yes	At Bridge (Y/N)	Yes				
Remarks												
Hazard Marker At Bridge (Y/N) Yes												
Remarks Installed 400mm too low.												
Other Sign Types Narrow bridge, stop if oncoming traffic, max 30 km/hr, one lane.												

Utilities (Located at)			
Utility Attachments	TELEPHONE UTILITIES-PHONE LINE		
Telephone	West @ bottom chord.		Gas East 30m from c/l.
Power	10m East, 50m East & West of c/l.		Municipal Water station at NE
Others	Multiple lines both sides.		Problem (Y/N) No
Remarks			

Approach Road				
		Last	Now	Explanation of Condition
Horizontal Alignment		5	4	Sharp turn both ends, adequate for posted speeds.
Vertical Alignment		6	6	
Roadway Width (m)	7.600			{Asphalt settled, minor bump. July 22, 2009 UT report}
Approach Bump		5	4	
Guardrail (Y/N)	Yes			Incorrect splice lap at SW wing end, but flared from lane Not thriebeam
Guardrail		5	7	
Length (m)	22.000			
Current Standard (Y/N)	No			
Termination Type	Turn Down			
Drainage		6	7	
Approach Road General Rating		5	4	

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : TH, 4 Spans, Lengths(m): 53.3-53.3-53.3-8.5, A-Ident Number: A0108-03;A0108-01;A0108-02)					
Special Features					
Special Feature			X	{Dwydag strengthening. July 22, 2009 UT report}	
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last	0	0	0	0	
Now					
Wearing Surface/Deck Top			5	5	Lagged in @ ends.
(Material Type : UNTREATED TIMBER)					
(Plank Thickness(mm) : 75)					
(Plank Width(mm) : 300)					
Deck Rideability			6	7	
Deck Joints			X	X	
Temperature (deg. C)					
(Expansion Type :)					
(Fixed Type :)					
Gap Size (mm)		Gap Location			
Curbs/Wheel Guards			5	4	{Minor plow damage, still functional. July 22, 2009 UT report}
(Curb Type : Standard)					
(Type : TREATED TIMBER)					
(Thickness(mm) : 100)					
(Width(mm) : 300)					
Bridge Rail			4	4	{Missing 67 splice bolts, 3 rail blocks & 2 post bolts missing nuts. 3 layer & 2 row steel wire. July 22, 2009 UT report} U bolts holding cable broken @ one location. No steel end posts.
(Type : GALVANIZED STEEL FLEX BEAM)					
Bridge Rail Posts/Blocking			4	4	
(Type : POST STEEL;POST STEEL)					
Bridge Rail/Posts Coating			5	7	
(Type : PAINT)					
Sidewalk			X	X	

Superstructure						
Bridge Component		Last		Now		Explanation of Condition
(Primary Span : TH, 4 Spans, Lengths(m): 53.3-53.3-53.3-8.5, A-Ident Number: A0108-03;A0108-01;A0108-02)						
Wide Load Damage (Y/N)	Yes					{U9L9W span 1 has minor local bend @ wheelguard height, 25mm. Minor notches @ North portal @ span 3 & South portal @ span 2. Sway bracing @ U2, U3, U5, U6, U7, U8. S1-U2U2, U3U3, U5U5 bowed. S3-U9LW8 dented. S1-U9L9W, S3-U8L8W dented. Span 1 bent 25mm to 175mm. Span 3 U8L8 & U9L8W 40mm local bends at East truss. Strengthened with 2-75 x 75 angle floor beams. S3-U1L2W missing 1 tie plate bolt. July 22, 2009 UT report} Dwydag rods in bottom chords. {5 - 205 x 165 @ 800. 6 - 250 x 120 @ 770 + 2 channels. Original spacing left. July 22, 2009 UT report} 13 stringer/bay x 10 bays x 3 spans
High Load Damage (Y/N)	No					
Top Chord		7	7			
Batter Posts		7	7			
Sway Bracings		5	5			
Diagonals		6	5			
Verticals		4	5			
Portals		6	5			
Connections		5	5			
Floor Beams		7	7			
Bottom Chord		7	7			
(No. of Stringers : 130;130;130)						
Stringer Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
Last						
Now						
Stringers			6	7		
(Type : STEEL)						
(Width(mm) : 200)						
(Depth(mm) : 510)						
(Spacing(mm) : 774)						
Paint Condition		5	6			
(Colour Description : GREEN)					green	
(Colour Code : 503-113)						
Touchup Required (Y/N)	No					
Bearings		6	7			
Temperature (deg. C)	31				{Exp. @ S1@P1, S2@P2, S3@P3. Fully, 3/4 U/S, 3/4 U/S. 1/2 D/S. 1/2 D/S. July 22, 2009 UT report}	
(Expansion Type : ROLLER NEST BEARING)						
(Fixed Type : STEEL SLIDING PLATES WITH BRONZE PLATE IN BETWEEN;PINNED BEARING)						
Functioning (Y/N)	Yes					
Sub Deck/Deck Underside		5	5			
(Material Type : TREATED TIMBER)					{Laminated 50 x 100 subdeck @ Span 1. Some deteriorated @ span #1 laminated subdeck, splits plus 1 with end rot @ SW, some too short. July 22, 2009 UT report}	
(Plank Thickness(mm) : 100)						
(Plank Width(mm) : 300)						
Defects (Percent Area)	2					
Span Alignment Problems						
Vertical (Y/N)	No					
Horizontal (Y/N)	No					
Superstructure General Rating		4	5			
Superstructure						
Bridge Component		Last		Now		Explanation of Condition
(Secondary Span : TT)						
Special Features						
Special Feature				X		
(Type :)						
Special Feature				X		
(Type :)						

Superstructure						
Bridge Component				Last	Now	Explanation of Condition
(Secondary Span : TT)						
Wearing Surface/Deck Top Detail Ratings						
	N (%)	1 (%)	2 (%)	3 (%)		
Last	0	0	0	0		
Now						
Wearing Surface/Deck Top				5	4	{Lagged in @ ends. Heavily checked & abrasive wear. July 22, 2009 UT report}
(Material Type : UNTREATED TIMBER)						
(Plank Thickness(mm) : 75)						
(Plank Width(mm) : 300)						
Deck Rideability				6	7	
Wheel Guards				5	5	Scraped but functional.
(Curb Type : Standard)						
(Type : TREATED TIMBER)						
(Thickness(mm) : 100)						
(Width(mm) : 300)						
Bridge Rail				4	5	Single layer. 8 missing bolts @ splices.
(Type : GALVANIZED STEEL FLEX BEAM)						
Bridge Rail Posts				6	6	
(Type : TREATED TIMBER;TREATED TIMBER)						
Bridge Rail/Posts Coating				6	6	
(Type : GALVANIZED)						
(No. of Stringers : 12)						
Stringer Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
Last	0	0	0	0		
Now						
Stringers				5	6	{Angle and cable bracing @ mid span. 2nd from East twisted. Varies, new stringers were added, 4 stringers doubled up. 400 to 800 mm spacing. July 22, 2009 UT report}
(Type : TREATED TIMBER)						
(Width(mm) : 200)						
(Depth(mm) : 510)						
(Spacing(mm) : 400)						
Sub Deck/Deck Underside				5	5	
(Material Type : TREATED TIMBER)						
(Plank Thickness(mm) : 100)						
(Plank Width(mm) : 300)						
Defects (Percent Area)		2				
Span Alignment Problems						
Vertical (Y/N)		No				
Horizontal (Y/N)		No				
Superstructure General Rating				5	5	
Substructure						
Bridge Component				Last	Now	Explanation of Condition
Abutments						
(Extended Backwall Piles (Y/N) : Y)						
(Extended Backwall Piles Spacing(mm) : 2000)						

Substructure							
Bridge Component				Last	Now	Explanation of Condition	
(Total Number of Caps/Corbels : 1:1)						Concrete abut. at South	
Bearing Seats/Caps/Corbels Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)			
Last	0	0	0	0			
Now							
Bearing Seats/Caps/Corbels				6	6		
(Type : TREATED TIMBER)							
(Depth(mm) : 300)							
(Width(mm) : 300)							
Backwalls/Breastwalls					5		5
Greatest Height (m)		1.40					
Wingwalls					5	5	
(Total Number of Bearing Piles : 5:5)						T.T piles N. abut	
Piles Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)			
Last	0	0	0	0			
Now							
Piles				6	6		
Paint/Coating				X	X		
Abutment Stability				7	7		
Scour/Erosion				7	7		
Piers/Bents							
(Type : PIER-SOLID)							
(Total Number of Caps/Corbels : 1:1:1)						{Top of pier 1 and 2 have medium to heavy scaling. July 22, 2009 UT report}	
Bearing Seats/Caps/Corbels Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)			
Last	0	0	0	0			
Now							
Bearing Seats/Caps/Corbels				4	4		
(Type : CONCRETE)							
(Total Number of Bearing Piles : 0:0:0)							{Cracked but functional. Wide cracks in random checked pattern and vertical wide cracks below anchor bolts, 4mm to 8mm wide cracks. July 22, 2009 UT report}
Piles Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)			
Last	0	0	0	0			
Now							
Pier Shaft/Piles				5	5		
Greatest Height (m)		5.20					
Bracing/Struts/Sheathing				X	X		
Nose Plate				6	7		
Paint/Coating				4	4	{Surface corrosion @ nose plates. No coating at piers. July 22, 2009 UT report} blue	
(Colour Description :)							
(Colour Code :)							
Pier Stability				7	7		
Scour				6	N		
Debris (Y/N)		Yes				Minor drift at p 2	

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Substructure General Rating		4	5	
Structure Usage				
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : W)				{Flows against north bank @ high water. July 22, 2009 UT report}
(D/S Direction : E)				
Alignment		4	5	
Bank Stability		5	5	{Spurs and rock @ NW & SE. July 22, 2009 UT report}
HWM (m below Top of Curb)	4.0			((2.1m below top stringers South side - 97/01/08)) (Water-deck 6.1m (Water to deck 6.5m. 97/01/08) Minor drift
Drift (Y/N)	Yes			
Slope Protection		5	5	
(Type : RIP RAP; RIP RAP)				
Guidebank/Spurs		7	7	4 rock spurs u/s
Adequacy of Opening		6	7	
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		4	5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL	2012	{67 flexbeam splice bolts, 3 blocks. July 22, 2009 UT report}					
RETROFIT BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
OVERLAY DECK							
REPLACE STRIP DECK							
REPLACE SUB DECK	2012	{Replace rotted planks. July 22, 2009 UT report}					
RESET/ PAINT BEARINGS							
REPAINT SUPERSTRUCTURE							
STRAIGHTEN/REPLACE MEMBERS	2011	{Straighten U9L9W, U7L7, U3U3 on span 3 and U8L8W plus U9L8W on span 1. July 22, 2009 UT report}					
WASHING							
SHOTCRETE REPAIRS							
CORE TIMBER CAPS/CORBELS							
REPAIR/REPLACE TIMBER CAPS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
OTHER ACTION	2012	{Raise hazard markers. July 22, 2009 UT report}					
OTHER ACTION	2012	{Epoxy seal pier top. July 22, 2009 UT report}					
OTHER ACTION	2012	{Patch approach ACP. July 22, 2009 UT report}					
OTHER ACTION	2012	{Add bolt at splice plates U1L2W span 1 & 2. July 22, 2009 UT report}					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	44.4/55.6	Sufficiency Rating (Last/Now) (%)	40.3/37.3	Est. Repl. Yr	2034	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							

Proposed Action			
Previous Inspector's Name	Garry Roberts	Previous Assistant's Name	
Next Inspection Date	20-Apr-2013	Previous Inspection Date	19-Jan-2010
Inspection Cycle (Default) (months)	39		
Comment			