

Bridge Inspection									
Bridge File Number	01161 -3 Bridge				Form Type	PSR			
Year Built/Year Supstr	1998/1998				Lot No.	4			
Bridge or Town Name	STAVELY				Inspector Name	Garry Roberts			
Located Over	PINE CREEK, 2.12.25.8, WATERCRS-ST				Inspector Class	BR CLS A			
Located On	527:02 C1 7.858				Assistant Name				
Water Body Cl./Year					Assistant Class				
Navigabil. Cl./Year					Inspection Date	22-May-2010			
Legal Land Location	SE SEC 15 TWP 14 RGE 28 W4M				Data Entry By	Alyssa Boynton			
Longitude, Latitude	-113:44:06, 50:09:53				Data Entry Date	17-Aug-2010			
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Ash Morjaria			
Contract Main. Area	CMA26				Review Date	28-May-2010			
Clear Roadway/Skew	9.1 /				Dept. Reviewer Name	Lorenz Bohnert			
AADT/Year	490 / 2009 (A)				Dept. Review Date	18-Aug-2010			
Road Classification	RCU-209-110				Follow-Up By				
Detour Length (km)	3								
Allowable Load (t):	Single	CS1 28	Semi	CS2 49	Train	CS3 62	----> On Critical Spans ---->Critical Member		
Design Loading:	CS750						----> Primary Span		
Posting Information									
Required Load Posting (t)	Single		Semi		Truck Train				
Posted Loading (t)	Single		Semi		Truck Train				
Posted:	Lane	EB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Posted:	Lane	WB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Remarks	Not Required								
Hazard Marker At Bridge (Y/N)	No								
Remarks									
Other Sign Types	Pine Coulee Reservoir								
Utilities (Located at)									
Utility Attachments	TELEPHONE UTILITIES-PHONE LINE; POWER UTILITIES-POWER LINE								
Telephone	S RW				Gas	1W @ N RW			
Power	North Row				Municipal				
Others					Problem (Y/N)	No			
Remarks									
Approach Road									
			Last	Now	Explanation of Condition				
Horizontal Alignment			8	8	In vertical sag curve				
Vertical Alignment			6	7					
Roadway Width (m)	10.000								
Approach Bump			7	7					
Guardrail (Y/N)	Yes				150x150 HSS on 60x75 I-beam posts				
Guardrail			9	8					
Length (m)	99.000								
Current Standard (Y/N)	Yes								
Termination Type	TURNDOWN								
Drainage			8	7					
<b>Approach Road General Rating</b>			<b>6</b>	<b>7</b>					

Superstructure						
Bridge Component		Last	Now	Explanation of Condition		
(Primary Span : DBT, 2 Spans, Lengths(m): 28-38, A-Ident Number: )						
<b>Special Features</b>						
Special Feature			X			
(Type : )						
Special Feature			X			
(Type : )						
<b>Wearing Surface/Deck Top Detail Ratings</b>						
	N (%)	1 (%)	2 (%)	3 (%)		
<b>Last</b>	0	0	0	0		
<b>Now</b>	0.0	0.0	0.0	0.0		
Wearing Surface			6	6	Moderate transverse cracks	
(Material Type : <b>ACP</b> )						
(Thickness(mm) : <b>50</b> )						
Lateral Connection Problem (Y/N)		No				
Deck Top			N	N		
Deck Rideability			8	8		
Deck Joints			8	8	1 loose boltat NW curb cover plate	
Temperature (deg. C)		12				
(Expansion Type : )						
(Fixed Type : )						
Gap Size (mm)		Gap Location				
90		W abut				
80		E abut				
Deck Drainage			4	5	All but one of six drains are missing grates @ deck	
Drains Clogged (Y/N)		No				
Curbs/Median			8	8		
(Curb Type : <b>Standard</b> )						
Scaling (Percent Area)		0				
Bridge Rail			8	8	Most anchor bolts-steel without galvanizing-all surface corroded	
(Type : <b>BRIDGE TUBE</b> )						
Bridge Rail Posts		8	8			
(Type : <b>GALVANIZED POST STEEL;GALVANIZED POST STEEL</b> )						
Bridge Rail/Posts Coating		8	6			
(Type : )						
Sidewalk			X	X		
<b>Girder Detail Ratings</b>						
	N (count)	1 (count)	2 (count)	3 (count)		
<b>Last</b>	0	0	0	0		
<b>Now</b>	0	0	0	0		
Girders			8	8	8 lines continuous girders	
Cracking (Y/N)		No				
Spalling (Percent Area)		0				
(Number Of Girders : <b>100007</b> )						

Superstructure				
Bridge Component		Last	Now	Explanation of Condition
(Primary Span : DBT, 2 Spans, Lengths(m): 28-38, A-Ident Number: )				
Diaphragms/Cross Frame		8	8	
Bearings		5	6	Pins bent towards stream 10mm @ W beyond max contraction @ W Pins bent 5 to 20mm towards stream @ E-have been beyond max contraction @ E  Exp @ abuts and fixed neopad at pier
Temperature (deg. C)	12			
(Expansion Type : <b>REINFORCED NEOPRENE BEARING WITH TEFLON AND STAINLESS STEEL</b> )				
(Fixed Type : <b>REINFORCED PAD BEARING</b> )				
Coating Adequate (Y/N)	Yes			
Functioning (Y/N)	Yes			
Deck Underside		8	8	
Stains (Percent Area)	0			
<b>Span Alignment Problems</b>				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
<b>Superstructure General Rating</b>		<b>5</b>	<b>6</b>	
Substructure				
Bridge Component		Last	Now	Explanation of Condition
<b>Abutments</b>				
Bearing Seats/Caps		8	8	
(Type : <b>CONCRETE</b> )				
Backwalls/Breastwalls		8	8	
Wingwalls		8	8	
Piles		N	N	Buried
Paint/Coating		5	5	
Abutment Stability		7	8	
Scour/Erosion		9	7	
<b>Piers/Bents</b>				
(Type : <b>PIER-SOLID</b> )				
Bearing Seats/Caps		8	8	
(Type : <b>CONCRETE</b> )				
(Total Number of Bearing Piles : <b>0</b> )				
Pier Shaft/Piles		8	8	
Bracing/Struts/Sheathing		X	X	
Nose Plate		9	8	
Paint/Coating		7	7	
(Colour Description : )				
(Colour Code : )				
Pier Stability		8	8	
Scour		N	N	To Deep
Debris (Y/N)	No			
<b>Substructure General Rating</b>		<b>7</b>	<b>8</b>	

Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel</b>				
(U/S Direction : <b>N</b> )				Reservoir
(D/S Direction : <b>S</b> )				
Alignment		9	9	
Bank Stability		7	7	
HWM (m below Top of Curb)	4.0			No visable HWM
Drift (Y/N)	No			
Slope Protection		9	8	
(Type : <b>RIP RAP; RIP RAP</b> )				
Guidebank/Spurs		8	8	
Adequacy of Opening		9	7	
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>9</b>	<b>8</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
GALVANIZE/PAINT BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
SEAL DECK							
OVERLAY DECK							
REPAIR/REPLACE DECK JOINTS							
RESET/ PAINT BEARINGS							
WASHING							
SHOTCRETE REPAIRS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>66.7/77.8</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>70.0/72.4</b>	Est. Repl. Yr	2063	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tom Carey		Previous Assistant's Name				
Next Inspection Date	22-Aug-2013		Previous Inspection Date	04-Dec-2006			
Inspection Cycle (Default) (months)	39						
Comment							