

Bridge Inspection										
Bridge File Number	01293 -1 Bridge					Form Type	TH			
Year Built/Year Supstr	1908/1907					Lot No.	1			
Bridge or Town Name	GLEICHEN					Inspector Name	Garry Roberts			
Located Over	BOW RIVER, 2.13, WATERCRS-ST					Inspector Class	BR CLS A			
Located On	547:04 C1 16.850					Assistant Name				
Water Body Cl./Year						Assistant Class				
Navigabil. Cl./Year						Inspection Date	03-Jan-2012			
Legal Land Location	NE SEC 9 TWP 21 RGE 23 W4M					Data Entry By	Anne Roberts			
Longitude, Latitude	-113:07:52, 50:46:19					Data Entry Date	29-Jan-2012			
Road Authority	Alberta Transportation (AIT)					Reviewer Name	Joel Wozney			
Contract Main. Area	CMA30					Review Date	05-Jan-2012			
Clear Roadway/Skew	5.1 /					Dept. Reviewer Name	Tim Davies			
AADT/Year	940 / 2010 (A)					Dept. Review Date	06-Feb-2012			
Road Classification	RLU-208-100					Follow-Up By				
Detour Length (km)	50									
Allowable Load (t):	Single	H 22 STRINGER			Semi	HS 27 U1L2		Train	CS3 29 L3L4	----> On Critical Spans ---->Critical Member
Design Loading:	HS20									----> Primary Span

Posting Information												
Required Vert. Clearance Posting (m)												
Posted Vertical Clearance (Y/N)												
Posted:	Lane	NB	On Bridge (m)	4.4	In Advance (Y/N)	Yes	Lane	SB	On Bridge (m)	4.4	In Advance (Y/N)	Yes
Remarks												
Measured 4.590 at West and 4.586 at East. East portal sign damaged Minor damage @ north.												
Required Load Posting (t)												
Posted Loading (t)												
Posted:	Lane	NB	At Junction (Y/N)	Yes	In Advance (Y/N)	Yes	At Bridge (Y/N)	Yes				
Posted:	Lane	SB	At Junction (Y/N)	Yes	In Advance (Y/N)	No	At Bridge (Y/N)	Yes				
Remarks												

Hazard Marker At Bridge (Y/N)	Yes											
Remarks												
Other Sign Types	Narrow bridge, Stop if oncoming traffic on bridge.											

Utilities (Located at)												
Utility Attachments	TELEPHONE UTILITIES-Telus Fiber placed in duct March 2005											
Telephone	North side in conduit - One conduit is abandoned					Gas						
Power	3 wires 10 m North side. 1 attached to truss					Municipal						
Others	Lights installed along West truss. 400m below braces. Fiber optics East ROW					Problem (Y/N)		Yes				
Remarks												
Seven lights missing or broken. Conduit seperated along Sp3 and perforated at Sp1.												

Approach Road					
		Last	Now	Explanation of Condition	
Horizontal Alignment		4	5	Curves both ends.	
Vertical Alignment		5	5	Hills both ends.	
Roadway Width (m)		8.300			
Approach Bump		6	6		
Guardrail (Y/N)		Yes		Missing 1 splice bolt at SE	
Guardrail		5	4	Not thriebeam	
Length (m)		23.000			
Current Standard (Y/N)		No			
Termination Type		TURNED DOWN			
Drainage		7	7		
Approach Road General Rating		4	5		

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : TH, 3 Spans, Lengths(m): 53.3-53.3-53.3, A-Ident Number: A0108-04;A0108-05;A0108-06)					
Special Features					
Special Feature			X		
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last	0	0	0	0	
Now	0.0	0.0	0.0	0.0	
Wearing Surface/Deck Top			4	5	
(Material Type : UNTREATED TIMBER)					
(Plank Thickness(mm) : 75)					
(Plank Width(mm) : 300)					
Deck Rideability			6	6	
Deck Joints			X	X	
Temperature (deg. C)					
(Expansion Type :)					
(Fixed Type :)					
Gap Size (mm)		Gap Location			
Curbs/Wheel Guards			3	3	21 split blocks 3 wheelguard planks damaged, split or rotten
(Curb Type : Standard)					
(Type : TREATED TIMBER)					
(Thickness(mm) : 100)					
(Width(mm) : 300)					
Bridge Rail			4	4	Double layer of flexbeam not attached to bridge at Sp3- LOS and LON. 9 bridge rail blocks split or missing. Missing 21 splice bolts
(Type : GALVANIZED STEEL FLEX BEAM)					
Bridge Rail Posts/Blocking			4	4	
(Type : TREATED TIMBER;TREATED TIMBER)					
Bridge Rail/Posts Coating			7	6	
(Type : GALVANIZED)					
Sidewalk			X	X	

Superstructure							
Bridge Component		Last	Now	Explanation of Condition			
(Primary Span : TH, 3 Spans, Lengths(m): 53.3-53.3-53.3, A-Ident Number: A0108-04;A0108-05;A0108-06)							
Wide Load Damage (Y/N)	Yes			Open holes on all vert. & BP's where old bracing was connected. Minor damage at both portals of Sp. 2 & West portal Sp. 1 Minor high & Wide load damage @ Vert., diag. and portals Sp2- L0U1S and Sp3 - U9L10S have bends Sp 3 - U4L 4 top & bottom angle twisted bent & buckled. Sp 3 has moderate at U4S Sp 3 N - U3L4 has bend Sp2- U2L2S, Sp3 N- U4L4, U4L7, U8L8 all have bends or dents. Missing bolts at Sp2- U1S, U9S. Loose bolt at Sp3- U1N. Minor high load damage & isolated corrosion pitting at gussets. 300 x 150 dent Sp. 1 U5L5S and U7L7S 13 bayx30= 390 On set of corrosion on top flanges. Outside line of stringers are misaligned along Sp1 at L9S 100x210 stringers in between +2 channel 255 dp @ exit- 13 total lines.			
High Load Damage (Y/N)	Yes						
Top Chord		6	6				
Batter Posts		4	5				
Sway Bracings		4	4				
Diagonals		4	4				
Verticals		5	4				
Portals		5	5				
Connections		4	4				
Floor Beams		7	6				
Bottom Chord		6	6				
(No. of Stringers : 130;130;130)							
Stringer Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)			
Last							
Now							
Stringers			5	5			
(Type : STEEL)							
(Width(mm) : 100)							
(Depth(mm) : 255)							
(Spacing(mm) : 774)							
Paint Condition		3	3	Some isolated areas up to 1 - 2mm deep corrosion. Splash zone & lower steel @ abutment are rusting 15% - top steel paint is adequate. 10% surface corrosion @ floor system - photo. Corrosion depth comment from past U.T. inspection.			
(Colour Description : BLUE)							
(Colour Code : 15182)							
Touchup Required (Y/N)	No						
Bearings		4	4	SW & SE bridge rollers twisted 35mm. to 25mm & 2 broken A/B 4 a/b's broken @ South pier bearings. End of casting has broken piece at Sp1 - L0S and pin retainer plate has minor end cracks Functioning as sliding plates			
Temperature (deg. C)	11						
(Expansion Type : ROLLER NEST BEARING)							
(Fixed Type : PINNED BEARING)							
Functioning (Y/N)	No						
Sub Deck/Deck Underside		5	5				
(Material Type : TREATED TIMBER)							
(Plank Thickness(mm) : 100)							
(Plank Width(mm) : 300)							
Defects (Percent Area)	5						
Span Alignment Problems							
Vertical (Y/N)	No						
Horizontal (Y/N)	No						
Superstructure General Rating		4	4				
Substructure							
Bridge Component		Last	Now	Explanation of Condition			
Abutments							
(Extended Backwall Piles (Y/N) : N)							
(Extended Backwall Piles Spacing(mm) :)							

Substructure									
Bridge Component		Last	Now	Explanation of Condition					
(Total Number of Caps/Corbels : 1:1)				Several areas of concrete cracked and spalling - Massive concrete					
Bearing Seats/Caps/Corbels Detail Ratings									
	N (count)	1 (count)	2 (count)				3 (count)		
Last	0	0	0				0		
Now	0	0	0				0		
Bearing Seats/Caps/Corbels			4				4		
(Type : CONCRETE)									
(Depth(mm) :)									
(Width(mm) :)									
Backwalls/Breastwalls			5				5		
Greatest Height (m)		6.00		Wide map cracking. Worst at S abut					
Wingwalls			5	4					
(Total Number of Bearing Piles : 0:0)									
Piles Detail Ratings									
	N (count)	1 (count)	2 (count)				3 (count)		
Last	10								
Now	10	0	0				0		
Piles			N				N		
Paint/Coating			X				X		
Abutment Stability			7				6		
Scour/Erosion			8				8		
Piers/Bents									
(Type : PIER-SOLID)				Wide horizontal & map cracks. Horizontal crack under bearings, concrete is cracked and scaling on top of all piers.					
(Total Number of Caps/Corbels : 1:1)									
Bearing Seats/Caps/Corbels Detail Ratings									
	N (count)	1 (count)	2 (count)				3 (count)		
Last	0	0	0				0		
Now	0	0	0				0		
Bearing Seats/Caps/Corbels			4				4		
(Type : CONCRETE)									
(Total Number of Bearing Piles : 0:0)							Wide horizontal map cracks		
Piles Detail Ratings									
	N (count)	1 (count)	2 (count)	3 (count)					
Last	10	0	0	0					
Now	10	0	0	0					
Pier Shaft/Piles			5	5					
Greatest Height (m)		5.50							
Bracing/Struts/Sheathing			X	X					
Nose Plate			7	7					
Paint/Coating			4	4					
(Colour Description :)				100% surface corrosion @ nose plates.					
(Colour Code :)									
Pier Stability			7	7					
Scour			N	N					
Debris (Y/N)		Yes		Ice					
				Old piling D/S of pier 1 Beaver dam under Sp. 1					

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Substructure General Rating		4	4	
Structure Usage				
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : W)				The North bank is lined up 10m behind abutment.
(D/S Direction : E)				
Alignment		5	5	
Bank Stability		5	4	Vertical banks U/S and D/S Erosion at North end bank on U/S side
HWM (m below Top of Curb)				HWM not visible
Drift (Y/N)	Yes			Drift at Pier 1
Slope Protection		5	5	Class I @ both abutments.
(Type : RIP RAP; RIP RAP)				
Guidebank/Spurs		X	X	
Adequacy of Opening		7	7	
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		5	4	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL	2012	Replace damaged rail blocks - 9 in total and 21 splice bolts					
RETROFIT BRIDGE RAIL							
SEAL CURBS	2012	Replace 1- 1.5m, 1-1.9m, 6-5.6m wheelguard planks c/w 21 100x300 blocks					
PATCH DECK							
SEAL DECK							
OVERLAY DECK							
REPLACE STRIP DECK							
REPLACE SUB DECK							
RESET/ PAINT BEARINGS	2015	Replace bearings with neoprene pads next major rehab.					
REPAINT SUPERSTRUCTURE	2012	Assess paint or monitor					
STRAIGHTEN/REPLACE MEMBERS	2012	Sp2- L0U1S, U2L2S, and Sp 3 - U9L10S, U4L4N, U7L7N, U8L8N, U3L4N. Replace top and bottom sway brace angles at sp 3- U4U4. Salvage cross frame bracing					
WASHING							
SHOTCRETE REPAIRS							
CORE TIMBER CAPS/CORBELS							
REPAIR/REPLACE TIMBER CAPS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION	2012						
OTHER ACTION	2012	Add bolts at Sp2- U1S, U9S and sp3 U1N					
OTHER ACTION	2012	Replace broken lights at NW at West side					
OTHER ACTION	2015	Patch substructure next major rehab					
OTHER ACTION	2012	Assess for replacement vs. repair					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	44.4/44.4	Sufficiency Rating (Last/Now) (%)	16.5/23.7	Est. Repl. Yr	2023	Maint. Req. (Y/N)	Yes

Special Comments for Next Inspection		Department Comments	
Maintenance Reviewed By		Date	Estimated Total 0
Proposed Long-Term Strategy			
On 3-Year Program (Y/N)			
Proposed Action			
Previous Inspector's Name	Owen Salava	Previous Assistant's Name	Ed Kowal
Next Inspection Date	03-Apr-2015	Previous Inspection Date	08-Jun-2010
Inspection Cycle (Default) (months)	39		
Comment			