							Bridge I	nspe	ction							
Bridge File Num	nber	13114	4 -1 Bridg	Э				Form Type				PCS				
Year Built/Year 1961/1961							Lot No.				3					
Supstr									Inspector Name			Colin Roy				
Bridge or Town	Name								Inspector Class			BR CLS A				
Located Over				REEK, 2.13.32, WATERCRS-ST					istant 1	Name						
Located On		LOCA	L ROAD			Assistant Class										
Water Body Cl./									ection	Date		18-Aug-2010				
Navigabil. Cl./Y									a Entry	Ву Ву		Alyssa Boynton				
Legal Land Loc									a Entry	Date		03-Dec-2010				
Longitude, Latit	ude			27, 51:16:15					Reviewer Name			Garry Roberts				
•				ortation (AIT)			Rev	Review Date			14-Sep-2010				
Contract Main. Area UNDEFIN				MA				Dep	t. Revi	ewer N	lame	Lorenz Bohi	nert			
Clear Roadway/Skew 13.8 /								Dep	t. Revi	ew Dat	:e	13-Dec-201	0			
AADT/Year 15,000 / 2								Foll	ow-Up	Ву						
Road Classification RCU-211			211.0-11)				_								
	etour Length (km) 3			1-		_			I	1			l			
Allowable Load	(t): Sin		CS1 23 SIRDER		Semi		S2 40 SIRDER			Train	GII	3 58 RDER		> On Critical Spans >Critical Member		
Design Loading: HS2			HS20											> Primary	Span	
Deguired Load Desting (t)				0: 1		Р	osting I	nforn					Tuus	Truck Train		
Required Load Posting (t) Posted Loading (t)				Single			23		Semi							
Posted:	T.		<u> </u>	Single At Junction (. (A.I)			Semi In Advance (Y/N)			Truck Train				
	Lane	EE			•								At Bridge (Y/N) At Bridge (Y/N)			
Remarks	Posted: Lane WB		Ь	At Junction (Y					In Advance (Y/N)			ALD	riuge (1714)			
	Not re		N) No													
Hazard Marker At Bridge (Y/N) Remarks		N) INO														
Other Sign Types		Rou	e, speed,	60 km/l	hr											
Striot Sign Types		Rou	с, эрсса,	OO KITI/I		tilities (l	Locaí	ted at)								
Utility Attachme	nts						(
Telephone	T.	 а						Gas	 S							
Power								Municipal								
Others	wer In area hers Light standard		rds					Problem (Y/N) No								
Remarks	rs In area Light standards															
							Approa	ach R	oad							
						Now	Exp	Explanation of Condition								
Horizontal Alignment					5	5	Inte	rsectio	n with t	raffic	lights 10m W	/est				
Vertical Alignment					7	7										
Roadway Width (m)																
Approach Bump)					7	7									
Guardrail (Y/N)			Yes	Yes				Insufficient bolt length at SE corner								
Guardrail						8	4	esm	n at NE							
Length (m)																
Current Stand	lard (Y/	N)	Yes													
Termination T	уре		Turr	down												
Drainage						7	7									
Approach Roa	d Gene	eral Ra	ting			5	5									

						Supers	tructure
Bridge Component							Explanation of Condition
		M), 3 S	pans, l	_engths(m): 6	6.1-8.5-		dent Number:)
Special Feat	ures						
Special Feat						Х	
(Type:)							
Special Feat	ure					X	
(Type :)							
	ace/Deck Top	Detail	Ratings				
Trouming Curr	N (%)	1 (%)	rtatirige	2 (%)	3 (%)		
Last	0		0	0		0	
Now	0.0		0.0	0.0	1	0.0	
Wearing Surf			7.0	0.0	7	6	Narrow longitudinal cracks at WBL. Diagonal cracking at 100mm
(Material Type :)						0	above north CIP girder span 1
(Thickness(mm) :) Lateral Connection Problem No							
(Y/N) Deck Top					N	6	Transverse and longitudinal narrow either side of median
							-
Deck Rideability					8	8	
Deck Joints					8	8	Galv. buffer angles
Bump (Y/N)		No			1	
Deck Drainage					7	7	
Drains Clogged (Y/N) No							
Curbs/Median						8	
(Curb Type	: Standard)						
Scaling (Percent Area) 2							
Bridge Rail					9	9	
(Type : GA	LVANIZED ST	TEEL T	HRIE B	BEAM)			
Bridge Rail P	osts			·	9	9	
(Type:)							
Bridge Rail/Posts Coating					8	8	
(Type : GALVANIZED)							
Sidewalk					Х	Х	
Cidowant							
Girder Detail	Ratings						
	N (count) 1 (count) 2 (count)		3 (cou	ınt)			
Last	0	(0	0	0		
Now	Now 0 0 0					0	
Girders					8	7	Bridge has been widened several times and is comprised of CIP
Last Complete Inspection Date 18-Aug-2010				-2010			sections at east end and a mix of SL-SC and SM girders. 4 transverse cracks with efflorecenses CIP girder, span 2, south side
Cracking (\	Cracking (Y/N) Yes						gruor, span 2, south side
Spalling (Percent Area) 0							
	Lift or Connector Pocket Yes						
(Number Of 0	•						
	nent Problems	s					
Vertical (Y/			No				
Horizontal			No				
	ure General R				8	7	

					Subst	ructure
Bridge Comp	nonent			Last	Now	Explanation of Condition
Abutments	Jonem	<u> </u>		Last	INOW	Explanation of condition
	Backwall Piles	(Y/N) · Y)				
	Backwall Piles		\\ : 1600\			-
	er of Caps/Cor		i) . 1000)			
	s/Caps/Corbel		age .			-
bearing Seats	N (count)			3 (cou	ınt\	_
Loot	,	1 (count)	2 (count)			
Last	0	0	0		0	-
Now	0 (0 1 1	0	0		0	_
	s/Caps/Corbel	S		8	8	
(Type : STE						_
(Depth(mm)						
(Width(mm)	· · · · · · · · · · · · · · · · · · ·			8	_	
Backwalls/Breastwalls					8	
Greatest Height (m) 3.20						
Wingwalls					8	H-pile wing walls.
/Total Niveska	or of Pooring D	iloo : 25-22\				22 piles at East abut
(Total Number of Bearing Piles : 25:23)						23 piles at East abut.
Piles Detail R	_	1 (05:07!)	2 (55.151)	2 /==	.n.t\	-
1 1	N (count)	1 (count)	2 (count)	3 (cou		_
Last	0	0	0		0	
Now	0	0	0		0	
Piles				8 X	8	
Paint/Coating					X	
Abutment Stability					8	
Scour/Erosion					8	
Piers/Bents						
	R-COLUMN)					
	· ·	hels : 1:1)				10-300x300 HP piles. Old timber
(Total Number of Caps/Corbels : 1:1) Bearing Seats/Caps/Corbels Detail Ratings						piles cut 150mm below steel caps
N (count) 1 (count) 2 (count)					unt)	
Last 0 0 0					0	Double H-pile caps.
Now	0	0	0		0	-
Bearing Seats/Caps/Corbels					8	-
(Type : STE				8	U	-
(Depth(mm) : 305) (Width(mm) : 620)						
	· · · · · · · · · · · · · · · · · · ·	iloo (OF-O4)				24 piles at Fast shut
	er of Bearing P	riies : 25:24)				24 piles at East abut.
Piles Detail R		4 (- 1)	0 ()	0.1	4\	-
•	N (count)	1 (count)	2 (count)	3 (cou		-
Last	0	0	0		0	
Now	0	0	0		0	_
Pier Shaft/Piles				8	8	
Greatest He		3.00				
Bracing/Struts	s/Sheathing			7	7	
Nose Plate				8	8	
Paint/Coating				Х	Х	
(Colour Des						
(Colour Cod	de :)					

				ructure
Bridge Component		Last	Now	Explanation of Condition
Pier Stability		7	7	
Scour		7	7	
Debris (Y/N)	No			
Substructure General Rating			7	
		5	Structu	re Usage
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : N)				Ped. bridge 25m D/S
(D/S Direction : S)				
Alignment			7	
Bank Stability			7	
HWM (m below Top of Curb)				No visible HWM
Drift (Y/N)	t (Y/N)			
Slope Protection		6	7	
(Type: RIP RAP; RIP RAP)				
Guidebank/Spurs			X	
Adequacy of Opening			7	
(Fish Compensation Measure 1	: NONE)			
(Fish Compensation Measure 2	: NONE)			
Channel General Rating		6	7	

		Maintenance Re	commend	ations					
Inspector Recommendations	Year	Inspector Comments		Department Comm	ents		Target Year	Est. Cost	Cat #
REPAIR/REPLACE BRIDGE RAIL									
SEAL CURBS									
PATCH DECK									
OVERLAY DECK									
STRAIGHTEN/REPLACE MEMBERS									
WASHING									
SHOTCRETE REPAIRS									
CORE TIMBER CAPS/CORBELS									
REPAIR/REPLACE TIMBER CAPS									
REPAIR ABUTMENT SCOUR/EROSI	NC								
PLACE ADDITIONAL RIP RAP									
REMOVE DRIFT ACCUMULATION									
INSTALL STRUTS									
OTHER ACTION	2010	Replace Short GR bolts							
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
Structural Condition Rating (Last/N (%)	ow) 88.9/7	7.8 Sufficiency Rating (Last/N	low) 7	75.8/71.8	Est. Repl. Yr	2060	Maint. Re	qd. (Y/N)	Yes
Special Comments for Next Inspection	,	,		Department Comments			,		
Maintenance Reviewed By				Date			Estimated Total	0	
Proposed Long-Term Strategy									
On 3-Year Program (Y/N)									
Proposed Action									
Previous Inspector's Name	Garry Robert	S	Previous A	Assistant's Name					
Previous Inspector's Name Next Inspection Date	Garry Roberts 18-Nov-2013	3		Assistant's Name	01-Mar-2010				
					01-Mar-2010				