

Bridge Culvert Inspection			
Bridge File Number	13320 -1 Bridge Culvert	Form Type	CUL1
Year Built	1956	Lot No.	1
Bridge or Town Name	BROCKET	Inspector Name	Calvin Roberts
Located Over	CROWLIDGE CREEK, 2.12.28, WATERCRS-ST	Inspector Class	BR CLS B
Located On	786:02 C1 2.604	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	28-Nov-2012
Legal Land Location	NE SEC 19 TWP 6 RGE 28 W4M	Data Entry By	Lauren Korte
Longitude, Latitude	-113:44:59, 49:29:19	Data Entry Date	19-Dec-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Garry Roberts
Contract Main. Area	CMA26	Review Date	02-Dec-2012
Clear Roadway/Skew	8.8 /	Dept. Reviewer Name	Tim Davies
AADT/Year	80 / 2011 (A)	Dept. Review Date	27-Dec-2012
Road Classification	RCU-209-110	Follow-Up By	
Detour Length (km)	6		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	2316	2560	SPE	28.8	152X51	3.5	ELLIPSE
Special Features	VERT TIMBER STRUTS							
Special Features Comment								

Utilities (Located at)

Utility Attachments							
Telephone	West ROW.			Gas	Crosses 15m South.		
Power	1 Line 50m North.			Municipal			
Others	Waterline 30m North.			Problem (Y/N)	No		
Remarks							

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		5	5	Sharp curve 60m North. Gentle sag curve through valley.
Vertical Alignment		5	5	
Roadway Width (m)	8.800			
Embankment		7	7	
Sideslope (:1)	3.0			
(Height of Cover(m) : 2.2)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		5	5	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction				West end.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		6	6	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			Drift and Debris blocking the bevel.
Above/Below (mm)	200			
Scour Protection		5	5	Vegetation growing.
(Type :)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Upstream End General Rating		6	6	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2316, Rise (mm): 2560, Type: SPE)				
Barrel Last Accessible Date	28-Nov-2012			
Special Features				
Special Feature		6	5	
(Type : VERT TIMBER STRUTS)				
Special Feature				
(Type :)				
Roof		3	3	Rating based in deflection.
Measured Rise (mm)	2200			
Measured At Ring No.	5			
Sag (mm)	360			
Percent Sag	14			
Sidewall		2	2	Cracks in both sidewalls.
Measured Span (mm)	2740			
Measured At Ring No.	5			
Deflection (mm)	424			
Percent Deflection	18			
Floor		N	N	Silt and water covered.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	Yes			
Circumferential Seams		5	5	
Separation (mm)	0			
Longitudinal Seams		2	2	Cracks in both sidewalls of R-3 and 5 with 27mm rem. steel at R5. Cracks in 1 sidewall of R-2,4,6 and 8 all at South sidewall.
Total No. of Cracked Rings	6			
Total No. of Rings with Two Cracked Seams	2			
Min. Remaining Steel Between Cracks (mm)	25			
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	Yes			
Coating		4	4	Extensive corrosion at sidewalls.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	Yes			Water 0.7m.

Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2316, Rise (mm): 2560, Type: SPE)					
Fish Passage Adequacy		4	4		
Baffle		X	X		
(Type :)					
Waterway Adequacy		3	3	U/S end is blocked with drift and debris. Silt to 0.4m	
Icing (Y/N)	No				
Silting (Y/N)	Yes				
Drift (Y/N)	Yes				
Barrel General Rating		3	3	The GR increased due to the struts.	
Downstream End					
Culvert Component		Last	Now	Explanation of Condition	
Direction				East end.	
End Treatment (Concrete, Steel, Others, None)	STEEL				
Headwall		X	X		
Collar		X	X		
Wingwalls		X	X		
(Shape :)					
Cutoff Wall		X	X		
Bevel End		6	6		
Heaving (mm)	0				
Invert Above/Below Stream Bed	ABOVE				
Above/Below (mm)	0				
Scour Protection		4	4	Scoured @ sides of bevel. Appears to have scour @ stream also.	
(Type : NATURAL)					
(Avg. Rock Size(mm) :)					
Scour/Erosion		4	4	Scour hole d/s 8m x 10mx 1.0m	
Beavers (Y/N)	No				
Downstream End General Rating		4	4		
Structure Usage					
		Last	Now	Explanation of Condition	
Channel (U/S and D/S)					
Alignment		5	5		
Bank Stability		5	5		
HWM (m below Top of Culvert)				HWM not visible. At U/S bevel.	
Drift (Y/N)	Yes				
Channel Bottom Degrading/Aggrading	DEGRADING			At D/S.	
Beavers (Y/N)	No				
(Fish Compensation Measure 1 : NONE)					
(Fish Compensation Measure 2 : NONE)					
Channel General Rating		5	5		

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION	2013	Remove drift blockage at U/S bevel.					
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2015	Replace pipe.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	33.3/33.3	Sufficiency Rating (Last/Now) (%)	34.2/34.3	Est. Repl. Yr	2015	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	2 Notification sent Dec 3/12.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	28-Feb-2016		Previous Inspection Date	09-Sep-2009			
Inspection Cycle (Default) (months)	39						
Comment							