

Bridge Inspection									
Bridge File Number	13473 -1 Bridge				Form Type	SG			
Year Built/Year Supstr	1987/1987				Lot No.	2			
Bridge or Town Name	LUNNFORD				Inspector Name	Arnold Assenheimer			
Located Over	PEMBINA RIVER, 8.11.84, WATERCRS-ST				Inspector Class	BR CLS A			
Located On	654:04 C1 5.188				Assistant Name	Wade Nanninga			
Water Body Cl./Year					Assistant Class	BR CLS B			
Navigabil. Cl./Year					Inspection Date	19-Aug-2011			
Legal Land Location	SW SEC 1 TWP 59 RGE 3 W5M				Data Entry By	Theresa Lacusta			
Longitude, Latitude	-114:19:15, 54:03:54				Data Entry Date	27-Sep-2011			
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Eric Carcoux			
Contract Main. Area	CMA10				Review Date	21-Sep-2011			
Clear Roadway/Skew	9 / 20 deg. (RHF)				Dept. Reviewer Name	Brent Herrick			
AADT/Year	470 / 2010 (A)				Dept. Review Date	28-Sep-2011			
Road Classification	RCU-209-110				Follow-Up By				
Detour Length (km)	13								
Allowable Load (t):	Single	CS1 28	Semi	CS2 49	Train	CS3 62	----> On Critical Spans ---->Critical Member		
Design Loading:	MS300						----> Primary Span		
Posting Information									
Required Load Posting (t)	Single			Semi			Truck Train		
Posted Loading (t)	Single			Semi			Truck Train		
Posted:	Lane	EB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Posted:	Lane	WB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Remarks	Not required.								
Hazard Marker At Bridge (Y/N)	Yes								
Remarks	Not at correct location on approach rail posts. At varying heights.								
Other Sign Types									
Utilities (Located at)									
Utility Attachments	TELEPHONE UTILITIES-PHONE LINE								
Telephone	South r/w.				Gas				
Power	1 wire South r/w.				Municipal				
Others					Problem (Y/N)	No			
Remarks									
Approach Road									
			Last	Now	Explanation of Condition				
Horizontal Alignment			5	5	Between 2 curves. Farm approach immediately at SW corner.				
Vertical Alignment			8	8					
Roadway Width (m)	9.200								
Approach Bump			7	7					
Guardrail (Y/N)	Yes				Not to proper height (too low), insufficient length - photo. Typical at all corners. Missing splice bolts @ SE & NW (end cap) - photos.				
Guardrail			4	4	SW twisted.				
Length (m)	10.000								
Current Standard (Y/N)	No								
Termination Type	Turned Down								
Drainage			3	3	Erosion hole @ SW & SE beside curbs - photos.				
<b>Approach Road General Rating</b>			<b>3</b>	<b>5</b>					

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : <b>WG, 3 Spans, Lengths(m): 30-38-30, A-Ident Number: A1081-01</b> )					
<b>Special Features</b>					
Special Feature			X		
(Type : )					
Special Feature			X		
(Type : )					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
<b>Last</b>				5	
<b>Now</b>	0.0	0.0	0.0	5.0	
Wearing Surface			3	3	Narrow/medium longitudinal & transverse cracking, some sealed, some not. Local unravelling/potholes at various locations in both lanes, holding water - photo.
(Material Type : <b>ACP</b> )					
(Thickness(mm) : <b>50</b> )					
Deck Top			N	N	
Deck Rideability			6	6	
Deck Joints			3	3	2 bolts missing broken East abutment. (EBL is incorrectly installed. 2001/08/14)
Temperature (deg. C)		20			
(Expansion Type : <b>ARMOURED GLAND (WABO UNDER FINGER OR SLIDING PLATES)</b> )					
(Fixed Type : )					
Gap Size (mm)		Gap Location			
25		East			
60		West			
Deck Drainage			8	8	
Drains Clogged (Y/N)		No			
Curbs/Median			7	7	Transverse cracks 500-1200 typical. Outside of curbs are cracked, rust stains and efflorescence.
(Curb Type : <b>Standard</b> )					
Scaling (Percent Area)		0			
Bridge Rail			9	9	Bridgerail post grout pad delaminating approx 2% of posts - photo.
(Type : <b>BRIDGE TUBE;GALVANIZED STEEL BRIDGE TUBE</b> )					
Bridge Rail Posts			5	4	
(Type : <b>GALVANIZED POST STEEL</b> )					
Bridge Rail/Posts Coating			8	8	
(Type : <b>GALVANIZED</b> )					
Sidewalk			X	X	
<b>Girder/Beam</b>					
Cover Plate			X	X	
Flange			9	9	
Web			9	9	
Stiffeners			9	9	
Splice			9	9	
Weld			9	9	
Diaphragms/Cross Frame			9	9	

Superstructure				
Bridge Component		Last	Now	Explanation of Condition
<b>(Primary Span : WG, 3 Spans, Lengths(m): 30-38-30, A-Ident Number: A1081-01)</b>				
Paint Condition		9	9	Weathering steel.
(Colour Description : )				
(Colour Code : )				
Touchup Required (Y/N)	No			
Bearings		4	4	A1G1& G3 neoprene pad with horizontal narrow crack. - photo. Bearings on piers viewed with binoculars.
Temperature (deg. C)	20			
(Expansion Type : <b>POT BEARING</b> )				
(Fixed Type : <b>REINFORCED NEOPRENE BEARING WITH TEFLON AND STAINLESS STEEL</b> )				
Coating Adequate (Y/N)	Yes			
Functioning (Y/N)	Yes			
Deck Underside		7	6	Few narrow cracking.
Stains (Percent Area)	0			
<b>Span Alignment Problems</b>				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
<b>Superstructure General Rating</b>		<b>8</b>	<b>4</b>	
Substructure				
Bridge Component		Last	Now	Explanation of Condition
<b>Abutments</b>				
Bearing Seats/Caps		8	8	
(Type : <b>CONCRETE</b> )				
Backwalls/Breastwalls		8	8	
Wingwalls		7	7	
Piles		N	N	
Paint/Coating		4	6	
Abutment Stability		9	9	
Scour/Erosion		8	8	
<b>Piers/Bents</b>				
(Type : <b>PIER-SOLID</b> )				Couple pop outs east pier west face, (could have been from gun shots).
Bearing Seats/Caps		8	8	
(Type : <b>CONCRETE</b> )				
(Total Number of Bearing Piles : <b>0:0</b> )				Medium vertical crack both piers & random narrow cracking.
Pier Shaft/Piles		7	7	
Bracing/Struts/Sheathing		X	X	
Nose Plate		6	6	Slight scaling or abrasion from ice just below nose plate.
Paint/Coating		6	6	
(Colour Description : )				
(Colour Code : )				
Pier Stability		9	9	
Scour		N	N	
Debris (Y/N)	No			

Substructure				
Bridge Component		Last	Now	Explanation of Condition
<b>Substructure General Rating</b>		<b>7</b>	<b>7</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel</b>				
(U/S Direction : <b>S</b> )				
(D/S Direction : <b>N</b> )				
Alignment		7	6	
Bank Stability		5	5	
HWM (m below Top of Curb)				Vertical cut bank @ SW bank . Not affecting bridge.
Drift (Y/N)	Yes			HWM not visible.
Slope Protection		8	7	Riprap in top portion of West headslope only. Most of east headslope natural.
(Type : <b>RIP RAP; NATURAL</b> )				
Guidebank/Spurs		X	X	
Adequacy of Opening		9	9	
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>5</b>	<b>5</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
GALVANIZE/PAINT BRIDGE RAIL							
RETROFIT BRIDGE RAIL							
SEAL CURBS							
PATCH DECK	2011	Patch deck ACP delam/potholes, seal cracks.					
SEAL DECK							
OVERLAY DECK							
REPAIR/REPLACE DECK JOINTS	2011	Replace missing/broken cover plate bolts and tighten loose bolts.					
RESET/ PAINT BEARINGS	2011	Replace A1G1/G3 neoprene pad at major rehab.					
REPAINT SUPERSTRUCTURE							
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
SHOTCRETE REPAIRS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
OTHER ACTION	2011	Upgrade approach guardrail to meet standard, install splice bolt where missing.					
OTHER ACTION	2011	Plug erosion holes @ SW & SE corners.					
OTHER ACTION	2011	Reinstall hazard markers to meet standard.					
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>83.3/61.1</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>63.2/62.2</b>	Est. Repl. Yr	2055	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	Monitor bridgerail post grout pad delam.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Dave Lam		Previous Assistant's Name				
Next Inspection Date	19-Nov-2014		Previous Inspection Date	07-May-2008			
Inspection Cycle (Default) (months)	39						
Comment							