

| Bridge Culvert Inspection | | | | |
|---------------------------|---|--|---------------------|---------------|
| Bridge File Number | 01461 -2 Bridge Culvert | | Form Type | CUL1 |
| Year Built | 2006 | | Lot No. | 4 |
| Bridge or Town Name | ELKWATER | | Inspector Name | Jason Rusu |
| Located Over | TRIBUTARY TO ROSS CREEK, 2.7.9, WATERCRS-ST | | Inspector Class | BR CLS A |
| Located On | 41:04 C1 15.745 | | Assistant Name | |
| Water Body Cl./Year | | | Assistant Class | |
| Navigabil. Cl./Year | | | Inspection Date | 14-Jan-2012 |
| Legal Land Location | SW SEC 3 TWP 10 RGE 3 W4M | | Data Entry By | Anne Roberts |
| Longitude, Latitude | -110:20:37, 49:47:27 | | Data Entry Date | 29-Feb-2012 |
| Road Authority | Alberta Transportation (AIT) | | Reviewer Name | Garry Roberts |
| Contract Main. Area | CMA23 | | Review Date | 23-Jan-2012 |
| Clear Roadway/Skew | 8 / 0 deg. | | Dept. Reviewer Name | Tim Davies |
| AADT/Year | 650 / 2010 (A) | | Dept. Review Date | 11-Mar-2012 |
| Road Classification | RAU-209-110 | | Follow-Up By | |
| Detour Length (km) | 10 | | | |

Bridge Culvert Information

| | | | | | | | | |
|--------------------------|--------|------|----------------|------|--------|---------------|--------------------|-------|
| Number of Culverts | 1 | | | | | | | |
| Pipe # | Barrel | Span | Rise (or Dia.) | Type | Length | Corr. Profile | Pl./Slab Thickness | Shape |
| 1 | MAIN | 3440 | 3440 | SP | 48.77 | 152X51 | 3.5 | ROUND |
| Special Features | | | | | | | | |
| Special Features Comment | | | | | | | | |

Utilities (Located at)

| | | | | |
|---------------------|------------|--|---------------|----|
| Utility Attachments | | | | |
| Telephone | West Ditch | | Gas | |
| Power | | | Municipal | |
| Others | | | Problem (Y/N) | No |
| Remarks | | | | |

Approach Road / Embankment

| | | Last | Now | Explanation of Condition |
|--|-------|----------|----------|-------------------------------|
| Horizontal Alignment | | 7 | 7 | No passing In a sag curve. |
| Vertical Alignment | | 4 | 4 | |
| Roadway Width (m) | 8.000 | | | |
| Embankment | | 8 | 8 | |
| Sideslope (__:1) | 5.0 | | | |
| (Height of Cover(m) : 5.4) | | | | |
| Guardrail (Y/N) | No | | | |
| Approach Road / Embankment General Rating | | 4 | 4 | |

Upstream End

| Culvert Component | | Last | Now | Explanation of Condition |
|---|----------|------|-----|--------------------------|
| Direction | | W | | |
| End Treatment (Concrete, Steel, Others, None) | CONCRETE | | | |
| Headwall | | 9 | 8 | |
| Collar | | 9 | 8 | |
| Wingwalls | | X | X | |
| (Shape :) | | | | |
| Cutoff Wall | | N | N | |

| Upstream End | | | | |
|--|-------------|----------|----------|--|
| Culvert Component | | Last | Now | Explanation of Condition |
| Bevel End | | 8 | 8 | |
| Heaving (mm) | 0 | | | |
| Invert Above/Below Stream Bed | BELOW | | | |
| Above/Below (mm) | 800 | | | |
| Scour Protection | | 4 | 6 | U/S scour erosion displaced in previous high water- repaired |
| (Type : RIP RAP) | | | | |
| (Avg. Rock Size(mm) : 350) | | | | |
| Scour/Erosion | | 4 | 6 | |
| Beavers (Y/N) | No | | | |
| Upstream End General Rating | | 4 | 6 | |
| Bridge Culvert Barrel | | | | |
| Culvert Component | | Last | Now | Explanation of Condition |
| (Pipe # : 1, Secondary Span, Location Code: MAIN, Span (mm): 3440, Rise (mm): 3440, Type: SP) | | | | |
| Barrel Last Accessible Date | 07-Nov-2008 | | | 1m of water in pipe |
| Special Features | | | | |
| Special Feature | | | | |
| (Type :) | | | | |
| Special Feature | | | | |
| (Type :) | | | | |
| Roof | | N | N | Shape looks good PR 9 |
| Measured Rise (mm) | 3460 | | | |
| Measured At Ring No. | 8 | | | |
| Sag (mm) | 0 | | | |
| Percent Sag | | | | |
| Sidewall | | N | N | Inward PR 9 |
| Measured Span (mm) | 3416 | | | |
| Measured At Ring No. | 8 | | | |
| Deflection (mm) | 24 | | | Est |
| Percent Deflection | | | | |
| Floor | | N | N | PR 9 |
| Bulge (mm) | 0 | | | |
| Measured At Ring No. | | | | Est |
| Abrasion (Y/N) | | | | |
| Circumferential Seams | | N | N | PR 9 |
| Separation (mm) | 0 | | | |
| Longitudinal Seams | | N | N | PR 9 |
| Total No. of Cracked Rings | 0 | | | |
| Total No. of Rings with Two Cracked Seams | 0 | | | |
| Min. Remaining Steel Between Cracks (mm) | 0 | | | |
| Proper Lap (Y/N) | Yes | | | |
| Longitudinal Stagger (Y/N) | Yes | | | |
| Coating | | 9 | 8 | |
| Corrosion By Soil (Y/N) | No | | | |
| Corrosion By Water (Y/N) | No | | | |
| Camber POS/ZERO/NEG | ZERO | | | |
| Ponding (Y/N) | No | | | |

| Bridge Culvert Barrel | | | | |
|---|-----------|----------|----------|--------------------------------|
| Culvert Component | | Last | Now | Explanation of Condition |
| (Pipe # : 1, Secondary Span, Location Code: MAIN, Span (mm): 3440, Rise (mm): 3440, Type: SP) | | | | |
| Fish Passage Adequacy | | X | X | |
| Baffle | | X | X | |
| (Type :) | | | | |
| Waterway Adequacy | | 9 | 9 | |
| Icing (Y/N) | No | | | |
| Silting (Y/N) | No | | | |
| Drift (Y/N) | No | | | |
| Barrel General Rating | | N | N | PR 9 |
| Downstream End | | | | |
| Culvert Component | | Last | Now | Explanation of Condition |
| Direction | | E | | |
| End Treatment (Concrete, Steel, Others, None) | STEEL | | | |
| Headwall | | X | X | |
| Collar | | X | X | |
| Wingwalls | | X | X | |
| (Shape :) | | | | |
| Cutoff Wall | | X | X | |
| Bevel End | | 8 | 8 | |
| Heaving (mm) | 0 | | | |
| Invert Above/Below Stream Bed | BELOW | | | |
| Above/Below (mm) | 800 | | | |
| Scour Protection | | 4 | 6 | Rip rap is repaired |
| (Type : RIP RAP) | | | | |
| (Avg. Rock Size(mm) : 350) | | | | |
| Scour/Erosion | | 4 | 6 | |
| Beavers (Y/N) | No | | | |
| Downstream End General Rating | | 4 | 6 | |
| Structure Usage | | | | |
| | | Last | Now | Explanation of Condition |
| Channel (U/S and D/S) | | | | |
| Alignment | | 5 | 5 | U/S channel 90 degrees to pipe |
| Bank Stability | | 4 | 6 | |
| HWM (m below Top of Culvert) | 0.0 | | | Flood above crown |
| Drift (Y/N) | No | | | |
| Channel Bottom Degrading/Aggrading | DEGRADING | | | |
| Beavers (Y/N) | No | | | |
| (Fish Compensation Measure 1 : NONE) | | | | |
| (Fish Compensation Measure 2 : NONE) | | | | |
| Channel General Rating | | 4 | 5 | |

| Maintenance Recommendations | | | | | | | |
|---|------------------|--|---------------------------|---------------|-----------------|-------------------|----|
| Inspector Recommendations | Year | Inspector Comments | Department Comments | Target Year | Est. Cost | Cat # | |
| SHOTCRETE REPAIRS | | | | | | | |
| PLACE ADDITIONAL RIP RAP | | | | | | | |
| REMOVE DRIFT ACCUMULATION | | | | | | | |
| INSTALL CONCRETE/STEEL LINING | | | | | | | |
| INSTALL STRUTS | | | | | | | |
| INSTALL CONCRETE COLLAR/CUTOFF | | | | | | | |
| REPAIR SEAMS | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| Structural Condition Rating (Last/Now) (%) | 55.6/55.6 | Sufficiency Rating (Last/Now) (%) | 55.3/59.7 | Est. Repl. Yr | 2056 | Maint. Req. (Y/N) | No |
| Special Comments for Next Inspection | | | Department Comments | | | | |
| Maintenance Reviewed By | | | Date | | Estimated Total | 0 | |
| Proposed Long-Term Strategy | | | | | | | |
| On 3-Year Program (Y/N) | | | | | | | |
| Proposed Action | | | | | | | |
| Previous Inspector's Name | Jason Rusu | | Previous Assistant's Name | | | | |
| Next Inspection Date | 14-Oct-2013 | | Previous Inspection Date | 07-Aug-2010 | | | |
| Inspection Cycle (Default) (months) | 21 | | | | | | |
| Comment | | | | | | | |