

Bridge Culvert Inspection				
Bridge File Number	01635 -1 Bridge Culvert		Form Type	CUL1
Year Built	1960		Lot No.	1
Bridge or Town Name	STONY PLAIN		Inspector Name	Todd Warshawski
Located Over	ATIM CREEK, 6.65.8, WATERCRS-ST		Inspector Class	BR CLS B
Located On	16A:14 L1 13.760;16A:14 R1 14.287		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	05-Jul-2012
Legal Land Location	SE SEC 6 TWP 53 RGE 27 W4M		Data Entry By	Theresa Lacusta
Longitude, Latitude	-113:57:52, 53:32:28		Data Entry Date	10-Jul-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Eric Carcoux
Contract Main. Area	CMA11		Review Date	09-Jul-2012
Clear Roadway/Skew	34.6 /		Dept. Reviewer Name	Brent Herrick
AADT/Year	26,920 / 2011 (A)		Dept. Review Date	17-Jul-2012
Road Classification	RAD-616.6-130		Follow-Up By	
Detour Length (km)	1			

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	1429	1575	SPE	76	152X51	3.5	ELLIPSE
Special Features	VERT STEEL STRUTS							
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	S r/w.	Gas	
Power		Municipal	
Others		Problem (Y/N)	
Remarks			

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	8	8	Intersection to east. 6 lane divided highway.
Vertical Alignment	8	8	
Roadway Width (m)	34.600		17.3 WBL, 17.3 EBL
Embankment	8	8	
Sideslope (_ :1)	4.0		
(Height of Cover(m) : 2.8)			
Guardrail (Y/N)	No		
Approach Road / Embankment General Rating	8	8	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	S		
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls (Shape :)	X	X	
Cutoff Wall	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		6	4	Wire mesh screen over inlet. Bevel top twisted and turned.
Heaving (mm)	150			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	100			
Scour Protection		5	5	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 250)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Upstream End General Rating		5	4	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1429, Rise (mm): 1575, Type: SPE)				
Barrel Last Accessible Date	05-Jul-2012			Rings 1-15 not accessible.
Special Features				
Special Feature		6	6	Located 1/3L of D/S end. Steel 3" x 4" and 3" x 3" tubing.
(Type : VERT STEEL STRUTS)				
Special Feature				
(Type :)				
Roof		3	3	
Measured Rise (mm)	1480			
Measured At Ring No.	18			
Sag (mm)	95			
Percent Sag	6			
Sidewall		2	2	See longitudinal seam comment.
Measured Span (mm)	1467			
Measured At Ring No.	18			
Deflection (mm)	38			
Percent Deflection	3			
Floor		5	5	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		5	5	
Separation (mm)	0			
Longitudinal Seams		2	2	Rings 16, 18, 20 & 22 cracked. Ring 18, 20 & 22 cracked both sides with 25mm of steel between cracks. -photo R18 cracks at 2 o'clock and 8 o'clock. Rings 1-15 not inspected.
Total No. of Cracked Rings	4			
Total No. of Rings with Two Cracked Seams	3			
Min. Remaining Steel Between Cracks (mm)	25			
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	Yes			
Coating		4	4	Superficial rust on floor. Soil side corrosion d/s end.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1429, Rise (mm): 1575, Type: SPE)				
Fish Passage Adequacy		3	3	Perched outlet.
Baffle		X	X	
(Type :)				
Waterway Adequacy		4	4	Evidence pipe is too small due to scour hole @ D/S end.
Icing (Y/N)	No			Drift and debris caught in struts.
Silting (Y/N)	Yes			
Drift (Y/N)	Yes			
Barrel General Rating		3	3	General rating raised one point on account of struts.
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		4	4	Superficial corrosion.
Heaving (mm)	100			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	300			
Scour Protection		4	4	Bevel undermined about 1m.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 150)				
Scour/Erosion		4	4	Scour hole approx 4 x 10 x 1m - photo.
Beavers (Y/N)	No			
Downstream End General Rating		4	4	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	5	Channel turns 45deg at inlet.
Bank Stability		4	5	Vertical cut bank.-Oct, 2010
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	Yes			
Channel Bottom Degrading/Aggrading	DEGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		4	5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION	2012	Remove drift from barrel.					
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	33.3/33.3	Sufficiency Rating (Last/Now) (%)	29.8/29.3	Est. Repl. Yr	2015	Maint. Reqd. (Y/N)	Yes
Special Comments for Next Inspection	Genivar currently working on design for replacement.EDC-09-Jul-2012		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Shane Hall		Previous Assistant's Name				
Next Inspection Date	05-Apr-2014		Previous Inspection Date	06-Oct-2010			
Inspection Cycle (Default) (months)	21						
Comment							