

Bridge Inspection									
Bridge File Number	02109 -1 Bridge				Form Type	PCS			
Year Built/Year Supstr	1969/1969				Lot No.	3			
Bridge or Town Name	STIRLING				Inspector Name	Jon Davies			
Located Over	KIPP COULEE, 11.9.6, WATERCRS-ST				Inspector Class	BR CLS B			
Located On	846:02 C1 3.284				Assistant Name				
Water Body Cl./Year					Assistant Class				
Navigabil. Cl./Year					Inspection Date	11-Jun-2012			
Legal Land Location	SW SEC 28 TWP 6 RGE 19 W4M				Data Entry By	Kelsey Roberts			
Longitude, Latitude	-112:30:60, 49:29:40				Data Entry Date	27-Jun-2012			
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Garry Roberts			
Contract Main. Area	CMA25				Review Date	15-Jun-2012			
Clear Roadway/Skew	8.2 /				Dept. Reviewer Name	Tim Davies			
AADT/Year	880 / 2011 (A)				Dept. Review Date	29-Jun-2012			
Road Classification	RCU-208-110				Follow-Up By				
Detour Length (km)	5								
Allowable Load (t):	Single	CS1 30 GIRDER	Semi	CS2 49 GIRDER	Train	CS3 70 GIRDER	----> On Critical Spans ---->Critical Member		
Design Loading:	HS20						----> Primary Span		

Posting Information									
Required Load Posting (t)	Single				Semi		Truck Train		
Posted Loading (t)	Single				Semi		Truck Train		
Posted:	Lane	NB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Remarks	Not Required								
Hazard Marker At Bridge (Y/N)	No								
Remarks									
Other Sign Types									

Utilities (Located at)									
Utility Attachments									
Telephone	CONDUIT ALONG WEST SIDE				Gas				
Power	3 LINE GOES E-W 40 M SOUTH				Municipal				
Others	Fibre Optics East Ditch				Problem (Y/N)	No			
Remarks									

Approach Road									
			Last	Now	Explanation of Condition				
Horizontal Alignment			7	7	Intersection at south and residences				
Vertical Alignment			8	8					
Roadway Width (m)	9.000								
Approach Bump			8	7					
Guardrail (Y/N)			Yes		SE turnout not attached from mower damage.				
Guardrail			7	3	No thriebeam				
Length (m)			22.800						
Current Standard (Y/N)			No						
Termination Type			TURNED DOWN						
Drainage			7	7					
<b>Approach Road General Rating</b>			<b>7</b>	<b>7</b>					

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : <b>HC, 1 Spans, Lengths(m): 10.1, A-Ident Number: )</b>					
<b>Special Features</b>					
Special Feature			X		
(Type : )					
Special Feature			X		
(Type : )					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
<b>Last</b>	0	0	0	0	
<b>Now</b>	0.0	0.0	0.0	0.0	
Wearing Surface			9	7	
(Material Type : <b>ACP</b> )					
(Thickness(mm) : <b>70</b> )					
Lateral Connection Problem (Y/N)		No			
Deck Top			N	N	
Deck Rideability			9	8	
Deck Joints			N	N	Paved over
Bump (Y/N)		No			
Deck Drainage			7	7	
Drains Clogged (Y/N)		No			
Curbs/Median			7	7	CORNERS SPALLED MINOR
(Curb Type : <b>Standard</b> )					
Scaling (Percent Area)		1			
Bridge Rail			6	6	SINGLE LAYER - DENTED NE CORNER
(Type : <b>STEEL FLEX BEAM</b> )					
Bridge Rail Posts			7	7	
(Type : <b>GALVANIZED POST STEEL;GALVANIZED POST STEEL</b> )					
Bridge Rail/Posts Coating			7	6	
(Type : )					
Sidewalk			X	X	
Girder Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
<b>Last</b>	0	0	0	0	
<b>Now</b>	0	0	0	0	
Girders			5	4	Wide crack in AZ of G1, G6, G9 and G10 at 1 leg only and in sound concrete. Spall in G1 inside AZ at A2. Wide crack in AZ of G2 in unsound concrete 1 leg only. Hairline shear cracks both legs of G5 at A2.
Last Complete Inspection Date		11-Jun-2012			
Cracking (Y/N)		Yes			
Spalling (Percent Area)		1			
Lift or Connector Pocket Grouted (Y/N)		Yes			
(Number Of Girders : <b>10</b> )					
<b>Span Alignment Problems</b>					
Vertical (Y/N)		No			
Horizontal (Y/N)		No			
<b>Superstructure General Rating</b>			<b>5</b>	<b>4</b>	

Substructure						
Bridge Component		Last	Now	Explanation of Condition		
<b>Abutments</b>						
(Extended Backwall Piles (Y/N) : Y)						
(Extended Backwall Piles Spacing(mm) : 1500)						
(Total Number of Caps/Corbels : 3:3)						
Bearing Seats/Caps/Corbels Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
<b>Last</b>	0	0	0	0		
<b>Now</b>	0	0	0	0		
Bearing Seats/Caps/Corbels				6	5	
(Type : TREATED TIMBER)						
(Depth(mm) : 356)						
(Width(mm) : 305)						
Backwalls/Breastwalls			7	6		Breastwall aded at south abut.
Greatest Height (m)		1.80				
Wingwalls			7	6		
(Total Number of Bearing Piles : 7:8)						
Piles Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
<b>Last</b>	0	0	0	0		
<b>Now</b>	8	0	0	0		
Piles				6	5	
Paint/Coating				X	X	
Abutment Stability				7	7	
Scour/Erosion				6	6	
<b>Piers/Bents</b>						
(Type : )						
(Total Number of Caps/Corbels : )						
Bearing Seats/Caps/Corbels Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
<b>Last</b>						
<b>Now</b>						
Bearing Seats/Caps/Corbels				X	X	
(Type : )						
(Depth(mm) : )						
(Width(mm) : )						
(Total Number of Bearing Piles : )						
Piles Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
<b>Last</b>						
<b>Now</b>						
Pier Shaft/Piles				X	X	
Greatest Height (m)						
Bracing/Struts/Sheathing				X	X	
Nose Plate				X	X	
Paint/Coating				X	X	
(Colour Description : )						
(Colour Code : )						

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Pier Stability		X	X	
Scour		X	X	
Debris (Y/N)	No			
<b>Substructure General Rating</b>		<b>6</b>	<b>5</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel</b>				
(U/S Direction : <b>E</b> )				
(D/S Direction : <b>W</b> )				
Alignment		7	7	
Bank Stability		6	6	
HWM (m below Top of Curb)	1.5			No visible HWM
Drift (Y/N)	No			
Slope Protection		6	6	
(Type : <b>RIP RAP; RIP RAP</b> )				
Guidebank/Spurs		X	X	
Adequacy of Opening		7	7	
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>6</b>	<b>6</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
OVERLAY DECK							
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
SHOTCRETE REPAIRS							
CORE TIMBER CAPS/CORBELS							
REPAIR/REPLACE TIMBER CAPS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL STRUTS							
OTHER ACTION	2012	Replace 1 section of flex beam and 1 turndown at SE.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>61.1/50.0</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>69.9/61.8</b>	Est. Repl. Yr	2025	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	11-Sep-2015		Previous Inspection Date	20-Jun-2009			
Inspection Cycle (Default) (months)	39						
Comment							