

Bridge Inspection										
Bridge File Number	06754 -1 Bridge					Form Type	TH PT PCS TT			
Year Built/Year Supstr	1949/1949					Lot No.	2			
Bridge or Town Name	CLUNY					Inspector Name	Jason Rusu			
Located Over	BOW RIVER, 2.13, WATERCRS-ST					Inspector Class	BR CLS A			
Located On	842:06 C1 22.658					Assistant Name				
Water Body Cl./Year						Assistant Class				
Navigabil. Cl./Year						Inspection Date	16-Feb-2012			
Legal Land Location	NE SEC 9 TWP 21 RGE 21 W4M					Data Entry By	Alyssa Boynton			
Longitude, Latitude	-112:50:45, 50:46:18					Data Entry Date	16-Mar-2012			
Road Authority	Alberta Transportation (AIT)					Reviewer Name	Garry Roberts			
Contract Main. Area	CMA30					Review Date	24-Feb-2012			
Clear Roadway/Skew	6.6 /					Dept. Reviewer Name	Tim Davies			
AADT/Year	1,330 / 2010 (A)					Dept. Review Date	22-Mar-2012			
Road Classification	RCU-208-110					Follow-Up By				
Detour Length (km)	50									
Allowable Load (t):	Single	CS1 27 STRINGER			Semi	CS2 49		Train	CS3 65 GIRDER	---> On Critical Spans --->Critical Member
Design Loading:	HS20									---> Primary Span

Posting Information												
Required Vert. Clearance Posting (m)				ON: 5.8m								
Posted Vertical Clearance (Y/N)				Yes								
Posted:	Lane	NB	On Bridge (m)	5.8	In Advance (Y/N)	Yes	Lane	SB	On Bridge (m)	5.8	In Advance (Y/N)	Yes
Remarks		(Measured 5.98m both ends)										
Required Load Posting (t)			Single	28	Semi		Truck Train					
Posted Loading (t)			Single		Semi		Truck Train					
Posted:	Lane	NB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No				
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No				
Remarks		Not required.										
Hazard Marker At Bridge (Y/N)		Yes										
Remarks		{Low - 1.0m; loose @ North end. July 22, 2009 UT report} Wide load damage to South signs.										
Other Sign Types		Narrow bridge, curve, max 1 truck on bridge. 55km/hr on bridge.										

Utilities (Located at)			
Utility Attachments	TELEPHONE UTILITIES-PHONE LINE		
Telephone	{South, bottom chord. July 22, 2009 UT report}	Gas	
Power		Municipal	
Others		Problem (Y/N)	No
Remarks	Telus unconnected @ NE & @ pier #2 & @ N abutment @ East. Cable is sound, conduit is disconnected.		

Approach Road				
		Last	Now	Explanation of Condition
Horizontal Alignment		4	4	Curves both ends, posted 55 km/hr on bridge. Steep grades both sides.
Vertical Alignment		5	5	
Roadway Width (m)		9.500		4 missing splice bolts at North East. Not thrie beam.
Approach Bump		7	7	
Guardrail (Y/N)		Yes		
Guardrail		5	4	
Length (m)		34.000		Not thrie beam.
Current Standard (Y/N)		No		
Termination Type		Turn Down		
Drainage		7	7	
Approach Road General Rating		4	4	

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : TH, 6 Spans, Lengths(m): 8.5-30.5-61-30.5-8.5-6.1, A-Ident Number: A0174-01;A0165-03;A0165-07)					
Special Features					
Special Feature			X		
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last					
Now	0.0	0.0	0.0	1.0	
Wearing Surface/Deck Top			4	3	Missing lag bolts at panels 1+10 split/rotten planks at panel 7.
(Material Type : UNTREATED TIMBER)					
(Plank Thickness(mm) : 75)					
(Plank Width(mm) : 305)					
Deck Rideability			5	5	
Deck Joints			X	X	
Temperature (deg. C)					
(Expansion Type :)					
(Fixed Type :)					
Gap Size (mm)		Gap Location			
Curbs/Wheel Guards			6	4	200 x 200 blocking. Plow damage at Span 1 north side.
(Curb Type : Standard)					
(Type : TREATED TIMBER)					
(Thickness(mm) : 100)					
(Width(mm) : 300)					
Bridge Rail			6	6	Triple layer. Posts are steel, blocking is timber.
(Type : GALVANIZED STEEL FLEX BEAM)					
Bridge Rail Posts/Blocking			5	5	
(Type : POST STEEL;POST STEEL)					
Bridge Rail/Posts Coating			5	5	
(Type : PAINT)					
Sidewalk			X	X	

Superstructure						
Bridge Component				Last	Now	Explanation of Condition
(Primary Span : TH, 6 Spans, Lengths(m): 8.5-30.5-61-30.5-8.5-6.1, A-Ident Number: A0174-01;A0165-03;A0165-07)						
Wide Load Damage (Y/N)	Yes				10mm notch @ rail height on U9L10W. Typical where guard rail touches truss. {50mm bends @ cross angles @ U7U7. As constructed. S4-U9L10S has 10mm notch to inside flange at rail height. July 22, 2009 UT report} 9 x 10 lines	
High Load Damage (Y/N)	No					
Top Chord			7	7		
Batter Posts			6	5		
Sway Bracings			6	6		
Diagonals			7	7		
Verticals			7	7		
Portals			7	7		
Connections			7	7		
Floor Beams			N	N		
Bottom Chord			7	7		
(No. of Stringers : 90)						
Stringer Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
Last						
Now						
Stringers			N	N		
(Type : STEEL)						
(Width(mm) : 140)						
(Depth(mm) : 380)						
(Spacing(mm) : 851)						
Paint Condition			3	3	{Rusting in splash zone approx 10% - photos. Corrosion @ truss members with pitting up to 1mm deep. Lower chord braces spreading. July 22, 2009 UT report} From past U.T report members have thick cross section- no action	
(Colour Description : BLUE)						
(Colour Code : 502-105)						
Touchup Required (Y/N)	No					
Bearings			4	4	Anchor bolts at P3 are bent.	
Temperature (deg. C)	7					
(Expansion Type : ROCKER BEARING)						
(Fixed Type : DISC & DOME BEARING)						
Functioning (Y/N)	Yes					
Sub Deck/Deck Underside			N	N	Unable to inspect from shore.	
(Material Type : TREATED TIMBER)						
(Plank Thickness(mm) : 150)						
(Plank Width(mm) : 305)						
Defects (Percent Area)	0					
Span Alignment Problems						
Vertical (Y/N)	No					
Horizontal (Y/N)	No					
Superstructure General Rating			4	4		
Superstructure						
Bridge Component				Last	Now	Explanation of Condition
(Secondary Span : PT)						
Special Features						
Special Feature				X	A165-7	
(Type :)						
Special Feature				X		
(Type :)						

Superstructure						
Bridge Component		Last	Now	Explanation of Condition		
(Secondary Span : PT)						
Wearing Surface/Deck Top Detail Ratings						
	N (%)	1 (%)	2 (%)	3 (%)		
Last						
Now	0.0	0.0	0.0	5.0		
Wearing Surface/Deck Top			4	3	Split and rotten ends of boards at panel 2 of span 3.	
(Material Type : UNTREATED TIMBER)						
(Plank Thickness(mm) : 75)						
(Plank Width(mm) : 305)						
Deck Rideability			5	5		
Deck Joints			X	X		
Temperature (deg. C)						
(Expansion Type :)						
(Fixed Type :)						
Gap Size (mm)		Gap Location				
Curbs/Wheel Guards			5	5		
(Curb Type : Standard)						
(Type : TREATED TIMBER)						
(Thickness(mm) : 100)						
(Width(mm) : 305)						
Bridge Rail			5	5	Double layer.	
(Type : GALVANIZED STEEL FLEX BEAM)						
Bridge Rail Posts/Blocking			5	5	Posts are steel, blocking is timber.	
(Type : TREATED TIMBER;TREATED TIMBER)						
Bridge Rail/Posts Coating			7	7		
(Type : GALVANIZED)						
Sidewalk			X	X		
Wide Load Damage (Y/N)		Yes			{100mm notch @ L0U1N @ wheelguard. Also top chord lattice 1 bent. U1L1S gusset S5 has minor side load dent. S5-U1L0N has 40mm long sliver at wheelguard height. (Span 5, all bays are missing hanger bolts) Feb 9th 2010 S2-L2L2 missing to bolts. S5-L1L1 has 1mm pits in bottom flange and worst case rust blisters. July 22, 2009 UT report}	
Top Chord			7	7		
Batter Posts			5	5		
Diagonals			6	6		
Verticals			6	6		
Connections			7	7		
Floor Beams			7	7		
Bottom Chord			7	7		
Lateral Bracings			7	7		
(No. of Stringers : 54;54)						
Stringer Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
Last						
Now						
Stringers			7	7		
(Type : STEEL)						
(Width(mm) : 130)						
(Depth(mm) : 305)						
(Spacing(mm) : 851)						

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Secondary Span : PT)					
Paint Condition		4	4	{Rock chips, faded bottom chord. Splice plates have heavy rust, poor or missing primer, peeling. July 22, 2009 UT report} Rusting in splash zone approx 10% on verticals @ deck level.	
(Colour Description : BLUE)					
(Colour Code : 502-105;15182)					
Touchup Required (Y/N)	No				
Bearings		5	5	Spans 4 & 5 jammed above pier 4. Anchor bolt missing from upstream end on pier #3. S3 rockers are in contracted position.	
Temperature (deg. C)	7				
(Expansion Type : ROCKER BEARING)					
(Fixed Type : DISC & DOME BEARING)					
Functioning (Y/N)	Yes				
Sub Deck/Deck Underside		7	7		
(Material Type : TREATED TIMBER)					
(Plank Thickness(mm) : 150)					
(Plank Width(mm) : 305)					
Defects (Percent Area)	0				
Span Alignment Problems					
Vertical (Y/N)	No				
Horizontal (Y/N)	No				
Superstructure General Rating		5	5		

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Secondary Span : HC)					
Special Features					
Special Feature			X		
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last					
Now	0.0	0.0	0.0	10.0	
Wearing Surface		4	3	Wide cracks between girders on span 2 - all girder connections have failed.	
(Material Type : CONVENTIONAL CHIP SEAL COAT)					
(Thickness(mm) :)					
Lateral Connection Problem (Y/N)	Yes				
Deck Top		N	N		
Deck Rideability		5	5		
Deck Joints		N	N	Chip coat covered.	
Bump (Y/N)	No				
Deck Drainage		7	7		
Drains Clogged (Y/N)	No				
Curbs/Median		7	6		
(Curb Type : Standard)					
Scaling (Percent Area)	0				

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Secondary Span : HC)					
Bridge Rail		7	6	Single layer. Wrong lap at SW.	
(Type : GALVANIZED STEEL FLEX BEAM)					
Bridge Rail Posts		7	4	Accident damage at South side of span 1. First bridge rail post and blocking has been damaged.	
(Type : GALVANIZED POST STEEL;GALVANIZED POST STEEL)					
Bridge Rail/Posts Coating		7	6		
(Type : GALVANIZED)					
Sidewalk		X	X		
Girder Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
Last					
Now	0	0	0	3	
Girders		5	3	6 girders @ span 2 have wide cracks and spalls all outside the anchorage zone.	
Last Complete Inspection Date		16-Feb-2012		11 girders have cracks or spalls in the webs, one has medium crack in AZ with crack in other web.	
Cracking (Y/N)		Yes			
Spalling (Percent Area)		10		Significant girder deflection under load - several girder connections have failed.	
Lift or Connector Pocket Grouted (Y/N)		Yes			
(Number Of Girders : 18)					
Span Alignment Problems					
Vertical (Y/N)		No			
Horizontal (Y/N)		No			
Superstructure General Rating		5	3		
Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Secondary Span : TT)					
Special Features					
Special Feature			X		
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last					
Now	0.0	0.0	0.0	1.0	
Wearing Surface/Deck Top		5	3	Loose and rotted.	
(Material Type : UNTREATED TIMBER)				Plank at center.	
(Plank Thickness(mm) : 75)				Split and broken at east.	
(Plank Width(mm) : 305)					
Deck Rideability		5	5		
Wheel Guards		6	6		
(Curb Type : Standard)					
(Type : TREATED TIMBER)					
(Thickness(mm) : 100)					
(Width(mm) : 305)					

Superstructure						
Bridge Component			Last	Now	Explanation of Condition	
(Secondary Span : TT)						
Bridge Rail			7	7	Single layer.	
(Type : GALVANIZED STEEL FLEX BEAM)						
Bridge Rail Posts			7	7		
(Type : TREATED TIMBER;TREATED TIMBER)						
Bridge Rail/Posts Coating			7	7	Lateral beams added to strengthen stringers.	
(Type : GALVANIZED)						
(No. of Stringers : 11)						
Stringer Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
Last						
Now	0	0	0	0		
Stringers			7	7	(Type : TREATED TIMBER) (Width(mm) : 200) (Depth(mm) : 510) (Spacing(mm) : 700)	
(Type : TREATED TIMBER)						
(Width(mm) : 200)						
(Depth(mm) : 510)						
(Spacing(mm) : 700)						
Sub Deck/Deck Underside			7	7	Strutted longitudinally and transversely.	
(Material Type : TREATED TIMBER)						
(Plank Thickness(mm) : 100)						
(Plank Width(mm) : 305)						
Defects (Percent Area)	1					
Span Alignment Problems						
Vertical (Y/N)	No					
Horizontal (Y/N)	No					
Superstructure General Rating			7	7		
Substructure						
Bridge Component			Last	Now	Explanation of Condition	
Abutments						
(Extended Backwall Piles (Y/N) : Y)						
(Extended Backwall Piles Spacing(mm) : 1600)						
(Total Number of Caps/Corbels : 1:3)						
Bearing Seats/Caps/Corbels Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)	{East abutment modified to accept struts. E abutment leaning West. Strutted to P5. E timber struts 150 x 340mm - photos. W abutment leaning East. Strutted to P1. July 22, 2009 UT report} Checked at South up to 20mm wide.	
Last						
Now	0	0	0	0		
Bearing Seats/Caps/Corbels			5	5		
(Type : TREATED TIMBER)						
(Depth(mm) : 305)						
(Width(mm) : 305)						
Backwalls/Breastwalls			5	5	Greatest Height (m) : 2.20	
Greatest Height (m)						
Wingwalls			5	5		
(Total Number of Bearing Piles : 8:5)						
Piles Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
Last						
Now	0	0	0	0		
Piles			5	5		
Paint/Coating			X	X		

Substructure						
Bridge Component				Last	Now	Explanation of Condition
Abutment Stability				5	5	
Scour/Erosion				6	6	
Piers/Bents						
(Type : PIER-SOLID)						
(Total Number of Caps/Corbels : 6:5:1:1:3)						
Bearing Seats/Caps/Corbels Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		Cracked & leaching under bearing areas. Exposed rebar @ pier #2 @ North face. Scaling @ tops of some @ piers #3, 4 & 5. East bearing seat at P3 spalled and cracked under through truss bearing.
Last						
Now	0	0	0	0		
Bearing Seats/Caps/Corbels			4	4		
(Type : TREATED TIMBER;CONCRETE)						
(Total Number of Bearing Piles : 5:0:0:0:0)						
Piles Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		Only piles seen are timber pier at P1. All other piers concrete.
Last						
Now	0	0	0	0		
Pier Shaft/Piles			5	5		
Greatest Height (m)	5.50					
Bracing/Struts/Sheathing				X	X	
Nose Plate				6	6	
Paint/Coating				4	4	Steel rusty. Nose plates piers #3 & #4.
(Colour Description :)						
(Colour Code :)						
Pier Stability				7	7	
Scour				N	N	Iced over.
Debris (Y/N)	No					
Substructure General Rating				4	4	
Structure Usage						
				Last	Now	Explanation of Condition
Channel						
(U/S Direction : N)						
(D/S Direction : S)						
Alignment				7	7	
Bank Stability				5	5	
HWM (m below Top of Curb)	4.0				HWM not visible.	
Drift (Y/N)	Yes					
Slope Protection				7	7	
(Type : NATURAL; NATURAL)						
Guidebank/Spurs				X	X	
Adequacy of Opening				7	7	
(Fish Compensation Measure 1 : NONE)						
(Fish Compensation Measure 2 : NONE)						
Channel General Rating				7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
RETROFIT BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
SEAL DECK							
OVERLAY DECK							
REPLACE STRIP DECK	2012	Approx 8 planks 75mm X 305mm X 2.5m					
REPLACE SUB DECK							
RESET/ PAINT BEARINGS	2012	Reset bearings, allow for design thermal movements.					
REPAINT SUPERSTRUCTURE	2016	Consider painting of bridge is to remain in service.					
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
SHOTCRETE REPAIRS							
CORE TIMBER CAPS/CORBELS							
REPAIR/REPLACE TIMBER CAPS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL STRUTS							
OTHER ACTION	2012	Recast SE bearing seat of through truss @ Pier 4.					
OTHER ACTION	2012	Add hanger bolt to span 5.					
OTHER ACTION							
OTHER ACTION	2012	S3-L2L2 fill open holes with bolts.					
OTHER ACTION	2012	Restore HC span connector pockets.					
OTHER ACTION	2012	Reset hazard markers to standard.					
OTHER ACTION	2012	Contact Telus about conduit.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	44.4/38.9	Sufficiency Rating (Last/Now) (%)	33.8/31.3	Est. Repl. Yr	2028	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				

Maintenance Reviewed By		Date		Estimated Total	0
Proposed Long-Term Strategy					
On 3-Year Program (Y/N)					
Proposed Action					
Previous Inspector's Name	Paul Carter	Previous Assistant's Name			
Next Inspection Date	16-May-2015	Previous Inspection Date	09-Feb-2010		
Inspection Cycle (Default) (months)	39				
Comment					