

Bridge Culvert Inspection								
Bridge File Number	70052 -1 Bridge Culvert				Form Type	CUL1		
Year Built	1970				Lot No.	1		
Bridge or Town Name	GIBBONS				Inspector Name	Kris Bosters		
Located Over	STURGEON RIVER, 6.65, WATERCRS-ST				Inspector Class	BR CLS A		
Located On	28A:03 R1 13.795;28A:03 L1 13.795				Assistant Name	Brian Cote		
Water Body Cl./Year					Assistant Class			
Navigabil. Cl./Year					Inspection Date	10-Apr-2012		
Legal Land Location	SW SEC 14 TWP 56 RGE 23 W4M				Data Entry By	Lisa Fairhurst		
Longitude, Latitude	-113:19:20, 53:50:23				Data Entry Date	25-Apr-2012		
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Eric Carcoux		
Contract Main. Area	CMA09				Review Date	25-Apr-2012		
Clear Roadway/Skew	30.2 / 40 deg. (RHF)				Dept. Reviewer Name	Brent Herrick		
AADT/Year	4,220 / 2011 (A)				Dept. Review Date	04-May-2012		
Road Classification	RAU-211.8-110				Follow-Up By			
Detour Length (km)	3							
Bridge Culvert Information								
Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	7600	7600	AP	194.5			ARCH
Special Features								
Special Features Comment								
Utilities (Located at)								
Utility Attachments								
Telephone	East r/w.				Gas			
Power	2 lines east r/w.				Municipal			
Others					Problem (Y/N)	No		
Remarks	Bridge plaque SW wingwall & NE corner of East headwall.							
Approach Road / Embankment								
			Last	Now	Explanation of Condition			
Horizontal Alignment			7	7	Bermed area 25m wide on east side. Located on transition from 4 lane to 2 lane. 2 lanes from the south.			
Vertical Alignment			7	7				
Roadway Width (m)	12.000							
Embankment			4	4	Upper 3:1 sideslope and lower 2:1 on the west embankment. 5m on West, 7.5m on East. Ditch gully along NW bank has developed to 1.2m wide, 1.5m deep & 30m long approx over the years. Filled with grasses - photo (Ditch gullies along NW bank. (0.6m x 0.6m x 30m long . Concrete debris @ ditch drainage in SW corner stable.			
Sideslope (___:1)	2.0							
(Height of Cover(m) : 5)								
Guardrail (Y/N)	Yes				There is minor creasing along the flexbeam guardrail.			
Approach Road / Embankment General Rating			7	7				
Upstream End								
Culvert Component			Last	Now	Explanation of Condition			
Direction			W		With steel rail at top.			
End Treatment (Concrete, Steel, Others, None)	CONCRETE							
Headwall			7	7				
Collar			X	X				
Wingwalls			6	6	Three medium cracks on SW corner. There is cracking at all wingwalls. Concrete spall SW wingwall & tie holes.			
(Shape :)								
Cutoff Wall			N	N				

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	600			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 450)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Upstream End General Rating		6	6	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 7600, Rise (mm): 7600, Type: AP)				
Barrel Last Accessible Date	23-Nov-2006			Water 1.2m deep. Viewed from ends. Shape looks good
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		7	N	
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	0			
Percent Sag				
Sidewall		N	N	(There is random vertical cracking along the sidewalls. There is leaching along some cracks - photo #1. Cracks range from hairline to medium. Most cracks are on South wall. Inspected 30m of U/S end. The rest was viewed and shape looks good. Efflorescence on South wall - photo 2.) 23Nov06
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)	0			
Percent Deflection				
Floor		N	N	Covered with water.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	N	(Grout at construction joints (circumferential seams) has deteriorated - photo #2. Rings 2 & 3 North wall.-23-Nov-2006)
Separation (mm)	25			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		X	X	
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 7600, Rise (mm): 7600, Type: AP)				
Fish Passage Adequacy		8	8	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		N	N	Rated "5" on 23/Nov/2006.
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		With steel rail on top.
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		7	7	Couple bullet holes in railing.
Collar		X	X	
Wingwalls		6	6	2 wide cracks on south wall. 1 wide crack on North wall.
(Shape :)				
Cutoff Wall		N	N	
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			Approx.
Above/Below (mm)	600			
Scour Protection		7	7	Very little rock, well grassed. Minor settlement along wingwalls. SE w/w -
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Downstream End General Rating		6	6	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	
Bank Stability		5	5	(Lots of springs & minor slides. 08/Apr/2005)
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	Yes			
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		5	5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2012	Level 2 inspection to inspect floor as per previous comments.-do if not done.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/55.6	Sufficiency Rating (Last/Now) (%)	65.9/65.8	Est. Repl. Yr	2040	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	Monitor ditch erosion. Should check floor at low water to review condition, if not already done, to avoid a disaster similar to Weed Creek on Hwy 39. Consider Level 2 inspection 08/Apr/05		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Arnold Assenheimer		Previous Assistant's Name				
Next Inspection Date	10-Jan-2014		Previous Inspection Date	22-Jun-2010			
Inspection Cycle (Default) (months)	21						
Comment							