

Bridge Culvert Inspection				
Bridge File Number	70113 -2 Bridge Culvert		Form Type	CUL1
Year Built	2006		Lot No.	4
Bridge or Town Name	MACKAY		Inspector Name	Kris Bosters
Located Over	TRIBUTARY TO POISON CREEK, 8.11.84.51.15.1, WATERCRS-ST		Inspector Class	BR CLS A
Located On	751:02 C1 16.509		Assistant Name	Brian Cote
Water Body Cl./Year			Assistant Class	BR CLS B
Navigabil. Cl./Year			Inspection Date	18-Apr-2013
Legal Land Location	NE SEC 17 TWP 55 RGE 11 W5M		Data Entry By	Lisa Fairhurst
Longitude, Latitude	-115:35:16, 53:45:12		Data Entry Date	23-Apr-2013
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Eric Carcoux
Contract Main. Area	CMA12		Review Date	21-Apr-2013
Clear Roadway/Skew	9.5 /		Dept. Reviewer Name	Brent Herrick
AADT/Year	200 / 2012 (A)		Dept. Review Date	01-May-2013
Road Classification	RCU-209-110		Follow-Up By	
Detour Length (km)	3			

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	3670	SP	53.03	152X51	3.0	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments				
Telephone	20m West.		Gas	
Power	1 line OH 20m East.		Municipal	
Others			Problem (Y/N)	No
Remarks				

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Curves to North & South. Sag curve, no passing.
Vertical Alignment		7	7	
Roadway Width (m)	10.000			
Embankment		8	8	
Sideslope (__:1)	4.0			
(Height of Cover(m) : 4.5)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		7	7	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		8	8	
Collar		8	6	Narrow transverse cracks in N collar
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		N	N	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	900			
Scour Protection		8	8	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 500)				
Scour/Erosion		8	8	
Beavers (Y/N)	No			
Upstream End General Rating		8	8	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1 , Primary Span, Location Code: MAIN , Span (mm): , Rise (mm): 3670 , Type: SP)				
Barrel Last Accessible Date	27-Jul-2006			Water too deep. Viewed from ends, shape looks good.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		N	N	
Measured Rise (mm)	3643			
Measured At Ring No.	7			
Sag (mm)	27			
Percent Sag	1			
Sidewall		N	N	
Measured Span (mm)	3652			
Measured At Ring No.	7			
Deflection (mm)	18			
Percent Deflection	1			
Floor		N	N	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	N	
Separation (mm)				
Longitudinal Seams		N	N	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)				2N Stagger
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			
Coating		8	N	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	POS			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 3670, Type: SP)				
Fish Passage Adequacy		9	9	
Baffle (Type :)		N	N	300 x 300 H-pile. Galvanized steel sections.
Waterway Adequacy		9	7	
Icing (Y/N)		No		
Siltting (Y/N)		No		
Drift (Y/N)		No		
Barrel General Rating		N	N	G.R. was "9" from July 27, 2006.
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)		STEEL		
Headwall		X	X	
Collar		X	X	
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	
Bevel End		8	8	
Heaving (mm)		0		
Invert Above/Below Stream Bed		BELOW		
Above/Below (mm)		900		
Scour Protection (Type : RIP RAP) (Avg. Rock Size(mm) : 500)		8	8	
Scour/Erosion		8	8	
Beavers (Y/N)		No		
Downstream End General Rating		8	8	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		8	4	100 degree bend d/s causing re-circulation pool.
Bank Stability		9	4	Sloughing bank d/s
HWM (m below Top of Culvert)				No HWM visible.
Drift (Y/N)		No		
Channel Bottom Degrading/Aggrading		DEGRADING		
Beavers (Y/N)		Yes		
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		8	4	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/55.6	Sufficiency Rating (Last/Now) (%)	76.4/67.6	Est. Repl. Yr	2055	Maint. Req. (Y/N)	No
Special Comments for Next Inspection	Monitor d/s erosion		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Kris Bosters		Previous Assistant's Name	Sara Wadlow			
Next Inspection Date	18-Jul-2016		Previous Inspection Date	19-Nov-2009			
Inspection Cycle (Default) (months)	39						
Comment							