

Bridge Culvert Inspection			
Bridge File Number	70579 -1 Bridge Culvert	Form Type	CUL1
Year Built	1974	Lot No.	1
Bridge or Town Name	SHERWOOD PAR	Inspector Name	Kris Bosters
Located Over	216:04 L1 1.766;216:04 R1 1.782;UTIL-UN, OVER UT	Inspector Class	BR CLS A
Located On	216:04 L1 1.766;216:04 R1 1.782	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	05-Apr-2011
Legal Land Location	NW SEC 4 TWP 53 RGE 23 W4M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-113:20:39, 53:33:20	Data Entry Date	18-Apr-2011
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Arnold Assenheimer
Contract Main. Area	CMA09	Review Date	11-Apr-2011
Clear Roadway/Skew	43.4 /	Dept. Reviewer Name	Brent Herrick
AADT/Year	42,840 / 2009 (A)	Dept. Review Date	19-Apr-2011
Road Classification	RAU-213.4-120	Follow-Up By	
Detour Length (km)	1		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	2590	1880	RPP	123.7	152X51	3.5	PIPE ARCH
Special Features								
Special Features Comment	File tag @ u/s end 12 o'clock.							

Posting Information

Required Vert. Clearance Posting (m)	UNDER: 216 L1 4.6m, 216 R1 4.6m									
Posted Vertical Clearance (Y/N)										
Posted:	Lane	NB	On Bridge (m)	In Advance (Y/N)	Lane	SB	On Bridge (m)	In Advance (Y/N)		
Remarks	Not required.									

Utilities (Located at)

Utility Attachments	UNKNOWN UTILITY									
Telephone	20m south, runs East-West.				Gas	15m south, runs East-West.				
Power	7 wires 30m east, runs North-South.				Municipal					
Others	Light standards.				Problem (Y/N)	No				
Remarks										

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		8	8	Structure located 30m North of BF 77416. 3 lanes NB, 2 lanes SB, on ramp.
Vertical Alignment		9	8	
Roadway Width (m)	43.400			
Embankment		8	8	2.5 @ bottom, 5:1 @ top.
Sideslope (__:1)	2.5			
(Height of Cover(m) : 2.3)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		8	8	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		E		Acts as a drainage pipe as well.
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		7	7	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2590, Rise (mm): 1880, Type: RPP)				
Barrel Last Accessible Date	05-Apr-2011			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		4	N	U/S - 1880, D/S - 1865. Ring 27 missing bolt.
Measured Rise (mm)	1733			tOO MUCH ICE TO MEASURE RISE.
Measured At Ring No.	12			
Sag (mm)	147			
Percent Sag	8			
Sidewall		2	2	Small tear in North sidewall ring 1. U/S - 2549, ring 9 - 2627, D/S - 2579. Construction damage/modifications ring 14, South wall. Sidewall rating lowered due to cracks.
Measured Span (mm)	2676			
Measured At Ring No.	12			
Deflection (mm)	86			
Percent Deflection	3			
Floor		7	7	Lots of debris.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	Missing bolt ring 12.
Separation (mm)	0			
Longitudinal Seams		2	2	Cracked rings @ 9, 10, 11, 12, 13, 14, 15, 16, 19, 21, 23, 24, 25, & 26 3 o'clock. Rings 9 & 12 have 55mm steel left. Ring 14, 23 & 25 have 45mm steel left - photo.
Total No. of Cracked Rings	14			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	45			Sidewall not staggered, roof is.
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2590, Rise (mm): 1880, Type: RPP)				
Coating		4	4	Rusting at 10% bolt hole locations.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	Iced about 500mm at u/s end. Lots of garbage and debris in pipe.
Icing (Y/N)	Yes			
Silting (Y/N)	Yes			
Drift (Y/N)	No			
Barrel General Rating		2	2	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		7	7	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	
Structure Usage				
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		X	X	
Roadway Surface		X	X	
(Type :)				
Icing (Y/N)	No			
Traffic Safety Features		X	X	
Type				

Structure Usage				
		Last	Now	Explanation of Condition
Lighting		X	X	
Barrel Leakage (Y/N)	No			
Drainage		7	7	
Structure In Use (Y/N)	No			
Grade Separation General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2011	Assess options plus Level 2 inspection, monitor, repair or replace options. Pipe does not appear to be used, possibly some drainage. Could be grouted in or lined with small culvert.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	22.2/22.2	Sufficiency Rating (Last/Now) (%)	44.3/44.1	Est. Repl. Yr	2012	Maint. Req'd. (Y/N)	Yes
Special Comments for Next Inspection	Pipe is 40m North of BF 77416. Monitor cracks.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Shane Hall		Previous Assistant's Name				
Next Inspection Date	05-Jan-2013		Previous Inspection Date	24-Jun-2009			
Inspection Cycle (Default) (months)	21						
Comment							