

Bridge Inspection											
Bridge File Number	70789 -1 Bridge				Form Type	SG					
Year Built/Year Supstr	1985/1985				Lot No.	4					
Bridge or Town Name	G BAYNTON BR				Inspector Name	Jason Saly					
Located Over	NORTH SASKATCHEWAN RIVER, 6, WATERCRS-ST				Inspector Class	BR CLS A					
Located On	17:08 C1 33.967				Assistant Name						
Water Body Cl./Year					Assistant Class						
Navigabil. Cl./Year					Inspection Date	27-Jun-2012					
Legal Land Location	SE SEC 25 TWP 53 RGE 1 W4M				Data Entry By	Marcia Chavez					
Longitude, Latitude	-110:00:39, 53:36:13				Data Entry Date	13-Jul-2012					
Road Authority	Alberta Transportation (AIT)				Reviewer Name	John O'Brien					
Contract Main. Area	UNDEFINED CMA				Review Date	05-Jul-2012					
Clear Roadway/Skew	9 /				Dept. Reviewer Name	Andrew Smikles					
AADT/Year	1,820 / 2011 (A)				Dept. Review Date	19-Jul-2012					
Road Classification	RAU-211.8-110				Follow-Up By						
Detour Length (km)	5										
Allowable Load (t):	Single	CS1 28			Semi	CS2 49			Train	CS3 62	----> On Critical Spans ---->Critical Member
Design Loading:	MS230									----> Primary Span	

Posting Information									
Required Load Posting (t)	Single				Semi		Truck Train		
Posted Loading (t)	Single				Semi		Truck Train		
Posted:	Lane	NB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Remarks	Not required.								
Hazard Marker At Bridge (Y/N)	Yes								
Remarks	Not to std. - too low.								
Other Sign Types	Bridge name sign "George F. Baynton". River ID.								

Utilities (Located at)										
Utility Attachments										
Telephone	SGT cables buried @ both abut, E side.				Gas					
Power					Municipal					
Others	Flow gauges both abuts.				Problem (Y/N)	No				
Remarks										

Approach Road									
		Last	Now	Explanation of Condition					
Horizontal Alignment		6	6	Curves at top of both river banks. Steep grades in both directions of bridge. (Max. 8% at S).					
Vertical Alignment		5	5						
Roadway Width (m)	13.900			Insufficient lgth.					
Approach Bump		7	7						
Guardrail (Y/N)	Yes								
Guardrail		7	6						
Length (m)	26.600								
Current Standard (Y/N)	No								
Termination Type	FLARE W. BULB								
Drainage		6	6						
Approach Road General Rating		5	5						

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : WG, 6 Spans, Lengths(m): 49-63-84-84-84-70, A-Ident Number: A0999-03)					
Special Features					
Special Feature			X		
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last	0	0	0	0	
Now	0.0	0.0	0.0	0.0	
Wearing Surface			7	7	H2 (150-200A)ACP, covered by chip seal coat wearing surface.
(Material Type : ACP - CONVENTIONAL CHIP SEAL COAT)					
(Thickness(mm) : 90)					
Deck Top			N	N	
Deck Rideability			9	8	
Deck Joints			4	4	Plumbing allows water onto backwalls & seats at all 4 corners. Rust staining on abut conc. seats.
Temperature (deg. C)		16			
(Expansion Type : FINGER PLATES)					
(Fixed Type :)					
Gap Size (mm)		Gap Location			
161		N. abut			
197		S. abut			
Deck Drainage			7	4	Due to jnt leakage.
Drains Clogged (Y/N)		No			
Curbs/Median			7	6	Curbs only 140mm high. Drip groove on outside of curbs allows water to drain on girders. Transv. cracking.
(Curb Type : Standard)					
Scaling (Percent Area)		0			
Bridge Rail			8	7	
(Type : GALVANIZED STEEL BRIDGE TUBE)					
Bridge Rail Posts			7	7	
(Type : GALVANIZED POST STEEL; GALVANIZED POST STEEL)					
Bridge Rail/Posts Coating			6	6	
(Type : GALVANIZED)					
Sidewalk			X	X	
Girder/Beam					
Cover Plate			X	X	Bottom flange slight sag - typ.
Flange			6	6	
Web			8	8	
Stiffeners			8	8	
Splice			8	8	
Weld			8	8	
Diaphragms/Cross Frame			8	8	

Superstructure				
Bridge Component		Last	Now	Explanation of Condition
(Primary Span : WG, 6 Spans, Lengths(m): 49-63-84-84-84-70, A-Ident Number: A0999-03)				
Paint Condition		8	8	Weathering steel. Rusting uneven.
(Colour Description :)				
(Colour Code :)				
Touchup Required (Y/N)	No			
Bearings		8	7	All pier bearings inaccessible - viewed with binoculars.
Temperature (deg. C)	16			
(Expansion Type :)				
(Fixed Type :)				
Coating Adequate (Y/N)	Yes			
Functioning (Y/N)	Yes			
Deck Underside		8	8	
Stains (Percent Area)	0			
Span Alignment Problems				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
Superstructure General Rating		6	6	
Substructure				
Bridge Component		Last	Now	Explanation of Condition
Abutments				
Bearing Seats/Caps		8	7	
(Type : CONCRETE)				
Backwalls/Breastwalls		8	7	
Wingwalls		8	7	
Piles		N	N	
Paint/Coating		6	6	
Abutment Stability		5	5	
Scour/Erosion		5	5	
Piers/Bents				
(Type : PIER-SOLID)				Middle piers not accessible.
Bearing Seats/Caps		8	8	
(Type : CONCRETE)				As seen from bridge deck.
(Total Number of Bearing Piles : 0:0:0:0:0)				
Pier Shaft/Piles		8	8	
Bracing/Struts/Sheathing		X	X	
Nose Plate		X	X	
Paint/Coating		X	X	
(Colour Description :)				
(Colour Code :)				
Pier Stability		8	8	
Scour		6	N	
Debris (Y/N)	No			
Substructure General Rating		5	5	

Structure Usage				
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : W)				
(D/S Direction : E)				
Alignment		8	8	
Bank Stability		8	8	
HWM (m below Top of Curb)				HWM not visible.
Drift (Y/N)	No			
Slope Protection		7	7	
(Type : NATURAL; NATURAL)				
Guidebank/Spurs		8	8	Riprap armour on guidebanks, class 3.
Adequacy of Opening		8	8	
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
GALVANIZE/PAINT BRIDGE RAIL							
RETROFIT BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
SEAL DECK							
OVERLAY DECK							
REPAIR/REPLACE DECK JOINTS							
RESET/ PAINT BEARINGS							
REPAINT SUPERSTRUCTURE							
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
SHOTCRETE REPAIRS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	61.1/61.1	Sufficiency Rating (Last/Now) (%)	55.2/54.6	Est. Repl. Yr	2060	Maint. Req. (Y/N)	No
Special Comments for Next Inspection	Bridge is responsibility of Sask. Dept of Hwys.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Owen Salava		Previous Assistant's Name				
Next Inspection Date	27-Mar-2014		Previous Inspection Date	01-Sep-2010			
Inspection Cycle (Default) (months)	21						
Comment							