

Bridge Culvert Inspection				
Bridge File Number	70876 E-1 Bridge Culvert		Form Type	CUL1
Year Built	1954		Lot No.	2
Bridge or Town Name	OBED		Inspector Name	Shane Hall
Located Over	TRIBUTARY TO ATHABASCA RIVER, 8.11.128, WATERCRS-ST		Inspector Class	BR CLS A
Located On	16:02 R1 46.974		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	11-Aug-2012
Legal Land Location	SW SEC 21 TWP 52 RGE 23 W5M		Data Entry By	Theresa Lacusta
Longitude, Latitude	-117:19:55, 53:30:08		Data Entry Date	10-Sep-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Eric Carcoux
Contract Main. Area	CMA13		Review Date	31-Aug-2012
Clear Roadway/Skew	17.3 /		Dept. Reviewer Name	Brent Herrick
AADT/Year	5,630 / 2011 (A)		Dept. Review Date	18-Sep-2012
Road Classification	RAD-412.4-120		Follow-Up By	
Detour Length (km)	1			

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	1724	1901	SPE	55	152X51		ELLIPSE
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	North r/w	Gas	
Power		Municipal	
Others		Problem (Y/N)	No
Remarks	File tag on South (U/S).		

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	7	7	Obed Mountain road. Entrance 100m West. Long sag curve.
Vertical Alignment	7	7	
Roadway Width (m)	12.500		
Embankment	7	7	
Sideslope (__:1)	2.5		
(Height of Cover(m) : 6)			
Guardrail (Y/N)	No		
Approach Road / Embankment General Rating	7	7	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	S		
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape :)			
Cutoff Wall	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		6	5	Seam in bevel cusping.
Heaving (mm)	300			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		7	7	
Beavers (Y/N)	Yes			Large beaver dam 5 m U/S approx 2.5m high.
Upstream End General Rating		6	5	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1724, Rise (mm): 1901, Type: SPE)				
Barrel Last Accessible Date	11-Aug-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		5	5	Est rocks on floor
Measured Rise (mm)				
Measured At Ring No.	11			
Sag (mm)	130			
Percent Sag	7			
Sidewall		5	4	
Measured Span (mm)	1862			
Measured At Ring No.	11			
Deflection (mm)	138			
Percent Deflection	8			
Floor		N	N	Rock covered (up to 500 mm deep).
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	0			
Longitudinal Seams		6	6	3 U/S sections have poor nesting, up to 18mm gap.
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				1N stagger.
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	Yes			
Coating		6	6	Superficial rust lower half.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	Yes			Ponding due to negative camber. Uplift at D/S end holding water.

Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1724, Rise (mm): 1901, Type: SPE)					
Fish Passage Adequacy		4	4	Hanging outlet. (However fish were seen in the culvert. 12/July/2005)	
Baffle		X	X		
(Type :)					
Waterway Adequacy		6	6	Rock throughout barrel. Silt @ d.s end.	
Icing (Y/N)	No				
Silting (Y/N)	Yes				
Drift (Y/N)	Yes				
Barrel General Rating		5	4		
Downstream End					
Culvert Component		Last	Now	Explanation of Condition	
Direction		N			
End Treatment (Concrete, Steel, Others, None)	STEEL				
Headwall		X	X		
Collar		X	X		
Wingwalls		X	X		
(Shape :)					
Cutoff Wall		X	X		
Bevel End		6	6	Bevel twisting to the West. Scouring bevel projectiong from fill.	
Heaving (mm)	300				
Invert Above/Below Stream Bed	ABOVE				
Above/Below (mm)	500				
Scour Protection		3	3	Bevel undermined for 1m.-photo	
(Type : RIP RAP)					
(Avg. Rock Size(mm) : 200)					
Scour/Erosion		3	3		
Beavers (Y/N)	No				
Downstream End General Rating		3	3		
Structure Usage					
		Last	Now	Explanation of Condition	
Channel (U/S and D/S)					
Alignment		7	7		
Bank Stability		7	7		
HWM (m below Top of Culvert)				HWM not visible.	
Drift (Y/N)	Yes				
Channel Bottom Degrading/Aggrading	DEGRADING			Deg d/s. Dam u/s.	
Beavers (Y/N)	Yes				
(Fish Compensation Measure 1 : NONE)					
(Fish Compensation Measure 2 : NONE)					
Channel General Rating		7	7		

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP	2013	Additional riprap D/S 5m3.					
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/44.4	Sufficiency Rating (Last/Now) (%)	51.4/45.4	Est. Repl. Yr	2030	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Eric Carcoux		Previous Assistant's Name				
Next Inspection Date	11-May-2014		Previous Inspection Date	16-Sep-2010			
Inspection Cycle (Default) (months)	21						
Comment							