

Bridge Culvert Inspection				
Bridge File Number	70884 -1 Bridge Culvert		Form Type	CUL1
Year Built	1955		Lot No.	1
Bridge or Town Name	HINTON		Inspector Name	Shane Hall
Located Over	HAPPY CREEK, 8.11.140, WATERCRS-ST		Inspector Class	BR CLS A
Located On	16:02 R1 25.082;16:02 L1 25.092		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	06-Jul-2012
Legal Land Location	NW SEC 10 TWP 51 RGE 25 W5M		Data Entry By	Theresa Lacusta
Longitude, Latitude	-117:36:06, 53:23:44		Data Entry Date	10-Sep-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Eric Carcoux
Contract Main. Area	CMA13		Review Date	20-Aug-2012
Clear Roadway/Skew	15.2 /		Dept. Reviewer Name	Brent Herrick
AADT/Year	8,730 / 2011 (A)		Dept. Review Date	18-Sep-2012
Road Classification	RAD-412.4-120		Follow-Up By	
Detour Length (km)	1			

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	-	1800	SP	45.7			ROUND
Special Features		DROP STRUCTURE, BARREL ELBOW						
Special Features Comment								

Utilities (Located at)				
Utility Attachments				
Telephone	North & South r/w		Gas	
Power	Street light.		Municipal	Yes
Others			Problem (Y/N)	No
Remarks	All types of utilities cross pipe.			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	22m Hwy 16, East S.R. 8.7 Est - pipe crosses 4 lanes of hwy 16 and 2 service roads.
Vertical Alignment		8	8	
Roadway Width (m)	30.700			
Embankment		5	5	(Ditch gully down North sideslope (photo). North end Towns responsibility.
Sideslope (_ :1)	3.0			
(Height of Cover(m) : 8)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		7	7	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		Grizzly - grating was installed at culvert entrance. Grating mostly destroyed/removed.-photo Located West of Integra Tire.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		6	N	Bevel not connected for part of floor.-15-Sep-2010
Heaving (mm)	100			
Invert Above/Below Stream Bed	BELOW			Small logs & garbage has collected against grate and above pipe. Pipe not safely accessible due to steel/sharp edges and partial blockage.
Above/Below (mm)	500			
Scour Protection		6	6	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		6	6	
Beavers (Y/N)	No			
Upstream End General Rating		6	6	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1800, Type: SP)				
Barrel Last Accessible Date	15-Sep-2010			D/S of drop structure insp. July 6, 2012. U/S of drop not accessible due to unsafe access.
Special Features				
Special Feature		3	N	Floor buckling.
(Type : DROP STRUCTURE)				Too much water-not accessible. Large log caught in drop structure.-photo
Special Feature		5	N	
(Type : BARREL ELBOW)				
Roof		2	N	10m d/s of drop structure.
Measured Rise (mm)	1415			Span measurement confirmed at same location.
Measured At Ring No.				
Sag (mm)	255			
Percent Sag	14			
Sidewall		3	N	10m d/s of drop structure.
Measured Span (mm)	2055			Span measurement confirmed at same location.
Measured At Ring No.				
Deflection (mm)	255			
Percent Deflection	14			
Floor		3	N	Floor buckling.
Bulge (mm)	400			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		5	N	
Separation (mm)	25			
Longitudinal Seams		5	N	Few missing bolts in long S. circum. seams.
Total No. of Cracked Rings	0			1N stagger.
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	Yes			
Coating		6	N	Minor superficial rust on floor of SPCSP and some spots of CSP.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1800, Type: SP)				
Fish Passage Adequacy		X	3	Drop structure
Baffle		X	X	
(Type :)				
Waterway Adequacy		5	5	Debris at inlet.
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	Yes			
Barrel General Rating		2	2	GR carried over.
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		Located W of Petro Canada.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		5	5	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		5	5	& riprap
(Type : CONCRETE)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Downstream End General Rating		5	5	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	Yes			
Channel Bottom Degrading/Aggrading	DEGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION	2013	From u/s end.					
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2013	Complete Assessment incl. Level 2 barrel inspection. Use 2 inspectors.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	22.2/22.2	Sufficiency Rating (Last/Now) (%)	40.7/33.1	Est. Repl. Yr	2015	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	Tranp. (Mike Botros) advised of low rating.-04-Oct-2010 300m length is approximate and is for the entire structure. Rizwan advised of low rating-29-Aug-2012		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Eric Carcoux		Previous Assistant's Name				
Next Inspection Date	06-Apr-2014		Previous Inspection Date	15-Sep-2010			
Inspection Cycle (Default) (months)	21						
Comment							