

Bridge Culvert Inspection				
Bridge File Number	70903 -1 Bridge Culvert		Form Type	CUL1
Year Built	1981		Lot No.	1
Bridge or Town Name	WETASKIWIN		Inspector Name	Owen Salava
Located Over	TRIBUTARY TO WEILLER CREEK, 5.47.2.1, WATERCRS-ST		Inspector Class	BR CLS A
Located On	13:10 C1 1.137		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	27-Jun-2012
Legal Land Location	SE SEC 30 TWP 46 RGE 23 W4M		Data Entry By	Marcia Chavez
Longitude, Latitude	-113:19:32, 52:59:30		Data Entry Date	15-Jul-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	John O'Brien
Contract Main. Area	CMA17		Review Date	05-Jul-2012
Clear Roadway/Skew	14.4 / 40 deg. (RHF)		Dept. Reviewer Name	Andrew Smikles
AADT/Year	3,820 / 2011 (A)		Dept. Review Date	19-Jul-2012
Road Classification	RAU-213.4-120		Follow-Up By	
Detour Length (km)	3			

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	-	2314	SP	57.9	152X51		ROUND
Special Features		VERT STEEL STRUTS						
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone		Gas	
Power	3 wire o/h, S r/w.	Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	In tangent between two curves.
Vertical Alignment		9	9	
Roadway Width (m)	14.400			
Embankment		7	7	Goes to 2:1 at pipe at south
Sideslope (__:1)	3.0			
(Height of Cover(m) : 3)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		7	7	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	7	
Heaving (mm)	150			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		5	5	Concrete filled sand bags.
(Type : CONCRETE)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		5	5	Minor erosion starting beside bevel.
Beavers (Y/N)	No			
Upstream End General Rating		5	5	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm):				, Rise (mm): 2314, Type: SP)
Barrel Last Accessible Date	30-Aug-2010			Viewed from ends; flow rate high; depth >0.6m at both ends, deepening at middle.
Special Features				
Special Feature		7	N	HSS steel, strut at cracked seam rings only.
(Type : VERT STEEL STRUTS)				
Special Feature				
(Type :)				
Roof		N	X	(Isolated perforations forming in R8 - photo. 12Feb2009).
Measured Rise (mm)	2410			
Measured At Ring No.	8			
Sag (mm)	142			
Percent Sag	6			
Sidewall		3	X	(150mm hole in R5 at 2 o'clock. Construction dents east S/W R4. 30Aug2010).
Measured Span (mm)	2611			
Measured At Ring No.	8			
Deflection (mm)	297			
Percent Deflection	13			
Floor		N	N	Water.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	N	
Separation (mm)	0			
Longitudinal Seams		N	N	(R8 at E, has 64 mm of steel and cracks both sides - 20 holes at E. R9 is cracked at E side - 16 hole. R8 has 2 cracks at W sidewall, 100 mm below bolts 60mm steel remaining at 6 corrugations. 12Feb2009).
Total No. of Cracked Rings	2			
Total No. of Rings with Two Cracked Seams	1			
Min. Remaining Steel Between Cracks (mm)	60			
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		3	N	(White stains through roof seams under sideslopes. Corrosion with extensive pitting at D/S longitudinal seams. - photo Isolated perforations in sidewall (photo). 30Aug2010).
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2314, Type: SP)				
Ponding (Y/N)	No			
Fish Passage Adequacy		5	5	
Baffle		X	X	
(Type :)				
Waterway Adequacy		5	5	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		3	2	Based on previous comments with cracks on both sides; sidewall & longit. seams rate 2.

Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		6	6	Concrete sand bags.
(Type : CONCRETE)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		6	6	
Beavers (Y/N)	No			
Downstream End General Rating		6	6	

Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	Train bridge 15m D/S
Bank Stability		7	7	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				Unknown
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations										
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #				
SHOTCRETE REPAIRS										
PLACE ADDITIONAL RIP RAP										
REMOVE DRIFT ACCUMULATION										
INSTALL CONCRETE/STEEL LINING										
INSTALL STRUTS										
INSTALL CONCRETE COLLAR/CUTOFF										
REPAIR SEAMS										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
Structural Condition Rating (Last/Now) (%)	33.3/22.2	Sufficiency Rating (Last/Now) (%)	44.6/39.6	Est. Repl. Yr	2015	Maint. Req. (Y/N)	No			
Special Comments for Next Inspection	Monitor corrosion & roof perforations - getting worse. Check struts in fall for R=2 sidewall & seam rating. Emailed LRA toDonald Saunders 05Jul2012.		Department Comments							
Maintenance Reviewed By	Date		Estimated Total	0						
Proposed Long-Term Strategy	2004.04.09 Monitor normal BIM. Estimated replacement year 2020.									
On 3-Year Program (Y/N)										
Proposed Action										
Previous Inspector's Name	Owen Salava	Previous Assistant's Name								
Next Inspection Date	27-Mar-2014	Previous Inspection Date	30-Aug-2010							
Inspection Cycle (Default) (months)	21									
Comment										

Maintenance Recommendations

Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #
SHOTCRETE REPAIRS						
PLACE ADDITIONAL RIP RAP						
REMOVE DRIFT ACCUMULATION						
INSTALL CONCRETE/STEEL LINING						
INSTALL STRUTS						
INSTALL CONCRETE COLLAR/CUTOFF						
REPAIR SEAMS						
OTHER ACTION						
OTHER ACTION						
OTHER ACTION						
OTHER ACTION						
Structural Condition Rating (Last/Now) (%)	33.3/22.2	Sufficiency Rating (Last/Now) (%)	44.6/39.6	Est. Repl. Yr	2015	Maint. Req. (Y/N) No
Special Comments for Next Inspection	Monitor corrosion & roof perforations - getting worse. Check struts in fall for R=2 sidewall & seam rating. Emailed LRA to Donald Saunders 05Jul2012.		Department Comments	Tentatively programmed to be replaced in 2022. AS		
Maintenance Reviewed By	Andrew Smikles	Date	23-Aug-2012	Estimated Total	0	
Proposed Long-Term Strategy	2004.04.09 Monitor normal BIM. Estimated replacement year 2020.					
On 3-Year Program (Y/N)						
Proposed Action						
Previous Inspector's Name	Owen Salava	Previous Assistant's Name				
Next Inspection Date	27-Mar-2014	Previous Inspection Date	30-Aug-2010			
Inspection Cycle (Default) (months)	21					
Comment						