

Bridge Culvert Inspection				
Bridge File Number	71327 -1 Bridge Culvert		Form Type	CULM
Year Built	1969		Lot No.	2
Bridge or Town Name	ISLAND LAKE		Inspector Name	Todd Warshawski
Located Over	2ND ORDER TRIBUTARY TO ATHABASCA RIVER, 8.11.75.1, WATERCRS-ST		Inspector Class	BR CLS B
Located On	2:44 C1 6.692		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	29-Mar-2013
Legal Land Location	NW SEC 19 TWP 69 RGE 24 W4M		Data Entry By	Theresa Lacusta
Longitude, Latitude	-113:39:32, 54:59:27		Data Entry Date	15-Apr-2013
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Eric Carcoux
Contract Main. Area	CMA10		Review Date	03-Apr-2013
Clear Roadway/Skew	10.3 /		Dept. Reviewer Name	Brent Herrick
AADT/Year	560 / 2012 (A)		Dept. Review Date	23-Apr-2013
Road Classification	RAU-211.8-110		Follow-Up By	
Detour Length (km)	50			

Bridge Culvert Information

Number of Culverts		2						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1200	MP	30	68X13	2.8	ROUND
2	MAIN	-	1200	MP	30	68X13	2.8	ROUND
Special Features								
Special Features Comment		Barrel lengths not confirmed, it is over 30m.						

Utilities (Located at)

Utility Attachments				
Telephone	West r/w.		Gas	
Power	2 wires West r/w.		Municipal	
Others			Problem (Y/N)	No
Remarks				

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Park access to North. Limited sight distance to south due to crest. No passing. Service road runs parallel to Hwy on west side.
Vertical Alignment		6	6	
Roadway Width (m)	10.300			
Embankment		7	7	
Sideslope (__:1)	3.0			
(Height of Cover(m) : 3.5)				
Guardrail (Y/N)	Yes			East side only.
Approach Road / Embankment General Rating		6	6	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Direction		E		North pipe.
End Treatment (Concrete, Steel, Others, None)		NONE		
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Cutoff Wall		X	X	
Bevel End		X	X	Removed during beaver dam removal.-Jul, 2011
Heaving (mm)				Water covered
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	700			
Scour Protection		5	N	Snow covered
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		5	N	Snow covered
Beavers (Y/N)	No			
Upstream End General Rating		5	5	GR carried fwd from Jul, 2011.
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Barrel Last Accessible Date	14-Sep-1995			Barrel not accessible, ice 0.3 from crown.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		N	N	(8% deflection, sag est. 29/Mar/2006) Upstream end damaged from beaver dam removal. Damage to inlet from beaver dam removal.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	100			
Percent Sag	8			
Sidewall		N	4	Upstream barrel is unravelling due to bevel removal.
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)	100			
Percent Deflection	8			
Floor		N	N	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	N	
Separation (mm)				
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		5	N	Pitting rust most of barrel.-Jul, 2011
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			

Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)					
Camber POS/ZERO/NEG	NEG				
Ponding (Y/N)					
Fish Passage Adequacy		5	N		
Baffle		N	N		
(Type :)					
Waterway Adequacy		5	N	Ice 0.3m from crown	
Icing (Y/N)	Yes				
Silting (Y/N)	No				
Drift (Y/N)	Yes				
Barrel General Rating		4	4	G.R. was "4" from 14/Sept/1995.	
Downstream End					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 1, Span Type: Primary Span)					
Direction		W		North pipe.	
End Treatment (Concrete, Steel, Others, None)	STEEL				
Headwall		X	X		
Collar		X	X		
Wingwalls		X	X		
(Shape :)					
Cutoff Wall		X	X		
Bevel End		5	N	Buried in snow/ice.	
Heaving (mm)	0				
Invert Above/Below Stream Bed	BELOW				
Above/Below (mm)	700				
Scour Protection		6	N	Snow covered	
(Type : NATURAL)					
(Avg. Rock Size(mm) :)					
Scour/Erosion		6	N		
Beavers (Y/N)	No				
Downstream End General Rating		5	5	GR carried fwd from Jul, 2011	
Upstream End					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 2, Span Type: Secondary Span)					
Direction		E		South pipe.	
End Treatment (Concrete, Steel, Others, None)	NONE				
Headwall		X	X		
Collar		X	X		
Wingwalls		X	X		
(Shape :)					
Cutoff Wall		X	X		

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Bevel End		X	X	Removed with beaver dam removal.
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		5	N	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		5	N	
Beavers (Y/N)	Yes			
Upstream End General Rating		5	5	GR carried fwd from Jul, 2011.
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Barrel Last Accessible Date	29-Mar-2013			
Special Features				
Special Feature				Only accessible for 5m u/s & d/s. Could not confirm previous measurements.
(Type :)				
Special Feature				
(Type :)				
Roof		4	N	Could not measure rise due to ice on floor.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall		4	N	
Measured Span (mm)	1308			
Measured At Ring No.				
Deflection (mm)	108			
Percent Deflection	9			
Floor		N	N	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	N	
Separation (mm)				
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		4	4	Pitting rust lower 1/3.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		5	5	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	Yes			
Barrel General Rating		4	4	GR carried fwd. 14-Sep-1995
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Direction		W		South pipe
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		5	N	Bevel unsupported for 800mm. -Jul, 2011 Snow covered
Heaving (mm)	50			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	400			
Scour Protection		4	N	No rock in haunch and streambed areas. -Jul, 2011
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		4	N	400 mm x 1.5 x 2.0m long scour hole off end of bevel. -Jul, 2011
Beavers (Y/N)	No			
Downstream End General Rating		4	4	GR carried fwd from Jul, 2011.
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		8	8	
Bank Stability		7	7	Low banks, grass & marsh area.
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	Yes			
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	Yes			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	8	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2013	Trim off unraveling/damaged upstream barrel ends.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	44.4/44.4	Sufficiency Rating (Last/Now) (%)	47.1/47.2	Est. Repl. Yr	2020	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Kris Bosters		Previous Assistant's Name				
Next Inspection Date	29-Dec-2014		Previous Inspection Date	07-Jul-2011			
Inspection Cycle (Default) (months)	21						
Comment							