

Bridge Inspection									
Bridge File Number	71580 -1 Bridge				Form Type	PCS			
Year Built/Year Supstr	1983/1983				Lot No.	2			
Bridge or Town Name	ROCHESTER				Inspector Name	Todd Warshawski			
Located Over	TRIBUTARY TO DAPP CK, 8.11.84.15.2, WATERCRS-ST				Inspector Class	BR CLS B			
Located On	661:08 C1 20.694				Assistant Name				
Water Body Cl./Year					Assistant Class				
Navigabil. Cl./Year					Inspection Date	27-May-2010			
Legal Land Location	SE SEC 20 TWP 62 RGE 24 W4M				Data Entry By	Theresa Lacusta			
Longitude, Latitude	-113:33:38, 54:22:13				Data Entry Date	21-Jun-2010			
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Arnold Assenheimer			
Contract Main. Area	CMA10				Review Date	09-Jun-2010			
Clear Roadway/Skew	10 /				Dept. Reviewer Name	Brent Herrick			
AADT/Year	300 / 2009 (A)				Dept. Review Date	29-Jun-2010			
Road Classification	RCU-209-110				Follow-Up By				
Detour Length (km)	10								
Allowable Load (t):	Single	CS1 28		Semi	CS2 49		Train	CS3 62	
Design Loading:	MS23							----> On Critical Spans ---->Critical Member	
----> Primary Span									
Posting Information									
Required Load Posting (t)			Single		Semi		Truck Train		
Posted Loading (t)			Single		Semi		Truck Train		
Posted:	Lane	EB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Posted:	Lane	WB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Remarks	Not required.								
Hazard Marker At Bridge (Y/N)	No								
Remarks									
Other Sign Types									
Utilities (Located at)									
Utility Attachments									
Telephone					Gas				
Power	2 wires North r/w.				Municipal				
Others					Problem (Y/N)	No			
Remarks									
Approach Road									
			Last	Now	Explanation of Condition				
Horizontal Alignment			9	9	Strike damage NE - Still functional plow damage SW - still functional. Non standard connection at bridge.				
Vertical Alignment			9	9					
Roadway Width (m)		10.000							
Approach Bump			5	5					
Guardrail (Y/N)		Yes							
Guardrail			8	4					
Length (m)		19.000							
Current Standard (Y/N)		No							
Termination Type		Turned Down							
Drainage			8	8					
Approach Road General Rating			9	9					

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : SM, 1 Spans, Lengths(m): 6, A-Ident Number:)					
Special Features					
Special Feature			X		
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last					
Now					
Wearing Surface			4	4	Longitudinal ACP cracks over keys.
(Material Type : ACP)					
(Thickness(mm) : 50)					
Lateral Connection Problem (Y/N)	Yes				
Deck Top			N	N	
Deck Rideability			7	6	
Deck Joints			N	N	Paved over.
Bump (Y/N)	No				
Deck Drainage			N	5	No deck drains.
Drains Clogged (Y/N)					
Curbs/Median			N	4	Lift pockets not grouted.
(Curb Type : Standard)					
Scaling (Percent Area)					
Bridge Rail			7	7	Torch cut holes in 4 posts.
(Type : GALVANIZED STEEL BRIDGE TUBE)					
Bridge Rail Posts			N	5	
(Type : GALVANIZED POST STEEL; GALVANIZED POST STEEL)					
Bridge Rail/Posts Coating			7	6	
(Type : GALVANIZED)					
Sidewalk			X	X	
Girder Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
Last					
Now					
Girders			5	5	Longitudinal hairline cracks on South & North ext girder fascia runs length of girder. 300 mm up from bottom. Staining from connector pockets at all locations.
Last Complete Inspection Date	27-May-2010				
Cracking (Y/N)	Yes				
Spalling (Percent Area)	0				
Lift or Connector Pocket Grouted (Y/N)					
(Number Of Girders : 9)					
Span Alignment Problems					
Vertical (Y/N)	No				
Horizontal (Y/N)	No				
Superstructure General Rating			5	5	

Substructure						
Bridge Component		Last	Now	Explanation of Condition		
Abutments						
(Extended Backwall Piles (Y/N) : Y)						
(Extended Backwall Piles Spacing(mm) : 1200)						
(Total Number of Caps/Corbels : 3:3)						
Bearing Seats/Caps/Corbels Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
Last				Sub caps cut to form crown. East subcap horizontal check.		
Now						
Bearing Seats/Caps/Corbels				6	6	
(Type : TREATED TIMBER)						
(Depth(mm) : 300)						
(Width(mm) : 350)						
Backwalls/Breastwalls				7	7	
Greatest Height (m)		2.50				
Wingwalls				7	6	
(Total Number of Bearing Piles : 10:10)						
Piles Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
Last						
Now						
Piles				7	7	
Paint/Coating				X	X	
Abutment Stability				8	8	
Scour/Erosion				8	8	
Piers/Bents						
(Type :)						
(Total Number of Caps/Corbels :)						
Bearing Seats/Caps/Corbels Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
Last						
Now						
Bearing Seats/Caps/Corbels				X	X	
(Type :)						
(Depth(mm) :)						
(Width(mm) :)						
(Total Number of Bearing Piles :)						
Piles Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
Last						
Now						
Pier Shaft/Piles				X	X	
Greatest Height (m)						
Bracing/Struts/Sheathing				7	7	
Nose Plate				X	X	
Paint/Coating				X	X	
(Colour Description :)						
(Colour Code :)						

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Pier Stability		X	X	
Scour		X	X	
Debris (Y/N)	Yes			Old backwall in channel
Substructure General Rating		6	6	
Structure Usage				
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : N)				Undercutting of banks U/S of bridge.
(D/S Direction : S)				
Alignment		7	7	
Bank Stability		4	4	
HWM (m below Top of Curb)				HWM not visible
Drift (Y/N)	No			
Slope Protection (Type : RIP RAP; RIP RAP)		7	7	Old backwall on West abut.
Guidebank/Spurs		X	X	
Adequacy of Opening		7	7	
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		4	4	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL	2010	properly connect approach rail.					
SEAL CURBS							
PATCH DECK							
OVERLAY DECK							
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
SHOTCRETE REPAIRS							
CORE TIMBER CAPS/CORBELS							
REPAIR/REPLACE TIMBER CAPS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION	2010	Remove old backwall planks					
INSTALL STRUTS							
OTHER ACTION	2010	Seal approach ACP cracks. Re-seal ACP wearing surface cracks on deck.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	61.1/61.1	Sufficiency Rating (Last/Now) (%)	64.5/63.5	Est. Repl. Yr	2034	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	Monitor cracks on girders.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Dave Lam		Previous Assistant's Name				
Next Inspection Date	27-Aug-2013		Previous Inspection Date	27-Feb-2007			
Inspection Cycle (Default) (months)	39						
Comment							