

Bridge Culvert Inspection			
Bridge File Number	71678 -1 Bridge Culvert	Form Type	CUL1
Year Built	1978	Lot No.	4
Bridge or Town Name	CAMPSIE	Inspector Name	Melanie Johnson
Located Over	TRIBUTARY TO PADDLE RIVER, 8.11.84.30.10, WATERCRS-ST	Inspector Class	BR CLS B
Located On	763:02 C1 5.228	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	24-Aug-2011
Legal Land Location	SE SEC 5 TWP 60 RGE 5 W5M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-114:42:26, 54:09:08	Data Entry Date	12-Sep-2011
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Eric Carcoux
Contract Main. Area	CMA10	Review Date	07-Sep-2011
Clear Roadway/Skew	8.2 /	Dept. Reviewer Name	Brent Herrick
AADT/Year	520 / 2010 (A)	Dept. Review Date	15-Sep-2011
Road Classification	RCU-209-110	Follow-Up By	
Detour Length (km)	14		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	3700	SP	37.2	152X51	3.5	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	North r/w.	Gas	To east @ resident entrance.
Power	2 lines north r/w.	Municipal	
Others		Problem (Y/N)	No
Remarks	BF tag installed @ top of North end roof.		

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	7	7	Resident entrance to NE. No passing to West.
Vertical Alignment	7	7	
Roadway Width (m)	8.200		Longitudinal crack in roadway pavement over pipe - photo. Typical both lanes (EB/WB).
Embankment	4	5	
Sideslope (__:1)	3.0		
(Height of Cover(m) : 3.7)			
Guardrail (Y/N)	No		
Approach Road / Embankment General Rating	7	7	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	N		
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	

Upstream End					
Culvert Component		Last	Now	Explanation of Condition	
Wingwalls (Shape :)		X	X		
Cutoff Wall		X	X		
Bevel End		7	N	Water up to 0.4m below crown.	
Heaving (mm)	200				
Invert Above/Below Stream Bed					
Above/Below (mm)	0				
Scour Protection (Type : NONE) (Avg. Rock Size(mm) :)		4	N		
Scour/Erosion		4	N	Scour at upstream around bevel end.-10-May-2008	
Beavers (Y/N)	No				
Upstream End General Rating		4	4	GR carried forward from 10-May-2008	
Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 3700, Type: SP)					
Barrel Last Accessible Date	16-Feb-2005			0.4m clear to crown. Viewed from both ends. Not able to see much.	
Special Features					
Special Feature (Type :)					
Special Feature (Type :)					
Roof		7	N		
Measured Rise (mm)					
Measured At Ring No.					
Sag (mm)	0				
Percent Sag					
Sidewall		7	N		
Measured Span (mm)					
Measured At Ring No.					
Deflection (mm)	0				
Percent Deflection					
Floor		N	N		
Bulge (mm)					
Measured At Ring No.					
Abrasion (Y/N)					
Circumferential Seams		N	N		
Separation (mm)	0				
Longitudinal Seams		N	N		
Total No. of Cracked Rings					
Total No. of Rings with Two Cracked Seams					
Min. Remaining Steel Between Cracks (mm)					
Proper Lap (Y/N)	No				
Longitudinal Stagger (Y/N)	No				
Coating		5	N	Staining at a few bolts.-10-May-2008	
Corrosion By Soil (Y/N)	Yes				
Corrosion By Water (Y/N)	Yes				

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 3700, Type: SP)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	Yes			Ponded 2.0 m.
Fish Passage Adequacy		7	7	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		N	N	Previously rated "7" from 16/Feb/2005.

Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	N	
Heaving (mm)	200			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		5	N	Well vegetated.-10-May-2008
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		5	N	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	GR carried fwd from 10-May-2008

Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	No			

Structure Usage				
		Last	Now	Explanation of Condition
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/55.6	Sufficiency Rating (Last/Now) (%)	67.2/63.2	Est. Repl. Yr	2030	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Dave Lam		Previous Assistant's Name				
Next Inspection Date	24-Nov-2014		Previous Inspection Date	10-May-2008			
Inspection Cycle (Default) (months)	39						
Comment							