

Bridge Culvert Inspection								
Bridge File Number	71710 -1 Bridge Culvert				Form Type	CUL1		
Year Built	1970				Lot No.	1		
Bridge or Town Name	CALGARY				Inspector Name	Garry Roberts		
Located Over	ELBOW RIVER, 2.13.33, WATERCRS-ST				Inspector Class	BR CLS A		
Located On	8:06 C1 16.215				Assistant Name			
Water Body Cl./Year					Assistant Class			
Navigabil. Cl./Year					Inspection Date	30-May-2012		
Legal Land Location	NE SEC 5 TWP 24 RGE 2 W5M				Data Entry By	Kelsey Roberts		
Longitude, Latitude	-114:14:18, 51:01:04				Data Entry Date	27-Jun-2012		
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Ash Morjaria		
Contract Main. Area	CMA27				Review Date	18-Jun-2012		
Clear Roadway/Skew	12.6 / 45 deg. (RHF)				Dept. Reviewer Name	Tim Davies		
AADT/Year	7,900 / 2011 (A)				Dept. Review Date	29-Jun-2012		
Road Classification	RAU-210-110				Follow-Up By			
Detour Length (km)	12							
Bridge Culvert Information								
Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	4142	4574	SPE	61	152X51	3.5,3.5,3.5	ELLIPSE
Special Features	VERT STEEL STRUTS							
Special Features Comment								
Utilities (Located at)								
Utility Attachments								
Telephone	SOUTH SIDE				Gas			
Power	6 WIRE POWER - SOUTH DITCH				Municipal			
Others					Problem (Y/N)	No		
Remarks								
Approach Road / Embankment								
			Last	Now	Explanation of Condition			
Horizontal Alignment			6	6	Crack sound over pipe, new ACP overlay in WBL NO PASSING EITHER DIRECTION.			
Vertical Alignment			7	7				
Roadway Width (m)	12.600							
Embankment			5	5				
Sideslope ( _ :1)	3.0							
(Height of Cover(m) : 1)								
Guardrail (Y/N)	Yes							
<b>Approach Road / Embankment General Rating</b>			<b>6</b>	<b>6</b>				
Upstream End								
<b>Culvert Component</b>			Last	Now	Explanation of Condition			
Direction			W		WEST PLACED COLLAR IN 1989(941012)			
End Treatment (Concrete, Steel, Others, None)	CONCRETE							
Headwall			4	4	10-3mm-10mm x 300mm LONG VERT @ HEADWALL Cracks Breaking up- Section of unsound concrete 540mmx150mm.			
Collar			3	3	S SIDE BROKEN OUT 0.5m x 0.5m- exposed rebar. N side breaking & Cracked.			
Wingwalls			X	X				
(Shape : )								
Cutoff Wall			N	N				

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		4	4	Pushing in 200mm- South side.
Heaving (mm)	400			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	250			
Scour Protection		5	5	
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>400</b> )				
Scour/Erosion		5	5	
Beavers (Y/N)	Yes			
<b>Upstream End General Rating</b>		<b>3</b>	<b>3</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 4142, Rise (mm): 4574, Type: SPE)</b>				
Barrel Last Accessible Date	18-Jan-2007			Water too deep to enter Could measure at horizontal struts only
<b>Special Features</b>				
Special Feature		6	5	Braces @ u/s & d/s U/S strut pulling away from North sidewall on one corner.
(Type : <b>VERT STEEL STRUTS</b> )				
Special Feature				
(Type : )				
Roof		N	N	3 points measured @ u/s brace
Measured Rise (mm)				
Measured At Ring No.				(Estimate roof max span 4250 @ ring #8) 18-Jan-2007
Sag (mm)	91			
Percent Sag	2			
Sidewall		N	N	#1-3010mm span #2, #2770mm span #3 -3040mm span 2770 at #2- measured to inside of strut on North sidewall, it should be noted this type of deflection is not typical of the majority of the barrel section, only U/S, D/S ends.
Measured Span (mm)	2770			
Measured At Ring No.	2			
Deflection (mm)	1372			
Percent Deflection	33			(50 to 80mm cracks @ ring 8 & 9 south sidewall - not @ seam) 18-Jan-2007 Inward (100mm bulge @ d/s south sideall) 18-Jan-2007 #4 3145mm at point 4
Floor		N	N	inward sidewall deflection. (Ring #1&2 cracked @ W longitudinal sidewall seam for 1.8m with less than) 18-Jan-2007
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	N	(50mm remaining steel @ area behind front plate under brace.) 18-Jan-2007
Separation (mm)	0			
Longitudinal Seams		N	N	(corrosion with some pitting @ waterline-circ seams missing bolts @ ring #7 & #8) 18-Jan-2007
Total No. of Cracked Rings	1			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	50			
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		N	N	(Corrosion with some pitting @ sidewalls)
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 4142, Rise (mm): 4574, Type: SPE)				
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		3	4	Constricted @ u/s Brace with drift accumulation
Baffle		X	X	
(Type : )				
Waterway Adequacy		7	7	Drift at u/s brace
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	Yes			
<b>Barrel General Rating</b>		<b>4</b>	<b>4</b>	Raised to 4 due to permanent brace GR carried forward
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		EAST
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		4	4	6-2mm w x 300mm I CRK-HWALL.
Collar		4	4	6-3mm widex350mm long- Cracks in North side.
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		N	N	Rock covered
Bevel End		4	4	North sidewall bulge in 500mm. South sidewall bulge in 300mm.
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	300			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 1000)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>4</b>	<b>4</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		7	7	
Bank Stability		6	6	
HWM (m below Top of Culvert)	1.0			Debris at U/S HWM not visible
Drift (Y/N)	Yes			
Channel Bottom Degrading/Aggrading	DEGRADING			Beaver activity at u/s bevel
Beavers (Y/N)	Yes			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>6</b>	<b>6</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS	2013	Struts in D/S end (if structure not replaced)					
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2013	Replace structure when hwy twinned in future.					
OTHER ACTION	2013	Repair approx. 600mmx500xx hole in collar.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>44.4/44.4</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>48.4/42.0</b>	Est. Repl. Yr	2015	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jason Rusu		Previous Assistant's Name				
Next Inspection Date	28-Feb-2014		Previous Inspection Date	21-Oct-2010			
Inspection Cycle (Default) (months)	21						
Comment							