

Bridge Inspection									
Bridge File Number	72485 -1 Bridge				Form Type	PCS			
Year Built/Year Supstr	1954/1954				Lot No.	2			
Bridge or Town Name	DEADWOOD				Inspector Name	Brian Pientsch			
Located Over	TRIBUTARY TO ROUSSEAU CREEK, 8.10.44.2.2, WATERCRS-ST				Inspector Class	BR CLS A			
Located On	690:02 C1 8.799				Assistant Name				
Water Body Cl./Year					Assistant Class				
Navigabil. Cl./Year					Inspection Date	20-Mar-2013			
Legal Land Location	SW SEC 30 TWP 89 RGE 22 W5M				Data Entry By	Theresa Lacusta			
Longitude, Latitude	-117:30:04, 56:44:27				Data Entry Date	09-Apr-2013			
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Eric Carcoux			
Contract Main. Area	CMA04				Review Date	03-Apr-2013			
Clear Roadway/Skew	9.1 /				Dept. Reviewer Name				
AADT/Year	210 / 2012 (A)				Dept. Review Date				
Road Classification	RCU-209-110				Follow-Up By				
Detour Length (km)	6								
Allowable Load (t):	Single	CS1 28 GIRDER	Semi	CS2 49 GIRDER	Train	CS3 66 GIRDER	----> On Critical Spans ---->Critical Member		
Design Loading:	HS20						----> Primary Span		
Posting Information									
Required Load Posting (t)	Single				Semi		Truck Train		
Posted Loading (t)	Single				Semi		Truck Train		
Posted:	Lane	EB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Posted:	Lane	WB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Remarks									
Hazard Marker At Bridge (Y/N)	Yes								
Remarks	ALL FOUR CORNERS.								
Other Sign Types									
Utilities (Located at)									
Utility Attachments									
Telephone	East r/w				Gas				
Power	2 wire OH				Municipal				
Others					Problem (Y/N)	No			
Remarks									
Approach Road									
			Last	Now	Explanation of Condition				
Horizontal Alignment			7	7	APPROACHES N & S 30 M WEST				
Vertical Alignment			8	8					
Roadway Width (m)	9.900				Both approaches have 50mm settlement.				
Approach Bump			7	3					
Guardrail (Y/N)	Yes				Not thrie beam.				
Guardrail			4	5					
Length (m)	23.300								
Current Standard (Y/N)	No								
Termination Type	TURNED DOWN								
Drainage			7	7					
Approach Road General Rating			7	7					

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : PGO, 3 Spans, Lengths(m): 6.1-6.1-6.1, A-Ident Number:)					
Special Features					
Special Feature			X		
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last	0	0	0	0	
Now	5.0				
Wearing Surface			4	4	CONCRETE OVERLAY 200mm x 300mm pothole on center span, covered in tar.
(Material Type : CONCRETE)					
(Thickness(mm) : 100)					
Lateral Connection Problem (Y/N)		No			
Deck Top			N	N	
Deck Rideability			7	7	
Deck Joints			N	N	
Bump (Y/N)		No			
Deck Drainage			7	7	
Drains Clogged (Y/N)		No			
Curbs/Median			5	5	
(Curb Type : Standard)					
Scaling (Percent Area)		50			
Bridge Rail			4	9	DOUBLE LAYER FLEXBEAM
(Type : GALVANIZED STEEL FLEX BEAM)					
Bridge Rail Posts			3	9	
(Type : POST STEEL;POST STEEL)					
Bridge Rail/Posts Coating			7	9	
(Type : GALVANIZED)					
Sidewalk			X	X	
Girder Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
Last	0	0	0	0	
Now					
Girders			4	4	10 girders in S1 & S3 have wide cracking in the anchorage zone of both legs. S2 has 2 girders. Concrete sound. Curb lift pockets to be grouted Spring 2013 Contrat 11895.
Last Complete Inspection Date		20-Mar-2013			
Cracking (Y/N)		Yes			
Spalling (Percent Area)		2			
Lift or Connector Pocket Grouted (Y/N)		No			
(Number Of Girders : 36)					
Span Alignment Problems					
Vertical (Y/N)		No			
Horizontal (Y/N)		No			
Superstructure General Rating			4	4	

Substructure					
Bridge Component		Last	Now	Explanation of Condition	
Abutments					
(Extended Backwall Piles (Y/N) : N)					
(Extended Backwall Piles Spacing(mm) :)					
Abutment eroding SW corner.					
(Total Number of Caps/Corbels : 5:5)					
Bearing Seats/Caps/Corbels Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
Last					
Now					
Bearing Seats/Caps/Corbels				4	9
(Type : TREATED TIMBER)					
(Depth(mm) : 300)					
(Width(mm) : 300)					
Backwalls/Breastwalls				4	7
Backwall scabs on E. abut.					
Greatest Height (m)		3.20			
Wingwalls				4	7
(Total Number of Bearing Piles : 7:7)					
Piles Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
Last					
Now					
Piles				4	7
Paint/Coating				X	X
Abutment Stability				5	6
Scour/Erosion				4	5
Piers/Bents					
(Type : PIER-COLUMN)					
(Total Number of Caps/Corbels : 5:5)					
Bearing Seats/Caps/Corbels Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
Last	10	0	0	0	
Now					
Bearing Seats/Caps/Corbels				N	9
(Type : TREATED TIMBER)					
(Depth(mm) : 300)					
(Width(mm) : 350)					
(Total Number of Bearing Piles : 7:7)					
Piles Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
Last	14	0	0	0	
Now					
Pier Shaft/Piles				N	7
Greatest Height (m)		3.50			

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Bracing/Struts/Sheathing		4	7	
Nose Plate		X	X	
Paint/Coating		X	X	
(Colour Description :)				
(Colour Code :)				
Pier Stability		6	6	
Scour		6	6	
Debris (Y/N)	Yes			Few small logs.
Substructure General Rating		4	6	
Structure Usage				
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : S)				
(D/S Direction : N)				Natural on W. headslope Class 1 rock on E. headslope.
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Curb)	2.2			HWM 18m-Apr.08
Drift (Y/N)	No			
Slope Protection		4	5	
(Type :)				Riprap on E. headslope.
Guidebank/Spurs		X	X	
Adequacy of Opening		7	7	
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		4	5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
OVERLAY DECK							
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
SHOTCRETE REPAIRS							
CORE TIMBER CAPS/CORBELS							
REPAIR/REPLACE TIMBER CAPS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL STRUTS							
OTHER ACTION	2013	ACP approaches require patching.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	44.4/55.6	Sufficiency Rating (Last/Now) (%)	58.1/64.3	Est. Repl. Yr	2028	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Eric Carcoux		Previous Assistant's Name				
Next Inspection Date	20-Jun-2016		Previous Inspection Date	21-Oct-2009			
Inspection Cycle (Default) (months)	39						
Comment							