

Bridge Inspection										
Bridge File Number	73173 -1 Bridge					Form Type	TH			
Year Built/Year Supstr	1971/1948					Lot No.	1			
Bridge or Town Name	SUNDRE					Inspector Name	Owen Salava			
Located Over	JAMES RIVER, 3.95, WATERCRS-ST					Inspector Class	BR CLS A			
Located On	734:12 C1 33.750					Assistant Name				
Water Body Cl./Year						Assistant Class				
Navigabil. Cl./Year						Inspection Date	29-Nov-2010			
Legal Land Location	SE SEC 10 TWP 33 RGE 9 W5M					Data Entry By	Marcia Chavez			
Longitude, Latitude	-115:11:33, 51:48:47					Data Entry Date	28-Feb-2011			
Road Authority	Alberta Transportation (AIT)					Reviewer Name	John O'Brien			
Contract Main. Area	CMA18					Review Date	22-Feb-2011			
Clear Roadway/Skew	6.7 / 0 deg.					Dept. Reviewer Name	Chris Black			
AADT/Year	100 / 2009 (A)					Dept. Review Date	01-Mar-2011			
Road Classification	RCU-208G-90					Follow-Up By				
Detour Length (km)	50									
Allowable Load (t):	Single	CS1 40 STRINGER			Semi	CS2 60 U2L3		Train	CS3 74 U2L3	---> On Critical Spans --->Critical Member
Design Loading:	HS20									---> Primary Span

Posting Information												
Required Vert. Clearance Posting (m)												
Posted Vertical Clearance (Y/N) Yes												
Posted:	Lane	NB	On Bridge (m)	4.7	In Advance (Y/N)	Yes	Lane	SB	On Bridge (m)	4.7	In Advance (Y/N)	Yes
Remarks Measured 4.89m both ends. Advanced NB has bullet hole through "7" making it illegible @ Red Deer River Crossing												
Required Load Posting (t)			Single			Semi			Truck Train			
Posted Loading (t)			Single			Semi			Truck Train			
Posted:	Lane	NB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No				
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No				
Remarks Not required. Minor damage to sign & bracket at N portal. Cracked bracket at S portal.												
Hazard Marker At Bridge (Y/N)		Yes										
Remarks		At varying heights. Increased sign height aids in visibility due to vertical curves										
Other Sign Types		Narrow Bridge, Max 1 Truck on Bridge, Stop if Oncoming Traffic, Max 20 - Logging Trucks; "James River".										

Utilities (Located at)									
Utility Attachments									
Telephone						Gas			
Power						Municipal			
Others						Problem (Y/N)	No		
Remarks									

Approach Road				
		Last	Now	Explanation of Condition
Horizontal Alignment		6	6	In sag curve with limited sight distance in both directions.
Vertical Alignment		4	4	
Roadway Width (m)	7.000			(S approach has large potholes. 28May2008).
Approach Bump		4	6	
Guardrail (Y/N)		No		No guardrail, height above water and vertical alignment contribute to potential hazard.
Guardrail		X	X	
Length (m)				
Current Standard (Y/N)		No		
Termination Type		None		
Drainage		4	4	Windrows at north, erosion channel NW, SW & SE. Drains to bridge.
<b>Approach Road General Rating</b>		<b>2</b>	<b>2</b>	Potential safety hazard.

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : <b>TH, 1 Spans, Lengths(m): 34.1, A-Ident Number: A0664-02</b> )					
<b>Special Features</b>					
Special Feature			X		
(Type : )					
Special Feature			X		
(Type : )					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	Snow covered.
<b>Last</b>	60	0	0	0	
<b>Now</b>	100.0	0.0	0.0	0.0	
Wearing Surface/Deck Top			4	N	(25mm worn in wheelpaths, ends starting to rot. 23Jun2010).
(Material Type : <b>UNTREATED TIMBER</b> )					
(Plank Thickness(mm) : <b>75</b> )					
(Plank Width(mm) : <b>300</b> )					
Deck Rideability			5	5	
Deck Joints			X	X	
Temperature (deg. C)		-8			
(Expansion Type : )					
(Fixed Type : )					
Gap Size (mm)		Gap Location			
Curbs/Wheel Guards			N	N	(2 wheelguards are splintered. "L" bolts are ineffective - photo. 1 spacer block split & dislodged at NE corner. 23Jun2010). Snow covered.
(Curb Type : <b>Standard</b> )					
(Type : <b>TREATED TIMBER</b> )					
(Thickness(mm) : <b>100</b> )					
(Width(mm) : <b>300</b> )					
Bridge Rail			2	2	(32 rail to truss hooked bolts are missing. 23Jun2010). Minor damage on W truss rail @ midpoint. Hole in another W panel near N end. There are no railings past batter posts. 3 steel posts are missing. Truss member used as support for panels. Rusting.
(Type : <b>LATTICE</b> )					
Bridge Rail Posts/Blocking			2	2	
(Type : <b>POST STEEL;POST STEEL</b> )					
Bridge Rail/Posts Coating			4	4	10% paint failure. Dirty.
(Type : <b>PAINT</b> )					
Sidewalk			X	X	

Superstructure						
Bridge Component				Last	Now	Explanation of Condition
<b>(Primary Span : TH, 1 Spans, Lengths(m): 34.1, A-Ident Number: A0664-02)</b>						
Wide Load Damage (Y/N)	Yes					Both portals (minor).  U6L7E has 30mm dent. U3m2E cracked at m2E. U4L3W has 30mm bend near L3. U6U6 has 20mm dent & both portals have high load gouges. Bay 3 & 4 missing lower bracing bolts at mid-point. Top bracing has headless rivet at U5W. Batter post has broken clip angle at L7E.
High Load Damage (Y/N)	Yes					
Top Chord			7	7		
Batter Posts			5	5		
Sway Bracings			7	7		
Diagonals			4	4		
Verticals			7	7		
Portals			4	4		
Connections			4	4		
Floor Beams			7	7		
Bottom Chord			7	7		
<b>(No. of Stringers : 91)</b>						
<b>Stringer Detail Ratings</b>						
	N (count)	1 (count)	2 (count)	3 (count)		
<b>Last</b>						
<b>Now</b>						
Stringers			7	7		
(Type : <b>STEEL</b> )						
(Width(mm) : <b>125</b> )						
(Depth(mm) : <b>300</b> )						
(Spacing(mm) : <b>557</b> )						
Paint Condition			4	5		5% peeling between primer and top coat and also peeling on any mill scale. Rust on 2% predominantly floor system. Green.
(Colour Description : )						
(Colour Code : )						
Touchup Required (Y/N)	No					
Bearings			7	7		Truss jammed into abutment timbers.  N abut at L7. S abut at L0. Covered with gravel & snow.
Temperature (deg. C)	-8					
(Expansion Type : <b>ROLLER NEST BEARING</b> )						
(Fixed Type : <b>PINNED BEARING</b> )						
Functioning (Y/N)	Yes					
Sub Deck/Deck Underside			6	6		Laminated.
(Material Type : <b>TREATED TIMBER</b> )						
(Plank Thickness(mm) : <b>105</b> )						
(Plank Width(mm) : <b>50</b> )						
Defects (Percent Area)	0					
<b>Span Alignment Problems</b>						
Vertical (Y/N)	No					
Horizontal (Y/N)	No					
<b>Superstructure General Rating</b>			<b>4</b>	<b>4</b>		
Substructure						
Bridge Component				Last	Now	Explanation of Condition
<b>Abutments</b>						
(Extended Backwall Piles (Y/N) : <b>Y</b> )						
(Extended Backwall Piles Spacing(mm) : <b>1500</b> )						

Substructure							
Bridge Component					Last	Now	Explanation of Condition
(Total Number of Caps/Corbels : <b>11:11</b> )							
Bearing Seats/Caps/Corbels Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)			8 - 310 x 94 HP corbel & 1 - 310 x 94 HP full length caps in front, 2 short. HP 310 x 94 cap in back at each abut. No stiffeners in corbels above caps.
<b>Last</b>	0	0	0	0			
<b>Now</b>	0	0	0	0			
Bearing Seats/Caps/Corbels				7	7		
(Type : <b>STEEL</b> )							
(Depth(mm) : <b>310</b> )							
(Width(mm) : <b>310</b> )							
Backwalls/Breastwalls					6	6	
Greatest Height (m)		4.50					
Wingwalls					7	7	
(Total Number of Bearing Piles : <b>8:8</b> )							
Piles Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)			With steel capital - typical. 14 / abutment with steel capital. 2 rows of 7 / abutments.
<b>Last</b>	0	0	0	0			
<b>Now</b>	0	0	0	0			
Piles				6	6		
Paint/Coating				X	X		
Abutment Stability					5	5	
Scour/Erosion					4	N	(Erosion scar along S abut & extends behind NW wingwall. Erosion gully at S breastwall. 23Jun2010).
<b>Piers/Bents</b>							
(Type : )							
(Total Number of Caps/Corbels : )							
Bearing Seats/Caps/Corbels Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)			
<b>Last</b>							
<b>Now</b>							
Bearing Seats/Caps/Corbels				X	X		
(Type : )							
(Total Number of Bearing Piles : )							
Piles Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)			
<b>Last</b>							
<b>Now</b>							
Pier Shaft/Piles				X	X		
Greatest Height (m)							
Bracing/Struts/Sheathing					X	X	
Nose Plate					X	X	
Paint/Coating					X	X	
(Colour Description : )							
(Colour Code : )							
Pier Stability					X	X	
Scour					X	X	
Debris (Y/N)		Yes					Old piles at S abut. Debris stuck in wheelguard at L3E.

Substructure				
Bridge Component		Last	Now	Explanation of Condition
<b>Substructure General Rating</b>		<b>5</b>	<b>5</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel</b>				
(U/S Direction : <b>E</b> )				River is on a skew and bridge is square.
(D/S Direction : <b>W</b> )				
Alignment		5	5	
Bank Stability		4	N	(Some erosion E of bridge on the S & N banks. 23Jun2010).
HWM (m below Top of Curb)	2.9			Could not confirm HWM Minor drift.
Drift (Y/N)	Yes			
Slope Protection		4	N	(Erosion of S bank under bridge (photo). 23Jun2010).
(Type : <b>RIP RAP; RIP RAP</b> )				
Guidebank/Spurs		X	X	
Adequacy of Opening		6	6	
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>4</b>	<b>4</b>	GR carried forward from 23Jun2010.



Maintenance Reviewed By		Date		Estimated Total	0
Proposed Long-Term Strategy	2006.01.17 With normal maintenance bridge should be good until 2035.				
On 3-Year Program (Y/N)					
Proposed Action					
Previous Inspector's Name	Owen Salava	Previous Assistant's Name	Bryce Clayton		
Next Inspection Date	28-Feb-2014	Previous Inspection Date	23-Jun-2010		
Inspection Cycle (Default) (months)	39				
Comment					