

Bridge Culvert Inspection			
Bridge File Number	73993 -1 Bridge Culvert	Form Type	CUL1
Year Built	1991	Lot No.	3
Bridge or Town Name	AIRDRIE	Inspector Name	Garry Roberts
Located Over	TRIBUTARY TO CROSSFIELD CREEK, 3.33.20.3, WATERCRS-ST	Inspector Class	BR CLS A
Located On	791:05 C1 2.193	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	17-Jul-2012
Legal Land Location	SW SEC 24 TWP 27 RGE 28 W4M	Data Entry By	Kelsey Roberts
Longitude, Latitude	-113:49:33, 51:19:10	Data Entry Date	23-Aug-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Ash Morjaria
Contract Main. Area	CMA29	Review Date	28-Jul-2012
Clear Roadway/Skew	9.2 /	Dept. Reviewer Name	Tim Davies
AADT/Year	450 / 2011 (A)	Dept. Review Date	24-Aug-2012
Road Classification	RCU-209-110	Follow-Up By	
Detour Length (km)	3		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2700	MP	30	75X25	2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	East ditch	Gas	
Power	E fenceline-15m-1W	Municipal	
Others	Irrigation line	Problem (Y/N)	No
Remarks	Through barrel		

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		8	8	
Vertical Alignment		8	8	
Roadway Width (m)	9.200			
Embankment		7	7	
Sideslope (__:1)	3.0			
(Height of Cover(m) : 2)				
Guardrail (Y/N)	Yes			Accident damage to NE corner, 1 broken post, detached at a second post- photo.
Approach Road / Embankment General Rating		8	8	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		W		West
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		8	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 350)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Upstream End General Rating		8	7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2700, Type: MP)				
Barrel Last Accessible Date	17-Jul-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	8	
Measured Rise (mm)	2640			
Measured At Ring No.	2			
Sag (mm)	60			
Percent Sag	2			
Sidewall		8	8	
Measured Span (mm)	2720			
Measured At Ring No.	2			
Deflection (mm)	20			
Percent Deflection	1			
Floor		7	7	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		6	6	Gaps at seams sealed with oakum.
Separation (mm)	110			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		7	7	Minor alkali stains at lower sidewall
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2700, Type: MP)				
Fish Passage Adequacy		6	6	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		8	8	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		East
End Treatment (Concrete, Steel, Others, None)		STEEL		
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed		BELOW		
Above/Below (mm)	100			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 350)				
Scour/Erosion		7	7	
Beavers (Y/N)		No		
Downstream End General Rating		7	7	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	Channel drains into dugout 40 m d/s.
Bank Stability		6	7	
HWM (m below Top of Culvert)				No visible HWM
Drift (Y/N)		No		
Channel Bottom Degrading/Aggrading		NONE		
Beavers (Y/N)		No		
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		6	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2012	Replace 1 section damaged guardrail and 2 posts.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	88.9/88.9	Sufficiency Rating (Last/Now) (%)	82.4/82.0	Est. Repl. Yr	2043	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	17-Oct-2015		Previous Inspection Date	17-May-2009			
Inspection Cycle (Default) (months)	39						
Comment							