

Bridge Culvert Inspection			
Bridge File Number	74106 -1 Bridge Culvert	Form Type	CULM
Year Built	1994	Lot No.	3
Bridge or Town Name	CARSELAND	Inspector Name	Tom Carey
Located Over	WID - IRRIGATION C, WATERCRS-IC	Inspector Class	BR CLS A
Located On	24:04 C1 13.777	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	21-Feb-2013
Legal Land Location	SW SEC 22 TWP 22 RGE 26 W4M	Data Entry By	Anne Roberts
Longitude, Latitude	-113:32:12, 50:53:05	Data Entry Date	19-Mar-2013
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Garry Roberts
Contract Main. Area	CMA30	Review Date	03-Mar-2013
Clear Roadway/Skew	8.3 / -10 deg. (LHF)	Dept. Reviewer Name	Tim Davies
AADT/Year	2,260 / 2011 (A)	Dept. Review Date	25-Mar-2013
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	3		

**Bridge Culvert Information**

Number of Culverts	2							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	5903	3188	RPB	29.3	152X51	4.0,4.0,4.0	ELLIPSE
2	MAIN	5903	3188	RPB	29.3	152X51	4.0,4.0,4.0	ELLIPSE
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments			
Telephone	West and East row	Gas	
Power	3w 20m East and NW.	Municipal	
Others		Problem (Y/N)	No
Remarks			

**Approach Road / Embankment**

	Last	Now	Explanation of Condition
Horizontal Alignment	9	9	2:1 SLOPE AT CULVERT ENDS
Vertical Alignment	9	9	
Roadway Width (m)	8.300		
Embankment	3	3	(Erosion and loss of fill behind headwall of north pipe @ D/S with large void approx- 1mx0.3mx1.2m) Ice and snow covered.
Sideslope ( __:1)	6.0		
(Height of Cover(m) : 1.3)			
Guardrail (Y/N)	Yes		Double laywer w-beam Bolt missing at post at North east at end - bolt pulled through. Turndown end torn and pointed upward at South East.
<b>Approach Road / Embankment General Rating</b>	<b>9</b>	<b>9</b>	

**Upstream End**

Culvert Component	Last	Now	Explanation of Condition
<b>(Pipe # : 1, Span Type: Primary Span)</b>			
Direction	W		West end, south pipe.
End Treatment (Concrete, Steel, Others, None)	CONCRETE		
Headwall	8	8	Narrow cracks
Collar	8	8	
Wingwalls	X	X	
(Shape : )			

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 1, Span Type: Primary Span)</b>				
Cutoff Wall		N	N	
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	400			
Scour Protection		8	N	PR 8 Completely snow covered.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		8	N	PR 8
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>8</b>	<b>8</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 5903, Rise (mm): 3188, Type: RPB)</b>				
Barrel Last Accessible Date	21-Feb-2013			South pipe.
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		8	8	
Measured Rise (mm)				Estimated
Measured At Ring No.				
Sag (mm)	50			
Percent Sag	1			
Sidewall		8	8	Inward
Measured Span (mm)	5830			
Measured At Ring No.	3			
Deflection (mm)	73			
Percent Deflection	1			
Floor		N	N	600 mm deep ice
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		8	8	
Separation (mm)	0			
Longitudinal Seams		8	8	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	No			
Coating		5	5	Alkali at seams. Isolated rust corrosion at South
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 5903, Rise (mm): 3188, Type: RPB)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type : )				
Waterway Adequacy		9	9	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>8</b>	<b>8</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Direction		E		East end, south pipe.
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		8	8	Narrow cracks
Collar		8	8	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		N	N	
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	400			
Scour Protection		8	N	Completely snow covered. PR 8
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		8	N	PR 8
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>8</b>	<b>8</b>	
Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Direction		W		West end, north pipe.
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		8	8	Narrow cracks
Collar		8	8	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		N	N	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 2, Span Type: Secondary Span)</b>				
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	400			
Scour Protection		8	N	PR 8 Completely snow covered.
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>200</b> )				
Scour/Erosion		8	N	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>8</b>	<b>8</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): 5903, Rise (mm): 3188, Type: RPB)</b>				
Barrel Last Accessible Date	21-Feb-2013			North pipe.
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		8	8	
Measured Rise (mm)				Estimated
Measured At Ring No.				
Sag (mm)	50			
Percent Sag	1			
Sidewall		8	8	Inward
Measured Span (mm)	5860			
Measured At Ring No.	3			
Deflection (mm)	43			
Percent Deflection	1			
Floor		N	N	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		8	8	
Separation (mm)	0			
Longitudinal Seams		8	8	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	No			
Coating		5	5	Alkali @ seams
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				
Camber POS/ZERO/NEG	ZERO			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): 5903, Rise (mm): 3188, Type: RPB)</b>				
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type : )				
Waterway Adequacy		9	9	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>8</b>	<b>8</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 2, Span Type: Secondary Span)</b>				
Direction		E		East end, north pipe.
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		8	8	Narrow cracks
Collar		8	8	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		N	N	
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	400			
Scour Protection		8	N	PR 8 Completely snow covered
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>200</b> )				
Scour/Erosion		8	N	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>8</b>	<b>8</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		8	8	
Bank Stability		8	N	Snow covered
HWM (m below Top of Culvert)	2.0			Snow covered
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	AGGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>8</b>	<b>8</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2013	Fill void with compacted pit run (0.4m <sup>3</sup> ) material @ N pipe down stream end- see photo. If not done.					
OTHER ACTION	2013	Replace South East gaurdrail. Turn down end and install one bolt at post at North east					
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>88.9/88.9</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>91.0/91.0</b>	Est. Repl. Yr	2041	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tom Carey		Previous Assistant's Name				
Next Inspection Date	21-Nov-2014		Previous Inspection Date	20-May-2011			
Inspection Cycle (Default) (months)	21						
Comment							