

Bridge Culvert Inspection			
Bridge File Number	74300 -1 Bridge Culvert	Form Type	CULM
Year Built	1954	Lot No.	2
Bridge or Town Name	WASKATENAU	Inspector Name	Kris Bosters
Located Over	WASKATENAU CREEK, 6.53, WATERCRS-ST	Inspector Class	BR CLS A
Located On	28:06 C1 17.922	Assistant Name	Brian Cote
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	10-Apr-2012
Legal Land Location	SE SEC 16 TWP 59 RGE 19 W4M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-112:46:53, 54:06:02	Data Entry Date	08-May-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Eric Carcoux
Contract Main. Area	CMA07	Review Date	25-Apr-2012
Clear Roadway/Skew	12.9 /	Dept. Reviewer Name	Brent Herrick
AADT/Year	3,640 / 2011 (A)	Dept. Review Date	12-Jun-2012
Road Classification	RAU-213.4-110	Follow-Up By	
Detour Length (km)	3		

Bridge Culvert Information

Number of Culverts	4							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	4267		RP	59.7	160X50	4.8	ARCH
2	MAIN	2019	2226	SPE	27.6	152X51	3.5	ELLIPSE
3	MAIN	2019	2226	SPE	27.6	152X51	3.5	ELLIPSE
4	MAIN	-	1500	MP	27.6	68X13	3.5	ROUND
Special Features	VERT STEEL STRUTS, VERT TIMBER STRUTS							
Special Features Comment	Vert. Steel Struts, Timber Chute (Primary span is a tunnel liner. SP's are 5% vert. ellipsed. Corrugation profile on pipe 1 was measured 180x52. (Size not in drop down list).-04-Dec-2006							

Utilities (Located at)

Utility Attachments			
Telephone	South ditch.	Gas	
Power	2 wires OH 30m North of c/l.	Municipal	
Others		Problem (Y/N)	No
Remarks	File tag North end of primary pipe.		

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Access road to Weskatenau 300m West. Taper for turning lanes start east of all culverts. No passing zones in both directions. Measured over tunnel liner pipe. More cover over SPCSP's and less over CSP. Slight sag over culverts.
Vertical Alignment		7	7	
Roadway Width (m)	13.000			
Embankment		7	7	Over CSP.
Sideslope (__:1)	3.0			
(Height of Cover(m) : 2.5)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		7	7	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Direction		N		
End Treatment (Concrete, Steel, Others, None)	CONCRETE			

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Headwall		X	X	
Collar		5	5	Slabs along collar have settled 350mm on both sides. Cracked collar has separated from bevel.
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		N	N	
Bevel End		7	7	
Heaving (mm)	100			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	600			
Scour Protection		5	4	Void under West slab.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		5	4	Void under top of east collar and slab along same side.
Beavers (Y/N)	Yes			1.5m high dam 30m u/s and 2.0m high dam 45m u/s.
Upstream End General Rating		5	4	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 4267, Rise (mm): , Type: RP)				
Barrel Last Accessible Date	04-Dec-2006			Water too deep to enter. Viewed from ends, shape and condition look adequate.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		N	N	(Bulge at c/l near mid span.From top of ice 2039mm.-Viewed from U/S, shape appears in good condition - photo 2.-04-Dec-2006)
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	0			
Percent Sag				
Sidewall		N	N	(150mm bulge at 8:00 position looking D/S, underneath c/l. 04/Dec/2006) At mid pipe. (1.8%. 04/Dec/2006)
Measured Span (mm)	4191			
Measured At Ring No.				
Deflection (mm)	76			
Percent Deflection	2			
Floor		N	N	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	N	(Midpoint has poorly matched seam. 04/Dec/2006)
Separation (mm)	350			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 4267, Rise (mm): , Type: RP)				
Longitudinal Seams		N	N	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			
Coating		N	N	(Heavy seepage of white deposits from outside the horizontal seams in sidewalls. 04/Dec/2006)
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		8	8	
Baffle		N	N	(Type :)
Waterway Adequacy		6	6	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		4	4	G.R. carried forward from 04/Dec/2006.
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	(Shape :)
Cutoff Wall		X	X	
Bevel End		6	6	
Heaving (mm)	200			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	900			
Scour Protection		7	7	
(Type : RIP RAP, NATURAL)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		7	7	
Beavers (Y/N)	Yes			
Downstream End General Rating		7	7	

Upstream End					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 2, Span Type: Secondary Span)					
Direction		N		Drift across inlet, 2nd from East.	
End Treatment (Concrete, Steel, Others, None)		STEEL			
Headwall		X	X		
Collar		X	X		
Wingwalls (Shape :)		X	X		
Cutoff Wall		X	X		
Bevel End		5	5		
Heaving (mm)		300			
Invert Above/Below Stream Bed		BELOW			
Above/Below (mm)		700			
Scour Protection (Type : RIP RAP) (Avg. Rock Size(mm) : 200)		5	5		
Scour/Erosion		7	7		
Beavers (Y/N)		Yes		Dam u/s.	
Upstream End General Rating		5	5		
Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): 2019, Rise (mm): 2226, Type: SPE)					
Barrel Last Accessible Date		22-Jun-2007		Viewed from ends, looks adequate, thin ice and deep water.	
Special Features					
Special Feature (Type : VERT STEEL STRUTS)		N	N		
Special Feature (Type :)					
Roof		N	N		
Measured Rise (mm)					
Measured At Ring No.					
Sag (mm)		346			
Percent Sag					
Sidewall		N	N		
Measured Span (mm)					
Measured At Ring No.					
Deflection (mm)		231			
Percent Deflection					
Floor		N	N	Under water.	
Bulge (mm)					
Measured At Ring No.					
Abrasion (Y/N)		No			
Circumferential Seams		N	N	(6 cracks on circ. seam at 12:00 on WSP/2 on ESP. 2001/09/17) (Infiltration on first 2 circumferential seams at D/S end of MP. 08/Apr/2005)	
Separation (mm)		160			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): 2019, Rise (mm): 2226, Type: SPE)				
Longitudinal Seams		N	N	(Rings 5 & 7 on west wall of WSP are cracked with 75 mm of steel between cracks. 2001/09/17) Previous inspector must have meant SPE. No WSP visible in culverts. 1N stagger
Total No. of Cracked Rings	2			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	Yes			
Coating		N	N	(Scaling rust on 300 mm strip on floor of MP. (Most of galvanizing in lower third of both barrels sacrificed. 92). 04/Dec/2006)
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		5	5	
Baffle		N	N	(Type :)
Waterway Adequacy		5	5	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		4	4	GR carried forward.-22-June-2007
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		5	5	
Heaving (mm)	100			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	700			
Scour Protection		5	5	
(Type : RIP RAP, NATURAL)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		7	7	
Beavers (Y/N)	Yes			
Downstream End General Rating		5	5	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 3, Span Type: Secondary Span)				
Direction		N		3rd from East, drift across inlet.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	
Bevel End		5	5	
Heaving (mm)	100			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	700			
Scour Protection (Type : RIP RAP) (Avg. Rock Size(mm) : 200)		5	4	Erosio9n along bevel 0.5x0.2x0.1 wide.
Scour/Erosion		7	4	
Beavers (Y/N)	Yes			2 dams u/s.
Upstream End General Rating		7	4	

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 3, Secondary Span, Location Code: MAIN, Span (mm): 2019, Rise (mm): 2226, Type: SPE)				
Barrel Last Accessible Date	22-Jun-2007			Not accessible. Viewed from ends, looks adequate.
Special Features				
Special Feature (Type : VERT STEEL STRUTS)		N	N	
Special Feature (Type :)				
Roof		N	N	
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall		N	N	
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)				
Percent Deflection				
Floor		N	N	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	N	
Separation (mm)				

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 3, Secondary Span, Location Code: MAIN, Span (mm): 2019, Rise (mm): 2226, Type: SPE)				
Longitudinal Seams		N	N	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		N	4	Pitting and scaling lower 1/2.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		4	4	Debris at inlet.
Baffle		N	N	
(Type :)				
Waterway Adequacy		4	4	Debris at inlet.
Icing (Y/N)	No			
Silting (Y/N)	No			Lots of drift at U/S end & caught in struts.-photo
Drift (Y/N)	Yes			
Barrel General Rating		4	4	GR carried fwd.-22-June-2007
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 3, Span Type: Secondary Span)				
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		5	5	
Heaving (mm)	200			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	700			
Scour Protection		5	5	
(Type : RIP RAP, NATURAL)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		7	7	
Beavers (Y/N)	Yes			
Downstream End General Rating		5	5	

Upstream End					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 4, Span Type: Secondary Span)					
Direction		N		4th from East.	
End Treatment (Concrete, Steel, Others, None)		STEEL			
Headwall		X	X		
Collar		X	X		
Wingwalls (Shape :)		X	X		
Cutoff Wall		X	X		
Bevel End		8	8		
Heaving (mm)		100			
Invert Above/Below Stream Bed		ABOVE			
Above/Below (mm)		3000			
Scour Protection (Type : RIP RAP) (Avg. Rock Size(mm) : 200)		7	7		
Scour/Erosion		7	7		
Beavers (Y/N)		Yes		Upstream dams.	
Upstream End General Rating		7	7		
Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 4, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1500, Type: MP)					
Barrel Last Accessible Date		10-Apr-2012			
Special Features					
Special Feature (Type : VERT TIMBER STRUTS)		4	4	Rot in timber chute-photo	
Special Feature (Type :)					
Roof		6	5	3.5%	
Measured Rise (mm)		1420			
Measured At Ring No.		2			
Sag (mm)		80			
Percent Sag		5			
Sidewall		6	5		
Measured Span (mm)		1600			
Measured At Ring No.		2			
Deflection (mm)		100			
Percent Deflection		7			
Floor		4	4	Separation at D/S coupler. Infiltration - photo.	
Bulge (mm)					
Measured At Ring No.					
Abrasion (Y/N)		No			
Circumferential Seams		4	4	Separation at couplers. Infiltration and weed - photo .	
Separation (mm)		160			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 4, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1500, Type: MP)				
Longitudinal Seams		7	7	Riveted.
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		6	6	Minor on floor.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		3	3	200mm drop D/S bevel on timber spillway and 3m above s/b.
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		6	5	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 4, Span Type: Secondary Span)				
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		4	4	
Heaving (mm)				
Invert Above/Below Stream Bed	ABOVE			Bevel section separating from barrel due to sag of bevel.-photo Bevel end inside timber chute.
Above/Below (mm)	3000			
Scour Protection		5	5	timber
(Type : RIP RAP, NATURAL)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	5	
Beavers (Y/N)	Yes			dam 10m d/s.
Downstream End General Rating		5	5	

Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		6	6	
Bank Stability		6	6	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	Yes			
Channel Bottom Degrading/Aggrading	AGGRADING			Large beaver dam 50m U/S of site.
Beavers (Y/N)	Yes			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		6	6	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2012	Remove debris U/S pipe 2 & 3.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	44.4/44.4	Sufficiency Rating (Last/Now) (%)	37.6/36.6	Est. Repl. Yr	2020	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	Monitor rot in timber chute, settlement/voids under collar, circumferential seam pipe 4.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Arnold Assenheimer		Previous Assistant's Name				
Next Inspection Date	10-Jan-2014		Previous Inspection Date	22-Jun-2010			
Inspection Cycle (Default) (months)	21						
Comment							