

Level 2 Inspection - Concrete Deck							
Bridge File Number	74440 -1 Bridge			Form Type	CDK		
Year Built/Year Supstr	1958/1956			Lot No.			
Bridge or Town Name	GUY			Inspector Name	Jason Saly		
Located Over	LITTLE SMOKY RIVER, 8.10.58.7, WATERCRS-ST			Inspector Class	BR CLS A		
Located On	49:12 C1 1.760			Assistant Name			
Water Body Cl./Year				Assistant Class			
Navigabil. Cl./Year				Inspection Date	11-Sep-2012		
Legal Land Location	NE SEC 33 TWP 74 RGE 21 W5M			Data Entry By	Jason Saly		
Longitude, Latitude	-117:09:44, 55:27:21			Data Entry Date	22-Feb-2013		
Road Authority	Alberta Transportation (AIT)			Reviewer Name	Paul Carter		
Contract Main. Area	CMA03			Review Date	26-Feb-2013		
Clear Roadway/Skew	10 /			Dept. Reviewer Name			
AADT/Year	1,700 / 2012 (A)			Dept. Review Date			
Road Classification	RAU-213.4-120			Follow-Up By			
Detour Length (km)	40			Visual Inspection?	Y		
				CSE Testing?	Y		
				Chloride Testing?	N		
Allowable Load (t):	Single	CS1 35 STRINGER	Semi	CS2 61 STRINGER	Train	CS3 78 GIRDER	----> On Critical Spans ---->Critical Member
Design Loading:	HS20						----> Primary Span
(Primary Span : DT, Spans: 3,4,5, Lengths(m): 61-61-61)							
(Secondary Span : RB, Spans: 1, Lengths(m): 21.3)							
(Secondary Span : RG, Spans: 2,6, Lengths(m): 33.5-33.5)							
(Total Length : 21.3-33.5-61-61-61-33.5 = 271.3)							

Concrete Deck Inspection							
				Last	Now	Explanation of Condition	
Wearing Surface							
Polymer? (Y/N)				N			
ACP? (Y/N)				N			
Chip Seal Coat? (Y/N)				N			
Polymer Rating (% Area)							
	9-7	6/5	4	3	2/1	N/X	
Last							
Now	0	0	0	0	0	100	
ACP Rating (% Area)							
	9-7	6/5	4	3	2/1	N/X	
Last							
Now	0	0	0	0	0	100	
Chip Seal Coat Rating (% Area)							
	9-7	6/5	4	3	2/1	N/X	
Last							
Now	0	0	0	0	0	100	
Polymer Total Debonded /Lost Area (m²)						X	
ACP Total Debonded /Lost Area (m²)						X	
ACP Average Measured Depth (mm)						X	
ACP Crack Frequency (m/m²)						X	
Chip Seal Coat Total Lost Area (m²)						X	
Concrete Overlay							
Overlay? (Y/N)				N			
Deck							
(Span Type : DT)							
(Span Numbers : 3, 4, 5)							
(Deck Type : CONCRETE (MODIFIED SILICA FUME, CORROSION INHIBITOR))							

Concrete Deck Inspection						
		Last	Now	Explanation of Condition		
(Area(m ²) : 1830.0)						
(Year Constructed : 2000)						
(Year Widened :)						
(Thickness(mm) : 150)						
(Average Cylinder Strength(MPa) :)						
	Type		Size	Design Cover (mm)	Spacing (mm)	
Long. Reinforcing	REINFORCING STEEL					
Trans. Reinforcing	REINFORCING STEEL					
Deck Top Rating (% Area)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now	0	100	0	0	0	0
Total Crack Length - Medium/Wide (m)					272	Crack repiars have been completed making crack counting challenging. There are random pop-outs along the deck top
Total Scaled Area - Light (m ²)					0	
Total Scaled Area - Moderate/Heavy/Severe (m ²)					0	
Delaminated Area (m ²)					149	
Spalled Area (m ²)					0	
Patched Area (m ²)					7	
Average Measured Cover Depth (mm)					71	
Standard Deviation of Measured Cover Depth (mm)					10	
Random patching						
Deck Underside Rating (% Area)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now	0	60	0	0	0	40
Total Stained Area - Moderate (m ²)					0	Could not inspect the underside of span 4 due to water levels in the river.
Total Stained Area - Heavy/Severe (m ²)					0	
Total Crack Length - Medium/Wide (m)					111	There is transverse cracking in the deck underside.
% of Medium/Wide Cracks Stained					100	
(Span Type : RB)						
(Span Numbers : 1)						
(Deck Type : CONCRETE (MODIFIED SILICA FUME, CORROSION INHIBITOR))						
(Area(m ²) : 213.0)						
(Year Constructed : 2000)						
(Year Widened :)						
(Thickness(mm) :)						
(Average Cylinder Strength(MPa) :)						
	Type		Size	Design Cover (mm)	Spacing (mm)	
Long. Reinforcing						
Trans. Reinforcing						

Concrete Deck Inspection									
						Last	Now	Explanation of Condition	
Deck Top Rating (% Area)									Transverse cracking repairs have been completed, making it difficult to get an accurate crack count.
	9-7	6/5	4	3	2/1	N/X			
Last									
Now	0	100	0	0	0	0	0		
Total Crack Length - Medium/Wide (m)							24		
Total Scaled Area - Light (m ²)							0		
Total Scaled Area - Moderate/Heavy/Severe (m ²)							0		
Delaminated Area (m ²)							32		
Spalled Area (m ²)							0		
Patched Area (m ²)							0		
Average Measured Cover Depth (mm)							65		
Standard Deviation of Measured Cover Depth (mm)							10		
Deck Underside Rating (% Area)									There is transverse cracking, mostly stained.
	9-7	6/5	4	3	2/1	N/X			
Last									
Now	0	100	0	0	0	0	0		
Total Stained Area - Moderate (m ²)							0		
Total Stained Area - Heavy/Severe (m ²)							0		
Total Crack Length - Medium/Wide (m)							58		
% of Medium/Wide Cracks Stained							90		
(Span Type : RG)									
(Span Numbers : 2, 6)									
(Deck Type : CONCRETE (MODIFIED SILICA FUME, CORROSION INHIBITOR))									
(Area(m ²) : 670.0)									
(Year Constructed : 2000)									
(Year Widened :)									
(Thickness(mm) : 150)									
(Average Cylinder Strength(MPa) :)									
	Type					Size	Design Cover (mm)	Spacing (mm)	
Long. Reinforcing	REINFORCING STEEL								
Trans. Reinforcing	REINFORCING STEEL								
Deck Top Rating (% Area)									Transverse cracking. Crack repairs have been completed, making accurate crack counting difficult.
	9-7	6/5	4	3	2/1	N/X			
Last									
Now	0	100	0	0	0	0	0		
Total Crack Length - Medium/Wide (m)							118		
Total Scaled Area - Light (m ²)							0		
Total Scaled Area - Moderate/Heavy/Severe (m ²)							0		
Delaminated Area (m ²)							53		
Spalled Area (m ²)							0		
Patched Area (m ²)							1		
Average Measured Cover Depth (mm)							69		
Standard Deviation of Measured Cover Depth (mm)							12		
Deck Underside Rating (% Area)									Minor corrosion along the bottom flanges of the girders. There is transverse cracking along the deck underside.
	9-7	6/5	4	3	2/1	N/X			
Last									
Now	0	100	0	0	0	0	0		
Total Stained Area - Moderate (m ²)							0		
Total Stained Area - Heavy/Severe (m ²)							0		
Total Crack Length - Medium/Wide (m)							143		
% of Medium/Wide Cracks Stained							95		
Edge Elements									

Concrete Deck Inspection						
		Last	Now	Explanation of Condition		
Curbs? (Y/N)		Y				
Parapets? (Y/N)		N				
Medians? (Y/N)		N				
Sidewalks? (Y/N)		N				
Curbs						
(Type : CONCRETE)						
(Total Length(m) : 542.6)						
(Height(mm) :)						
(Width(mm) :)						
(Average Cylinder Strength(MPa) :)						
Reinforcement Type			Size	Design Cover (mm)		Spacing (mm)
Curb Rating (% Length)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now	80	20	0	0	0	0
Total Crack Length - Medium/Wide (m)					137	Transverse cracking along the curbs.
Total Scaled Length - Light (m)					0	
Total Scaled Length - Moderate/Heavy/Severe (m)					0	
Delaminated Length (m)					0	
Spalled Length (m)					0	
Patched Length (m)					0	
Average Measured Cover Depth (mm)					85	
Standard Deviation of Measured Cover Depth (mm)					12	
Deck Joints						
(Type : ARMoured GLAND (WABO UNDER FINGER OR SLIDING PLATES))						
(Number of Joints : 4)						
(Expansion / Fixed? : EXPANSION)						
(Location : P1, P2, P3, P4)						
% Inspected				100	There are tears in the east pier joint. Other joints are fairly tight and tears are hard to determine. Previous inspection 06-Jun-2009 indicated leakage in the west pier joint as well as the third pier joint from the west.	
% Joints Leaks				25		
% Joint Length Leaks				10		
Superstructure Damage Rating				6		
Substructure Damage Rating				4		
Level 1 Joint Rating				4		
(Type : FINGER PLATES)						
(Number of Joints : 1)						
(Expansion / Fixed? : EXPANSION)						
(Location : A1)						
% Inspected				100	Water leaks onto the abutment. Abutment is scaled.	
% Joints Leaks				100		
% Joint Length Leaks				100		
Superstructure Damage Rating				6		
Substructure Damage Rating				4		
Level 1 Joint Rating				4		
(Type : GLAND (WABO-MAUER, TRANSFLEX, ETC))						
(Number of Joints : 1)						
(Expansion / Fixed? : EXPANSION)						
(Location : P5)						

Concrete Deck Inspection									
		Last	Now	Explanation of Condition					
% Inspected			100						
% Joints Leaks			25						
% Joint Length Leaks			10						
Superstructure Damage Rating			6						
Substructure Damage Rating			4						
Level 1 Joint Rating			4						
(Type : GLAND (WABO-MAUER, TRANSFLEX, ETC))									
(Number of Joints : 1)									
(Expansion / Fixed? : FIXED)									
(Location : A2)									
% Inspected			100	Water is leaking past plumbing at the south end.					
% Joints Leaks			100						
% Joint Length Leaks			5	Abutment is severely scaled, with exposed rebar.					
Superstructure Damage Rating			6						
Substructure Damage Rating			4						
Level 1 Joint Rating			4						
CSE Testing									
Testing Date		15-Jun-2012			Previous Testing Date		16-Jul-2009		
Weather Information									
Temperature (°C)		19							
Conditions		Sunny							
Equipment Information									
Test Equipment Make and Model		Corexco CDL - 200 EA/512							
Electrical Ground Location and Type		1DD, third deck joint from the west							
Measurement Locations Information									
Origin for Data		south west							
		Number		Length of Each (m)		Length of Last (m)			
X Increments (Length)		113		1.219		1.200			
Y Increments (Width)		9		1.219		0.300			
CSE Results									
Span Numbers		1,2,3,4,5,6							
Span Type		DT, RB, RG							
Wearing Surface		CONCRETE (MODIFIED SILICA FUME, CORROSION INHIBITOR)							
Testing Year	% Deck Area 0 to -0.1 V	% Deck Area < -0.1 to -0.2 V	% Deck Area < -0.2 to -0.3 V	% Deck Area < -0.3 to -0.4 V	% Deck Area < -0.4 V	Avg. Deck Reading (V)	Std. Dev. Deck Reading	Avg. Curb Reading (V)	Std. Dev. Curb Reading
2012	0.2	11.3	49.1	31.1	8.3	-0.281	0.094	-0.295	0.082
2009	0.0	15.0	53.0	27.0	5.0	-0.266	-0.084	-0.257	-0.083
2008	0.0	6.0	47.0	40.0	7.0	-0.295	0.083	-0.266	0.073
CSE Prediction Model Optimum 5 year Rehab Start Year		2015							
Comments									

Maintenance Recommendations										
Inspector Recommendations	Year	Inspector Comments			Department Comments			Target Year	Est. Cost	Cat #
SEAL CURBS										
PATCH DECK										
SEAL DECK										
OVERLAY DECK										
REPAIR/REPLACE DECK JOINTS										
WASHING										
CRACK REPAIRS/TREATMENT										
PATCH CURBS/PARPETS										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
Structural Condition Rating (%)	38.9	Sufficiency Rating (%)			36.1			Est Repl Year	2044	
Level 1 Insp Date	03-Dec-2012	Next Level 1 Insp Date			03-Sep-2014		Current Level 1 Insp Cycle (Default) (Months)			21
Special Comments for Next Insp	Monitor headslope movement and scour at SE headslope/pier. Monitor concrete pier abrasion.									
Snooper? (Y/N)	No	Lift? (Y/N)	No	Traffic Control? (Y/N)	Yes	Boat? (Y/N)	No	Ladder? (Y/N)	No	
Other Special Requirements Comments	Converted from CDIS									
Previous Level 2 Inspector's Name	Jason Saly				Previous Level 2 Insp Date		16-Jul-2009			
Next Level 2 Insp Date	11-Sep-2016				Discontinue Level 2 Insp? (Y/N)		No			
Level 2 Insp Previously Completed	16				Level 2 Insp Cycle (Default) (Months)		48			
Detailed Report/Diagram? (Y/N)	Yes									
Level 2 Insp Comments	Bearings at the east pier are deforming at on site indicating that they may be rehabed soon									
Next Level 2 Inspection/Test	Concrete Deck Insp? (Y/N)			Yes	CSE Testing? (Y/N)		Yes	Chloride Testing? (Y/N)		No
Department Reviewer Comments										