

Bridge Culvert Inspection				
Bridge File Number	74683 -1 Bridge Culvert		Form Type	CUL1
Year Built	1957		Lot No.	4
Bridge or Town Name	CARBON		Inspector Name	Owen Salava
Located Over	TRAIL-ANIMAL, OVER SP		Inspector Class	BR CLS A
Located On	21:14 C1 16.381		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	18-Sep-2012
Legal Land Location	NW SEC 31 TWP 29 RGE 23 W4M		Data Entry By	Marcia Chavez
Longitude, Latitude	-113:14:23, 51:31:50		Data Entry Date	03-Oct-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	John O'Brien
Contract Main. Area	CMA20		Review Date	27-Sep-2012
Clear Roadway/Skew	11 /		Dept. Reviewer Name	Andrew Smikles
AADT/Year	2,490 / 2011 (A)		Dept. Review Date	16-Oct-2012
Road Classification	RAU-211.8-110		Follow-Up By	
Detour Length (km)	3			

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	1800	1800	BPR	33			RECTANGLE
Special Features								
Special Features Comment								

**Posting Information**

Required Vert. Clearance Posting (m)												
Posted Vertical Clearance (Y/N)												
Posted:	Lane	NB	On Bridge (m)		In Advance (Y/N)	No	Lane	SB	On Bridge (m)		In Advance (Y/N)	No
Remarks	Not required.											

**Utilities (Located at)**

Utility Attachments												
Telephone	West ditch.					Gas						
Power	2 wire crosses road 40m North.					Municipal						
Others	Fibre optic E r/w.					Problem (Y/N)		No				
Remarks												

**Approach Road / Embankment**

		Last	Now	Explanation of Condition
Horizontal Alignment		8	8	Farm ent 20 m North. On crest of hill. Limited sight distance. No passing both directions.
Vertical Alignment		6	6	
Roadway Width (m)	11.000			
Embankment		7	7	Numerous transverse cracks in ACP over & near pipe - sealed.
Sideslope (___:1)	3.0			
(Height of Cover(m) : 1)				
Guardrail (Y/N)	Yes			
<b>Approach Road / Embankment General Rating</b>		<b>6</b>	<b>6</b>	

**Upstream End**

Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		6	6	Isolated medium crack - Minor.
Collar		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Wingwalls (Shape : )		6	6	Wings are moving away from the barrel to 50 mm (photo). (Some heaving of floor in West apron to 50 mm and 3 mm wide cracks. 22Feb2008).
Cutoff Wall		N	N	Covered by dirt, not visible.
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	50			
Scour Protection (Type : <b>NATURAL</b> ) (Avg. Rock Size(mm) : )		6	6	
Scour/Erosion		6	6	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>6</b>	<b>6</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1800, Rise (mm): 1800, Type: BPR)</b>				
Barrel Last Accessible Date	18-Sep-2012			
<b>Special Features</b>				
Special Feature (Type : )				
Special Feature (Type : )				
Roof		7	7	Midspan
Measured Rise (mm)	1800			
Measured At Ring No.				
Sag (mm)	0			
Percent Sag				
Sidewall		6	6	Minor honeycomb at South wall (is leaking in this area. 95/08/23). - not evident this inspection.
Measured Span (mm)	1825			
Measured At Ring No.				
Deflection (mm)	25			
Percent Deflection				
Floor		N	N	Mud covered - avg 100 mm deep.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		X	X	No circumferential seams, just form lines.
Separation (mm)	0			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1800, Rise (mm): 1800, Type: BPR)				
Coating		X	X	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type : )				
Waterway Adequacy		8	8	Takes some drainage West to East.
Icing (Y/N)	No			
Siltting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>6</b>	<b>6</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		5	5	Cracking - minor.
Collar		X	X	
Wingwalls		7	7	Wings have moved away from barrel to 40 mm.
(Shape : )				
Cutoff Wall		X	N	Apron floor covered by dirt.
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		6	6	
(Type : <b>NATURAL</b> )				
(Avg. Rock Size(mm) : )				
Scour/Erosion		6	6	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>5</b>	<b>5</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Grade Separation</b>				
Road Alignment		6	6	U/S apron cracked and heaved 50 mm.
Roadway Surface		5	5	Up to 100mm mud at D/S 1/3.
(Type : )				
Icing (Y/N)	No			
Traffic Safety Features		X	X	
Type	None			

Structure Usage				
		Last	Now	Explanation of Condition
Lighting		X	X	
Barrel Leakage (Y/N)	Yes			None at this inspection.
Drainage		6	6	
Structure In Use (Y/N)	Yes			Still in use by farmer on W side.
<b>Grade Separation General Rating</b>		<b>5</b>	<b>6</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>66.7/66.7</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>68.8/69.5</b>	Est. Repl. Yr	2030	Maint. Req. (Y/N)	No
Special Comments for Next Inspection	Monitor leakage & wingwall movement. This pipe handles some drainage.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)	N						
Proposed Action	2006.10.24 Revisit site in two years to check for continued usage.						
Previous Inspector's Name	Dave Lam		Previous Assistant's Name				
Next Inspection Date	18-Jun-2014		Previous Inspection Date	10-Nov-2010			
Inspection Cycle (Default) (months)	21						
Comment							