

Bridge Culvert Inspection			
Bridge File Number	74941 -1 Bridge Culvert	Form Type	CUL1
Year Built	1958	Lot No.	1
Bridge or Town Name	ARMENA	Inspector Name	Owen Salava
Located Over	TRIBUTARY TO CAMROSE CREEK, 5.44.2, WATERCRS-ST	Inspector Class	BR CLS A
Located On	21:24 C1 12.905	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	20-Sep-2012
Legal Land Location	NE SEC 11 TWP 48 RGE 21 W4M	Data Entry By	Marcia Chavez
Longitude, Latitude	-112:57:32, 53:07:51	Data Entry Date	03-Oct-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	John O'Brien
Contract Main. Area	CMA16	Review Date	27-Sep-2012
Clear Roadway/Skew	11.1 / 7 deg. (RHF)	Dept. Reviewer Name	Andrew Smikles
AADT/Year	5,010 / 2011 (A)	Dept. Review Date	22-Oct-2012
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	3		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	1829	1118	FP	30.5	68X13	3.5	ARCH
Special Features	CONC FLOOR							
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	East r/w.	Gas	
Power		Municipal	
Others	Fibre optic E r/w.	Problem (Y/N)	No
Remarks			

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		5	5	In curve, superelevated.
Vertical Alignment		8	8	
Roadway Width (m)	11.100			
Embankment		6	6	West side measured.
Sideslope (__:1)	3.0			
(Height of Cover(m) : 2.1)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		5	5	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		4	4	Moderate rusting/pitting. Bevel edge caps separated.
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		5	5	Overgrown with vegetation.
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Upstream End General Rating		4	4	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1829, Rise (mm): 1118, Type: FP)				
Barrel Last Accessible Date	20-Sep-2012			
Special Features				
Special Feature		4	4	Numerous transverse cracks.
(Type : CONC FLOOR)				
Special Feature				
(Type :)				
Roof		4	4	Roof to concrete floor 910mm. (Est roof sag 5%.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	100			
Percent Sag				
Sidewall		3	3	Some inward bulging due to corrosion & weakening of sidewall. Corrosion with loss of section.
Measured Span (mm)	1840			
Measured At Ring No.	2			
Deflection (mm)	11			
Percent Deflection				
Floor		N	N	Concrete covered.
Bulge (mm)	25			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		4	4	Minor infiltration.
Separation (mm)	65			
Longitudinal Seams		3	3	Riveted seams. Rivets in sidewall seams are corroding.
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			
Coating		3	3	Heavy sidewall corrosion & loss of section weakening sidewall at haunch area.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1829, Rise (mm): 1118, Type: FP)				
Fish Passage Adequacy		X	X	Only at high water.
Baffle (Type :)		X	X	
Waterway Adequacy		5	5	
Icing (Y/N)		No		
Siltting (Y/N)		No		
Drift (Y/N)		No		
Barrel General Rating		3	3	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)		STEEL		
Headwall		X	X	
Collar		X	X	
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	
Bevel End		4	4	Moderate corrosion below waterline. Bevel edge cap separated.
Heaving (mm)		0		
Invert Above/Below Stream Bed				
Above/Below (mm)		0		
Scour Protection		5	5	Well vegetated.
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		5	5	
Beavers (Y/N)		No		
Downstream End General Rating		4	4	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		6	6	
Bank Stability		6	6	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)		No		
Channel Bottom Degrading/Aggrading				Unknown.
Beavers (Y/N)		No		
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		6	6	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2015	Program for replacement.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	33.3/33.3	Sufficiency Rating (Last/Now) (%)	40.4/40.3	Est. Repl. Yr	2015	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	Inspect at reg BIM cycle until replaced.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy	2004.05.30 Montior normal BIM. Culvert should be ok until 2013.						
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Dave Lam		Previous Assistant's Name				
Next Inspection Date	20-Jun-2014		Previous Inspection Date	08-Nov-2010			
Inspection Cycle (Default) (months)	21						
Comment							