

Bridge Culvert Inspection			
Bridge File Number	74993 -1 Bridge Culvert	Form Type	CULM
Year Built	1991	Lot No.	4
Bridge or Town Name	PADDLE PRAIR	Inspector Name	Russel Vanderschaaf
Located Over	TRIBUTARY TO BOYER RIVER, 8.10.23.10, WATERCRS-ST	Inspector Class	BR CLS B
Located On	35:12 C1 43.484	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	15-Nov-2011
Legal Land Location	NE SEC 25 TWP 104 RGE 21 W5M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-117:19:17, 58:03:44	Data Entry Date	13-Dec-2011
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Eric Carcoux
Contract Main. Area	CMA01	Review Date	12-Dec-2011
Clear Roadway/Skew	10.8 /	Dept. Reviewer Name	Steve Pasquan
AADT/Year	900 / 2010 (A)	Dept. Review Date	10-Jan-2012
Road Classification	RAU-213.4-120	Follow-Up By	
Detour Length (km)	999		

**Bridge Culvert Information**

Number of Culverts	2							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2000	MP	30	125X26	2.8	ROUND
2	MAIN	-	2000	MP	30	125X26	2.8	ROUND
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments			
Telephone	Buried line on W ditch.	Gas	
Power	5 wire O/H along W. ditch.	Municipal	
Others		Problem (Y/N)	No
Remarks			

**Approach Road / Embankment**

		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	RESIDENCE ENTRANCE 60M N.
Vertical Alignment		9	8	
Roadway Width (m)	10.800			
Embankment		7	7	
Sideslope (__:1)	3.5			
(Height of Cover(m) : 1)				
Guardrail (Y/N)	No			
<b>Approach Road / Embankment General Rating</b>		<b>7</b>	<b>7</b>	

**Upstream End**

Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 1, Span Type: Primary Span)</b>				
Direction		W		(south pipe)
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 1, Span Type: Primary Span)</b>				
Cutoff Wall		X	X	
Bevel End		5	4	Pulled inward due to dent @ 10:00 in u/s barrel section . Under 1.6M at water
Heaving (mm)	250			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	150			
Scour Protection		N	N	Covered with snow.
(Type : <b>NATURAL</b> ) (Avg. Rock Size(mm) : )				
Scour/Erosion		N	N	Covered with snow.
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>5</b>	<b>4</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2000, Type: MP)</b>				
Barrel Last Accessible Date	15-Jan-2003			(South barrel)
<b>Special Features</b>				
Special Feature				Barrel shape appears good when viewed from ends.-15-Jan-2003 Dents in end of barrel at both ends.
(Type : )				
Special Feature				
(Type : )				
Roof		N	N	(Roof sag 20010510)  est
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	70			
Percent Sag				
Sidewall		N	N	
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)				
Percent Deflection				
Floor		N	N	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	N	(35 mm of seperation in the center of pipe - 940207).
Separation (mm)	35			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		5	N	Superficial rust above ice. Visible from u/s end.-15-Jan-2003
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2000, Type: MP)				
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	Yes			(1.6 m water ponding.-20010510)
Fish Passage Adequacy		7	8	
Baffle		X	X	
(Type : )				
Waterway Adequacy		6	6	(Pipe is always over 1/2 full of water-May 16, 2008.)
Icing (Y/N)	No			(Icing in culvert - 940207).
Silting (Y/N)	Yes			
Drift (Y/N)	Yes			
<b>Barrel General Rating</b>		<b>6</b>	<b>N</b>	GR was 6 on 15-Jan-2003
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Direction		E		(south pipe)
End Treatment (Concrete, Steel, Others, None)	STEEL			Ice to 500mm below crown.
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		5	N	Dent on top of bevel.
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		N	N	Ice 500mm below crown.
(Type : <b>NATURAL</b> )				
(Avg. Rock Size(mm) : )				
Scour/Erosion		N	N	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>5</b>	<b>5</b>	GR carried fwd 18-Feb-2010
Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Direction		W		(North pipe)
End Treatment (Concrete, Steel, Others, None)	STEEL			Ice to 600mm below crown.
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 2, Span Type: Secondary Span)</b>				
Cutoff Wall		X	X	
Bevel End		5	N	Dent on top of bevel.
Heaving (mm)	250			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	150			
Scour Protection		N	N	Ice 600 mm below crown
(Type : <b>NATURAL</b> )				
(Avg. Rock Size(mm) : )				
Scour/Erosion		N	N	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>5</b>	<b>5</b>	GR carried over 18-Feb-2010

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2000, Type: MP)</b>				
Barrel Last Accessible Date	27-Nov-2004			(North barrel). Ice approx. 600mm below crown.
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		N	N	
Measured Rise (mm)				estimated
Measured At Ring No.				
Sag (mm)	80			
Percent Sag				
Sidewall		N	N	
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)				
Percent Deflection				
Floor		N	N	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	N	(25 mm of seperaton on east end of pipe where the last joints meet 94/02/07)
Separation (mm)	25			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		5	N	Superficial rust visible above ice.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			

Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2000, Type: MP)					
Camber POS/ZERO/NEG	NEG				
Ponding (Y/N)	Yes				
Fish Passage Adequacy		8	8		
Baffle		X	X		
(Type : )					
Waterway Adequacy		6	6	(Pipe is always over 1/2 full of water - 20010510)	
Icing (Y/N)	No				
Silting (Y/N)	No				
Drift (Y/N)	Yes				
<b>Barrel General Rating</b>		<b>N</b>	<b>N</b>		
Downstream End					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 2, Span Type: Secondary Span)					
Direction		E		(North pipe) Ice to 500 below crown.	
End Treatment (Concrete, Steel, Others, None)	STEEL				
Headwall		X	X		
Collar		X	X		
Wingwalls (Shape : )		X	X		
Cutoff Wall		X	X		
Bevel End		5	N	Dent on top of bevel.	
Heaving (mm)					
Invert Above/Below Stream Bed	BELOW				
Above/Below (mm)	100				
Scour Protection		N	N	Ice 500mm below crown	
(Type : <b>NATURAL</b> )					
(Avg. Rock Size(mm) : )					
Scour/Erosion		N	N		
Beavers (Y/N)	No				
<b>Downstream End General Rating</b>		<b>5</b>	<b>5</b>	GR carried forward.-18-Feb-2010	
Structure Usage					
		Last	Now	Explanation of Condition	
<b>Channel (U/S and D/S)</b>					
Alignment		7	7		
Bank Stability		7	7		
HWM (m below Top of Culvert)				HWM NOT VISIBLE	
Drift (Y/N)	Yes				
Channel Bottom Degrading/Aggrading	NONE				
Beavers (Y/N)	No				
(Fish Compensation Measure 1 : <b>NONE</b> )					
(Fish Compensation Measure 2 : <b>NONE</b> )					

<b>Structure Usage</b>				
		<b>Last</b>	<b>Now</b>	<b>Explanation of Condition</b>
<b>Channel General Rating</b>		<b>7</b>	<b>7</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>66.7/55.6</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>61.6/55.1</b>	Est. Repl. Yr	2030	Maint. Req. (Y/N)	No
Special Comments for Next Inspection	Monitor dent u/s and d/s of bevels of South pipe. Monitor heaving u/s ends.-May16-2008		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Brian Pientsch		Previous Assistant's Name	Lisbeth Medina			
Next Inspection Date	15-Aug-2013		Previous Inspection Date	18-Feb-2010			
Inspection Cycle (Default) (months)	21						
Comment							