

Bridge Inspection							
Bridge File Number	75112 -1 Bridge			Form Type	PSR		
Year Built/Year Supstr	1961/1961			Lot No.	2		
Bridge or Town Name	SEEBE			Inspector Name	Garry Roberts		
Located Over	CPR			Inspector Class	BR CLS A		
Located On	1X:02 C1 2.078			Assistant Name			
Water Body Cl./Year				Assistant Class			
Navigabil. Cl./Year				Inspection Date	30-Jul-2012		
Legal Land Location	NW SEC 33 TWP 24 RGE 8 W5M			Data Entry By	Lauren Korte		
Longitude, Latitude	-115:03:49, 51:05:34			Data Entry Date	02-Sep-2012		
Road Authority	Alberta Transportation (AIT)			Reviewer Name	Tom Carey		
Contract Main. Area	CMA28			Review Date	07-Aug-2012		
Clear Roadway/Skew	11 /			Dept. Reviewer Name	Tim Davies		
AADT/Year	1,030 / 2011 (A)			Dept. Review Date	06-Sep-2012		
Road Classification	RAU-211.8-110			Follow-Up By			
Detour Length (km)	50						
Allowable Load (t):	Single	CS1 38 GIRDER	Semi	CS2 49 GIRDER	Train	CS3 65 GIRDER	----> On Critical Spans ---->Critical Member
Design Loading:	HS20						----> Primary Span

Posting Information												
Required Vert. Clearance Posting (m)												
Posted Vertical Clearance (Y/N)				No								
Posted:	Lane	NB	On Bridge (m)		In Advance (Y/N)	No	Lane	SB	On Bridge (m)		In Advance (Y/N)	No
Remarks		Not required.										
Required Load Posting (t)				Single			Semi			Truck Train		
Posted Loading (t)				Single			Semi			Truck Train		
Posted:	Lane	NB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No				
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No				
Remarks		Not required.										

Hazard Marker At Bridge (Y/N)	Yes
Remarks	
Other Sign Types	

Utilities (Located at)			
Utility Attachments	OTHER UTILITIES-OTHER LINES; TELEPHONE UTILITIES-PHONE LINE		
Telephone	Under bridge @ railway.	Gas	East of overpass.
Power	West side - 4 lines.	Municipal	
Others	Telegraph lines under deck @ South pier. Fibre optics @ West r/w & under bridge.	Problem (Y/N)	No
Remarks			

Approach Road				
		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	On crest curve.
Vertical Alignment		6	6	
Roadway Width (m)	12.000			
Approach Bump		6	6	
Guardrail (Y/N)	Yes			Has steel I posts @ 0.9m spacing but insufficient posts @ 1.9m spacing. 2 split posts at NW. Not thriebeam.
Guardrail		6	4	
Length (m)	99.000			
Current Standard (Y/N)	No			
Termination Type	TURNED DOWN			
Drainage		7	7	

Approach Road				
		Last	Now	Explanation of Condition
Approach Road General Rating		6	6	
Superstructure				
Bridge Component		Last	Now	Explanation of Condition
(Primary Span : PO, 3 Spans, Lengths(m): 18.3-18.3-18.3, A-Ident Number:)				
Special Features				
Special Feature			X	
(Type :)				
Special Feature			X	
(Type :)				
Wearing Surface/Deck Top Detail Ratings				
	N (%)	1 (%)	2 (%)	3 (%)
Last	0	0	0	0
Now	0.0	0.0	0.0	0.0
Wearing Surface		7	7	
(Material Type : CONCRETE - CONVENTIONAL CHIP SEAL COAT)				
(Thickness(mm) : 50)				
Lateral Connection Problem (Y/N)	No			
Deck Top		N	N	
Deck Rideability		7	7	
Deck Joints		7	7	
Temperature (deg. C)		20		
(Expansion Type : GLAND (WABO-MAUER, TRANSFLEX, ETC))				
(Fixed Type :)				
Gap Size (mm)		Gap Location		
75	South abutment			
70	South pier			
75	North pier			
75	North abutment			
Deck Drainage		4	4	Drains disconnected @ Both sides of North pier.
Drains Clogged (Y/N)		No		
Curbs/Median		4	4	Spall at SW concrete curb 500 X 260 X 200.
(Curb Type : Standard)				
Scaling (Percent Area)		2		
Bridge Rail		7	7	Missing 1 A/B at West rail over pier 2 and 1 at East rail Sp. 3- 2 A/B nuts with insufficient thread at SW.
(Type : BRIDGE TUBE)				
Bridge Rail Posts		3	3	
(Type : GALVANIZED POST STEEL;GALVANIZED POST STEEL)				
Bridge Rail/Posts Coating		6	6	
(Type :)				
Sidewalk		X	X	
Girder Detail Ratings				
	N (count)	1 (count)	2 (count)	3 (count)
Last	0	0	0	0
Now	0	0	0	0

Superstructure				
Bridge Component		Last	Now	Explanation of Condition
(Primary Span : PO, 3 Spans, Lengths(m): 18.3-18.3-18.3, A-Ident Number:)				
Girders		7	7	
Cracking (Y/N)	No			
Spalling (Percent Area)	0			
(Number Of Girders : 18)				
Diaphragms/Cross Frame		7	7	Diaphragms have 5% corrosion @ South abutment, North abutment re-coated.
Bearings		7	7	
Temperature (deg. C)	20			
(Expansion Type : SLIDING PLATE)				
(Fixed Type : PINNED BEARING)				
Coating Adequate (Y/N)	Yes			
Functioning (Y/N)	Yes			
Deck Underside		7	7	Some scaling @ deck underside exit.
Stains (Percent Area)	2			
Span Alignment Problems				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
Superstructure General Rating		7	7	
Substructure				
Bridge Component		Last	Now	Explanation of Condition
Abutments				
Bearing Seats/Caps		6	6	
(Type : CONCRETE)				
Backwalls/Breastwalls		6	6	
Wingwalls		7	7	
Piles		N	N	Buried.
Paint/Coating		X	X	
Abutment Stability		7	7	
Scour/Erosion		X	X	
Piers/Bents				
(Type : PIER-COLUMN)				
Bearing Seats/Caps		6	6	
(Type : CONCRETE)				
(Total Number of Bearing Piles : 4:4)				Random cracks in all piles.
Pier Shaft/Piles		6	6	
Bracing/Struts/Sheathing		X	X	
Nose Plate		X	X	
Paint/Coating		X	X	
(Colour Description :)				
(Colour Code :)				
Pier Stability		7	7	
Scour		X	X	

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Debris (Y/N)	No			
Substructure General Rating		6	6	
Structure Usage				
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		X	X	
Traffic Safety Features		X	X	
Type				
Slope Protection		7	7	
(Type : NATURAL; NATURAL)				
Bank Stability		7	7	
Drainage		7	7	
Grade Separation General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL	2012	Replace 2 post A/B. Replace 2 posts at NW approach.					
GALVANIZE/PAINT BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
SEAL DECK							
OVERLAY DECK							
REPAIR/REPLACE DECK JOINTS							
RESET/ PAINT BEARINGS							
WASHING							
SHOTCRETE REPAIRS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
OTHER ACTION	2012	Re-connect drains at both ends of P2.					
OTHER ACTION	2012	Repair SW curb spall 0.03m3.					
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	72.2/72.2	Sufficiency Rating (Last/Now) (%)	64.7/64.7	Est. Repl. Yr	2035	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	30-Apr-2014		Previous Inspection Date	29-Sep-2010			
Inspection Cycle (Default) (months)	21						
Comment							