						Brida	e Culve	ert Insp	ection						
Bridge File Nur	mber 751	75 -1 F	Bridge C	ulvert				Form 1			CUL1				
Year Built	196		Dilago C	417011				Lot No.			4				
Bridge or Town								Inspector Name		Jon Davies					
Located Over			IIMAL, O	\/ED	SP			<u> </u>	tor Class		BR CLS B				
Located On			34.655	VLIX	01				ant Name		DIX CLO D				
		0001	34.000												
Water Body Cl.								Assistant Class			44 lan 2042				
Navigabil. Cl./Y		050.6	04 TWD	40 005	45 1014	4 / 4		Inspection Date			11-Jan-2012				
Legal Land Loc			21 TWP		15 VV4	+IVI			Data Entry By Anne Roberts						
Longitude, Latitude -112:01:05, 50:31:58 Road Authority Alberta Transportation (AIT)							Data Entry Date 25-Feb-2012								
Road Authority Alberta Transportatio Contract Main. Area CMA23				tion (Al⊺	n (AIT)				er Name	9	Garry Roberts				
								/ Date		20-Jan-2012					
Clear Roadway									Dept. Reviewer Name Tim Davies						
AADT/Year	2,26	0 / 20	10 (A)					Dept. Review Date		11-Mar-2012					
Road Classifica		J-211.8	8-110					Follow-Up By							
Detour Length	(km) 6														
Bridge Culver	t Informatio	n													
Number of Cul	verts	1													
Pipe #	Barrel	Sp	oan	Ris	se (or D	Dia.)	Туре		Length		Corr. Profile	Pl./Slab Thickness	Shape		
1	MAIN	-		180	00		СР		26				ROUND		
Special Feature	es	CC	ONC FLO	OOR											
Special Feature	es Comment														
						Ро	sting li	nformat	ion						
Required Vert.															
Posted Vertica				No											
Posted: Lane			dge (m)		n Adva	ance (Y/N)	L	ane SB	3 C	n Bridge (m)	In Advan	ce (Y/N)		
Remarks	Not require	ed				Uti	lities (L	_ocated	at)						
Utility Attachme	ents						,		<u> </u>						
Telephone	West ditch							Gas		Cross	ses road 100 m	south			
Power	3 line 30 m	n east						Munici	oal						
Others	Water & oi		100 m s	outh					m (Y/N)	No					
Remarks	Fibre option							1. 102.0	(1711)	1.10					
Homano	T IDTO OPTIO	Cabic	Woot ait	011	An	proac	:h Roa	d / Emb	ankment						
						Last	Now	1			tion				
Horizontal Alig	nment					9	9	Explanation of Condition							
Vertical Alignm						9	9								
Roadway Widtl			11.400				<u> </u>								
Embankment						8	7								
	.1\		4.0			0	/								
Sideslope (4.0					-							
(Height of Cover(m): 0.8)															
Guardrail (Y/N) Yes															
Approach Roa	ad / Embank	ment	General	Rating		9	9								
								am End							
Culvert Comp	onent					Last	Now	Explar	ation of	Condi	tion				
Direction			1	W											
End Treatment Others, None)	End Treatment (Concrete, Steel, Others, None)														
Headwall						Χ	X								
Collar						Х	Х								

75175 -1 Bridge Culvert

Culvert Common and				Explanation of Condition
Culvert Component		Last	Now	Explanation of Condition
Wingwalls		X	X	
(Shape:)			T 1/	
Cutoff Wall		X	X	
Bevel End	1	X	X	
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		X	7	
(Type : NATURAL)				
(Avg. Rock Size(mm):)			_	
Scour/Erosion		X	7	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	
		Bri	dae Cu	lvert Barrel
Culvert Component			Now	Explanation of Condition
(Pipe # : 1, Primary Span, Loca	tion Code: MAIN, Sp			, Rise (mm): 1800, Type: CP)
Barrel Last Accessible Date	11-Jan-2012		<i>,</i>	
Special Features				
Special Feature			4	Spalls on flr throughout some with
(Type : CONC FLOOR)			_	exposed steel 4 sections were held together by steel
Special Feature				cable. Cable is broken at both ends
(Type:)				
Roof		6	5	Minor spall at East end
Measured Rise (mm)	1984			
Measured At Ring No.	1			
Sag (mm) 0				
Percent Sag	0			
Sidewall		6	6	Hairline to medium width longitudinal cracks throughout
Measured Span (mm)	1838			
Measured At Ring No.	1			
Deflection (mm)	0			
Percent Deflection	0			
Floor		4	N	Concrete floor
Bulge (mm)	0			
Measured At Ring No.	1			
Abrasion (Y/N)	No			
Circumferential Seams	-	5	4	Caulked with foam.
Separation (mm)	20	3	-	Minor infiltration of soil at 4 seams
Longitudinal Seams		X	X	
Total No. of Cracked Rings		^		
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		Х	X	
Corrosion By Soil (Y/N)				1
Corrosion By Water (Y/N)				
John Dy Waler (1/14)				2 2 of 5

		Brid	dge Cu	vert Barrel				
Culvert Component		Last Now		Explanation of Condition				
(Pipe #: 1, Primary Span, Loca	tion Code: MAIN, Spa	n (mm):	, Rise (mm): 1800, Type: CP)				
Camber POS/ZERO/NEG	ZERO							
Ponding (Y/N)	No							
Fish Passage Adequacy		Х	Х					
Baffle		Х	Х					
(Type:)			1					
Waterway Adequacy	I	X	7	Carries ditch drainage				
Icing (Y/N)	No							
Silting (Y/N)	No							
Drift (Y/N) No			1					
Barrel General Rating		6	5					
	l			eam End				
Culvert Component		Last	Now	Explanation of Condition				
Direction		Е						
End Treatment (Concrete, Steel, Others, None)	NONE							
Headwall		Х	Х					
Collar		Х	X					
Wingwalls		Х	Х					
(Shape:)								
Cutoff Wall		Х	Х					
Bevel End		Х	Х					
Heaving (mm)								
Invert Above/Below Stream Bed	BELOW							
Above/Below (mm)	150							
Scour Protection		Х	7					
(Type : NATURAL)								
(Avg. Rock Size(mm):)								
Scour/Erosion		Х	7					
Beavers (Y/N)	No							
Downstream End General Ratio	ng	7	7					
		s	tructu	e Usage				
		Last	Now	Explanation of Condition				
Grade Separation			1					
Road Alignment		X	X					
Roadway Surface		7	7					
(Type : SOIL)								
Icing (Y/N)	No							
Traffic Safety Features		Х	Х					
Туре								
Lighting		Х	X					
Barrel Leakage (Y/N)	No							

Structure Usage								
			Now	Explanation of Condition				
Drainage		4	4	Ponds water 50mm deep at East half				
Structure In Use (Y/N) No				Fencing guide down at West Closed off at east and west at fence line				
Grade Separation General Rating			4					

		Maint	enance Recommend	lations					
Inspector Recommendations	Year	Inspector Comments		Department Con	nments		Target Year	Est. Cost	Cat #
SHOTCRETE REPAIRS									
PLACE ADDITIONAL RIP RAP									
REMOVE DRIFT ACCUMULATION									
INSTALL CONCRETE/STEEL LINING	3								
INSTALL STRUTS									
INSTALL CONCRETE COLLAR/CUT	OFF								
REPAIR SEAMS									
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
Structural Condition Rating (Last/N (%)	low) 66.7/5	5.6 Sufficiency Rat (%)	ting (Last/Now)	76.0/61.9	Est. Repl. Yr	2021	Maint. Re	qd. (Y/N)	No
Special Comments for Next Inspection				Department Comments					
Maintenance Reviewed By				Date		E	stimated Tota	0	
Proposed Long-Term Strategy									
On 3-Year Program (Y/N)									
Proposed Action									
Previous Inspector's Name	Tom Carey		Previous	Assistant's Name					
Next Inspection Date	11-Oct-2013		Previous	Inspection Date	22-Jun-2010				
Inspection Cycle (Default) (months)	21								
Comment									