

Level 2 Inspection - Concrete Deck									
Bridge File Number	75195 W-2 Bridge				Form Type	CDK			
Year Built/Year Supstr	1961/1961				Lot No.				
Bridge or Town Name	CARVEL CORNE				Inspector Name	Jason Saly			
Located Over	43:22 R1 23.819;43:22 L1 23.856				Inspector Class	BR CLS A			
Located On	16:12 L1 51.547				Assistant Name				
Water Body Cl./Year					Assistant Class				
Navigabil. Cl./Year					Inspection Date	02-Aug-2012			
Legal Land Location	SW SEC 15 TWP 53 RGE 2 W5M				Data Entry By	Jason Saly			
Longitude, Latitude	-114:13:17, 53:34:13				Data Entry Date	22-Jan-2013			
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Paul Carter			
Contract Main. Area	CMA11				Review Date	25-Feb-2013			
Clear Roadway/Skew	12.2 / 38 deg. (RHF)				Dept. Reviewer Name				
AADT/Year	17,030 / 2012 (A)				Dept. Review Date				
Road Classification	RAD-412.4-120				Follow-Up By				
Detour Length (km)	1				Visual Inspection?	Y			
					CSE Testing?	Y			
					Chloride Testing?	N			
Allowable Load (t):	Single	CS1 28	Semi	CS2 49	Train	CS3 62	----> On Critical Spans ---->Critical Member		
Design Loading:	HS20						----> Primary Span		
(Primary Span : RB , Spans: 1,2,3 , Lengths(m): 14-24.4-17.1)									
(Total Length : 14-24.4-17.1 = 55.5)									

Concrete Deck Inspection

		Last	Now	Explanation of Condition			
Wearing Surface							
Polymer? (Y/N)	Y						
ACP? (Y/N)	N						
Chip Seal Coat? (Y/N)	Y						
	Type	Year Installed	Avg. Total Thickness (mm)		Area (m²)		
Seal Coat	CONVENTIONAL CHIP SEAL COAT	1994			677.1		
Polymer Rating (% Area)							
	9-7	6/5	4	3	2/1	N/X	
Last							
Now	0	0	0	0	0	100	
ACP Rating (% Area)							
	9-7	6/5	4	3	2/1	N/X	
Last							
Now	0	0	0	0	0	100	
Chip Seal Coat Rating (% Area)							
	9-7	6/5	4	3	2/1	N/X	
Last							
Now	100	0	0	0	0	0	
Polymer Total Debonded /Lost Area (m²)							2
ACP Total Debonded /Lost Area (m²)							X
ACP Average Measured Depth (mm)							X
ACP Crack Frequency (m/m²)							X
Chip Seal Coat Total Lost Area (m²)							0
Concrete Overlay							
Overlay? (Y/N)	Y						
(Span Type : RB)							
(Span Numbers : 1, 2, 3)							
(Overlay type : CONCRETE (HIGH DENSITY))							
(Area(m²) : 677.1)							

Concrete Deck Inspection						
	Last	Now	Explanation of Condition			
(Year Installed : 1982)						
(Thickness(mm) : 50)						
(Average Cylinder Strength(Mpa) :)						
Overlay Rating (% Area)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now	0	0	0	0	0	100
Total Crack Length - Medium/Wide (m)						N
Total Scaled Area - Light (m ²)						N
Total Scaled Area -Moderate/Heavy/Severe (m ²)						N
Debonded Area (m ²)						0
Spalled Area (m ²)						N
Patched Area (m ²)						N
Average Measured Cover Depth (mm)						127
Standard Deviation of Measured Cover Depth (mm)						11

Covered by chip seal coat and epoxy

Deck				
(Span Type : RB)				
(Span Numbers : 1, 2, 3)				
(Deck Type : CONCRETE (CLASS C))				
(Area(m ²) : 677.1)				
(Year Constructed : 1961)				
(Year Widened :)				
(Thickness(mm) : 150)				
(Average Cylinder Strength(MPa) :)				
	Type	Size	Design Cover (mm)	Spacing (mm)
Long. Reinforcing	REINFORCING STEEL			
Trans. Reinforcing	REINFORCING STEEL			

Deck Top Rating (% Area)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now	0	0	0	0	0	100
Total Crack Length - Medium/Wide (m)						N
Total Scaled Area - Light (m ²)						N
Total Scaled Area - Moderate/Heavy/Severe (m ²)						N
Delaminated Area (m ²)						N
Spalled Area (m ²)						N
Patched Area (m ²)						N
Average Measured Cover Depth (mm)						N
Standard Deviation of Measured Cover Depth (mm)						N

Deck Underside Rating (% Area)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now	0	100	0	0	0	0
Total Stained Area - Moderate (m ²)						7
Total Stained Area - Heavy/Severe (m ²)						0
Total Crack Length - Medium/Wide (m)						160
% of Medium/Wide Cracks Stained						50

Old accident fire caused staining on the deck underside. Small construction spalls between G4G5 S1. several high load scrapes, above southbound traffic on highway 43. Transverse cracks. Slight sag along centre span.

Edge Elements	
Curbs? (Y/N)	Y
Parapets? (Y/N)	N
Medians? (Y/N)	N
Sidewalks? (Y/N)	N

Concrete Deck Inspection						
		Last	Now	Explanation of Condition		
Curbs						
(Type : CONCRETE)						
(Total Length(m) : 111.0)						
(Height(mm) :)						
(Width(mm) :)						
(Average Cylinder Strength(MPa) :)						
Reinforcement Type			Size	Design Cover (mm)		Spacing (mm)
Curb Rating (% Length)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now	0	88	2	0	0	10
Total Crack Length - Medium/Wide (m)						16
Total Scaled Length - Light (m)						19
Total Scaled Length - Moderate/Heavy/Severe (m)						1
Delaminated Length (m)						0
Spalled Length (m)						1
Patched Length (m)						5
Average Measured Cover Depth (mm)						105
Standard Deviation of Measured Cover Depth (mm)						12
Partially covered by gravel.						
Isolated spall along the south curb.						
Deck Joints						
(Type : SLIDING PLATES)						
(Number of Joints : 2)						
(Expansion / Fixed? : EXPANSION)						
(Location : A1, A2)						
% Inspected						100
% Joints Leaks						100
% Joint Length Leaks						100
Superstructure Damage Rating						5
Substructure Damage Rating						4
Level 1 Joint Rating						5
CSE Testing						
Testing Date		18-Jul-2012			Previous Testing Date	24-Jul-2008
Weather Information						
Temperature (°C)		17				
Conditions		Sunny				
Equipment Information						
Test Equipment Make and Model		Corexco CDL - 200 EA/512				
Electrical Ground Location and Type		1DJ, West abutment along the south curb 2DJ, West abutment along the north curb				
Measurement Locations Information						
Origin for Data		Southwest				
		Number		Length of Each (m)		Length of Last (m)
X Increments (Length)	54			1.219		0.900
Y Increments (Width)	10			1.219		1.200
CSE Results						
Span Numbers		1,2,3				
Span Type		RB				
Wearing Surface		CONVENTIONAL CHIP SEAL COAT, CONCRETE (HIGH DENSITY)				

CSE Testing									
Testing Year	% Deck Area 0 to -0.1 V	% Deck Area < -0.1 to -0.2 V	% Deck Area < -0.2 to -0.3 V	% Deck Area < -0.3 to -0.4 V	% Deck Area < -0.4 V	Avg. Deck Reading (V)	Std. Dev. Deck Reading	Avg. Curb Reading (V)	Std. Dev. Curb Reading
2012	0.0	0.8	43.0	46.8	9.4	-0.320	0.072	-0.422	0.092
2008	0.0	1.0	38.0	55.0	7.0	-0.323	0.069	-0.169	0.168
2004	0.0	7.0	51.0	38.0	3.0	-0.291	0.068	-0.352	0.073
CSE Prediction Model Optimum 5 year Rehab Start Year			2028						
Comments									

Maintenance Recommendations										
Inspector Recommendations	Year	Inspector Comments			Department Comments			Target Year	Est. Cost	Cat #
SEAL CURBS										
PATCH DECK										
SEAL DECK										
OVERLAY DECK										
REPAIR/REPLACE DECK JOINTS										
WASHING										
OTHER ACTION										
CRACK REPAIRS/TREATMENT										
PATCH CURBS/PARPETS										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
Structural Condition Rating (%)	44.4	Sufficiency Rating (%)			43.2			Est Repl Year	2020	
Level 1 Insp Date	07-Aug-2012	Next Level 1 Insp Date			07-May-2014		Current Level 1 Insp Cycle (Default) (Months)			21
Special Comments for Next Insp										
Snooper? (Y/N)	No	Lift? (Y/N)	No	Traffic Control? (Y/N)	Yes	Boat? (Y/N)	No	Ladder? (Y/N)	No	
Other Special Requirements Comments										
Previous Level 2 Inspector's Name	Brian Cote			Previous Level 2 Insp Date	24-Jul-2008					
Next Level 2 Insp Date	02-Aug-2016			Discontinue Level 2 Insp? (Y/N)	No					
Level 2 Insp Previously Completed	11			Level 2 Insp Cycle (Default) (Months)	48					
Detailed Report/Diagram? (Y/N)	Yes									
Level 2 Insp Comments										
Next Level 2 Inspection/Test	Concrete Deck Insp? (Y/N)			Yes	CSE Testing? (Y/N)		Yes	Chloride Testing? (Y/N)		No
Department Reviewer Comments										